

SIX-MONTH SURVEILLANCE AHERA REPORT

**LANEVIEW ELEMENTARY SCHOOL
2095 WARMWOOD LANE
SAN JOSE, CA 95132**

**PREPARED FOR:
BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT
981 RIDDER PARK DRIVE
SAN JOSE, CA 95131**

**INSPECTED ON:
SEPTEMBER 19, 2025**

HAZMAT DOC PROJECT #25-101

**PREPARED BY:
HAZMAT DOC
3080 OLCOTT STREET • SUITE D135
SANTA CLARA, CA 95054
Tel: 408.748.0055**

BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT

LANEVIEW ELEMENTARY SCHOOL

**INSPECTED ON:
SEPTEMBER 19, 2025**

INSPECTED BY:



**Leland Kafeyan
Cal/OSHA Certified Site Surveillance Technician
Certification Number 06-4110**

REPORTED BY:

Maheen B. Doctor

**Maheen B. Doctor
Cal/OSHA Certified Asbestos Consultant
Certification Number 95-1798**

CONTENTS

PART - I

LEGEND AND GLOSSARY OF TERMS

PART – II

AHERA REPORT A – LIST OF BUILDINGS

PART – III

AHERA REPORT B – SURVEY REPORT

PART – IV

HOMOGENEOUS MATERIALS REPORT

PART – V

FRIABLE LOCATIONS REPORT

PART – VI

NON-FRIABLE LOCATIONS REPORT

PART – VII

RECOMMENDATIONS REPORT

PART – VIII

SAMPLES REPORT

PART – IX

DAMAGE REPORT

PART - X

SITE MAPS

LEGEND

THE FOLLOWING IS A LIST OF ABBREVIATIONS USED IN THIS REPORT:

Asbestos Sample Types

AC	=	ACTINOLITE
AM	=	AMOSITE
AN	=	ANTHOPHYLLITE
CH	=	CHRYSTOTILE
CR	=	CROCIDOLITE
TR	=	TREMOLITE
ND	=	NONE DETECTED
NS	=	NO SAMPLE

Measurements

APPROX.	=	APPROXIMATELY
EA	=	EACH
I	=	INCHES
LF	=	LINEAR FEET
N	=	NUMBER
O.D.	=	OUTSIDE DIAMETER
SF	=	SQUARE FEET
TBD	=	TO BE DETERMINED

LIST OF BUILDINGS AT

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME BUILDING USED AS (#FLOORS) CONSTRUCTION	BUILDING AREA (APPROXIMATE)
ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING	
Offices, Kitchen, Lounge, Library, and Restrooms (1) Wood, Metal, Concrete, Gypsum Wallboard System	9,150 SF
CLASSROOMS 01-02 BUILDING	
Classrooms (1) Wood, Metal, Concrete, Gypsum Wallboard System	2,520 SF
CLASSROOMS 03-14 BUILDING	
Classrooms (1) Wood, Metal, Concrete, Gypsum Wallboard System	9,900 SF
CLASSROOMS 15-26 BUILDING	
Classrooms (1) Wood, Metal, Concrete, Gypsum Wallboard System	9,900 SF
CLASSROOMS P1-P2 PORTABLES BUILDING	
Classrooms (1) Wood and Metal Portables	1,920 SF
CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)	
Classroom (1) Wood and Metal	960 SF
CLASSROOMS Y1 AND Y2	
Classrooms (1) Wood and Metal Portable	1,960 SF
COVERED WALKWAY AND OVERHANGS	
Covered Walkway (1) Metal, Plaster	3,900 SF
METAL STORAGE CONTAINER	
Storage (1) Metal	336 SF
STORAGE SHED	
Storage (1) Plastic	60 SF
Total Number Of Buildings : 10	(Approximate) Total Sq Ft. : 40,606
End Of Report, Total Of 1 Pages	

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

09/09/2005	BUILDING NOTES:
09/09/2005	Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. Existing Plaster Systems Removed and Replaced with new in-kind in Path-of-Construction. New Flooring Finishes per information received from the BUESD. New Suspended Ceiling Tiles installed.
10/20/2008	New Sinks with Thermal Undercoating installed in Staff Lounge and Nurse's Room. New Ceramic Wall and Floor Tiles installed in Students' Restrooms (4), Staff Restrooms (2), and Nurse's Restroom per information received from BUESD.
02/16/2018	New Flooring Finishes installed Summer 2017 per information received from the BUESD. New Suspended Ceiling Tiles installed.

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION OFFICE, AND LIBRARY

WINDOW SEALANT

240 SF

03/07/2017	Interior and Exterior Window Glazing Sealant. Material Condition is TBD as of this date.
03/07/2017	Sample 17-044-01 collected from Bldg B, South Elevation, Speech B20, Exterior Window Glazing Sealant. Sample 17-044-02 collected from Bldg B, South Elevation, Speech B20, Interior Window Glazing Sealant.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

17-044-01	ND	NONE DETECTED	(ND)
17-044-02	ND	NONE DETECTED	(ND)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

672 SF

09/09/2005 Fire Door Core Insulation. (32 EA Fire Doors). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

26,100 SF

09/09/2005	Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date. <5% Physical Damage. ~ 4 SF Damaged in Mechanical Room in various spots on all walls. Material is Friable. This Material is in FAIR condition overall as of this date.		
04/21/2008	<10% Water Damage in the form of 4 SF of Water Damage located under the 1'x1' Ceiling Tiles in the Kitchen. No other changes as of this date.		
10/20/2008	Additional Damage due to Rolling Door in Kitchen. No other changes as of this date.		
05/12/2009	Approximately 5 SF of Damage on Lower Walls of entry corridor in Kitchen, due to Physical contact. Lower Perimeter Walls are Damaged in the form of cuts and scratches, and debris observed, due to lunch benches being moved. No other changes as of this date.		
08/31/2017	Additional Damages. Damage Observed in the form of 2 SF of Scrapes in the Electrical Room by the Staff Room. No other changes as of this date.		
08/15/2018	Additional Damage Observed. 2 SF of Physical Damage in the form of Small Holes and Scrapes in Admin Area by Entry to Hallway. No other changes as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	(NS)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

26,100 SF

08/25/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date. <5% Physical Damage. ~ 4 SF Damaged in Mechanical Room in various spots on all walls. This Material is in FAIR condition overall as of this date.
04/21/2008	<10% Water Damage in the form of 4 SF of Water Damage located under the 1'x1' Ceiling Tiles in the Kitchen. No other changes as of this date.
10/20/2008	Additional Damage due to Rolling Door in Kitchen. No other changes as of this date.
05/12/2009	Approximately 5 SF of Damage on Lower Walls of entry corridor in Kitchen, due to Physical contact. Lower Perimeter Walls are Damaged in the form of cuts and scratches, and debris observed, due to lunch benches being moved. No other changes as of this date.
08/31/2017	Additional Damages Observed. Damage Observed in the form of 2 SF of Scrapes in the Electrical Room by the Staff Room. No other changes as of this date.
08/15/2018	Additional Damage Observed. 2 SF of Physical Damage in the form of Small Holes and Scrapes in Admin Area by Entry to Hallway. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

09/19/2025 This Material is unchanged as of this date.

06-223AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WALLS AND OVERHANG

ROUGH WALL SURFACING

5,300 SF

09/09/2005 Skim Coat for Stucco Walls and Overhangs. This Material is in GOOD condition as of this date.

08/16/2019 Damages Observed. <5% Physical Damage in the form of 1 SF Hole in Wall by double gates near Mechanical Room 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

5,300 SF

09/09/2005 Stucco Walls and Overhangs. This Material is in GOOD condition as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/16/2019	Damages Observed. <5% Physical Damage in the form of 1 SF Hole in Wall by double gates near Mechanical Room 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	(NS)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

400 SF

09/09/2005	Cementitious Window Panels. This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	(NS)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, ATTIC, AND PLENUM

PIPE FITTING INSULATION

32 LF

09/09/2005	Thermal System Insulation Pipe Fitting. (2 Ea Fittings under Kitchen Sink, remainder in Attic and Plenum). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE

440 SF

09/09/2005 1'x 1' White with a Light Brown sprinkle pattern Ceiling Tiles (with Smooth Texture). Tiles are Smooth, White. This Material is in GOOD condition as of this date.

09/08/2009 <5% Physical Damage. Damage Observed in the form of several Tiles with scratched and gouged surfaces. This Material is in FAIR condition overall. No other changes as of this date.

10/09/2012 Materials Removed during Renovation. Location Description changed from KITCHEN (COOKING AREA), SERVING AREA, LOUNGE, SPEECH ROOM, LIBRARY, HALLWAY, NURSES ROOM, AND OFFICES to KITCHEN (COOKING AREA), AND SERVING AREA. Quantity changed from 4,600 SF to 440 SF. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 Additional Damage Observed. <5% Physical Damage in the form of a total of 2 Tiles with Scuffs above oven and 2 Tiles with Cracks near South Wall. Material remains in FAIR condition overall. No other changes as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE MASTIC

440 SF

09/09/2005	Mastic/Adhesive for 1'x 1' White with a Light Brown sprinkle pattern Ceiling Tiles (with Smooth Texture). Tiles are Smooth, White. This Material is in GOOD condition as of this date.
09/08/2009	<5% Physical Damage. Damage Observed in the form of several Tiles with scratched and gouged surfaces. Material changed from Non to Friable. This Material is in FAIR condition overall. No other changes as of this date.
10/09/2012	Materials Removed during Renovation. Location Description changed from KITCHEN (COOKING AREA), SERVING AREA, LOUNGE, SPEECH ROOM, LIBRARY, HALLWAY, NURSES ROOM, AND OFFICES to KITCHEN (COOKING AREA), AND SERVING AREA. Quantity changed from 4,600 SF to 440 SF. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Additional Damage Observed. <5% Physical Damage in the form of a total of 2 Tiles with Scuffs above oven and 2 Tiles with Cracks near South Wall. Material remains in FAIR condition overall. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES

VINYL FLOOR TILE

4,184 SF

09/09/2005	9"x 9" Vinyl Floor Tile. (Approximately 3,404 SF is under Carpet). <5% Physical Damage. Damages noticed by Entry Area (approx. 4 Tiles) and in Electrical Room (~10 Tiles). Material changed from NON to FRIABLE. This Material is in FAIR condition as of this date.
08/25/2006	Kitchen Restroom added to Location Description. 4 Tiles are broken and cracked by the Kitchen Entry Door. No other changes as of this date.
10/20/2008	Location Description changed from KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, AND KITCHEN RESTROOM to KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES. Material may be under carpet in Lounge, Offices and Library. No other changed as of this date.
09/02/2010	Additional Damage observed in the form of 2 Tiles are Damaged at Entry to Kitchen. Material remains in <10% Physical Damage. No other changes as of this date.
11/29/2011	Additional Damage observed - in the form of 4 Tiles are cracked and 3 Tiles are broken, next to Freezer Door, and Mastic/Adhesive is exposed. No other changes as of this date.
02/16/2018	Additional Damage Observed. 25 Tiles are Cracked and Broken. 35 Tiles have been Replaced with Red 9"x9" Vinyl Floor Tiles. Remains in FAIR condition. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	(NS)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, OFFICES, AND LIBRARY

VINYL FLOOR TILE MASTIC

4,184 SF

09/09/2005	Mastic/Adhesive for 9"x 9" Vinyl Floor Tile. (Approximately 3,404 SF is under Carpet). <5% Physical Damage. Damages noticed by Entry Area (approx. 4 Tiles) and in Electrical Room (~10 Tiles). Material changed from NON to FRIABLE. This Material is in FAIR condition as of this date.
08/25/2006	Kitchen Restroom added to Location Description. 4 Tiles are broken and cracked by the Kitchen Entry Door. No other changes as of this date.
10/20/2008	Location Description changed from KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, AND KITCHEN RESTROOM to KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES. Material may be under carpet in Lounge, Offices and Library. No other changed as of this date.
09/02/2010	Additional Damage observed in the form of 2 Tiles are Damaged at Entry to Kitchen. Material remains in <10% Physical Damage. No other changes as of this date.
11/29/2011	Additional Damage observed - in the form of 4 Tiles are cracked and 3 Tiles are broken, next to Freezer Door, and Mastic/Adhesive is exposed. No other changes as of this date.
02/16/2018	Additional Damage Observed. 25 Tiles are Cracked and Broken. 35 Tiles have been Replaced with Red 9"x 9" Vinyl Floor Tiles. Remains in FAIR condition. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE

4,080 SF

10/09/2012 1'x 1' Ceiling Tiles. Tiles are White with a pitted mark form pattern. This Material is in GOOD condition as of this date. (Original Entry updated. 03/19/15.)

01/31/2020 This Material is unchanged as of this date.

09/01/2020 Damage Observed. <5% Physical Damage in the form of 2 Tiles with Scuffs above Stage. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

12-185AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE MASTIC

4,080 SF

10/09/2012 Mastic/Adhesive for 1'x 1' Ceiling Tile. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Tiles with Scuffs above Stage. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
12-185AAA	ASSUMED	NO SAMPLE	(NS)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE

VINYL WALL COVER MASTIC

6,800 SF

08/25/2006	Mastic/Adhesive for 4'x 10' and 4'x8' Vinyl Wall Panels (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	Damage Observed. <5% Physical Damage in the form of 4 LF of Torn Vinyl Wall Cover in Hallway between MPR and Kitchen. 1/4 SF Missing Vinyl Wall Cover in Kitchen Hallway at East Entry into MPR and Kitchen. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

06-223AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

PATROL STORAGE

HEAT SHIELD

1 SF

09/09/2005 Round Light Fixture Heat Shield. (1 EA). <50% Physical Damage with No Debris. 1 in Patrol Storage is damaged and in POOR condition.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 01-02 BUILDING

09/09/2005	BUILDING NOTES:
09/09/2005	Classrooms 1 and 2 are being used as Kindergarten K1 and K2. Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. Existing Plaster Systems Removed and Replaced with new in-kind in Path-of-Construction. New Flooring Finishes per information received from the BUESD. New Suspended Ceiling Tiles installed.
10/20/2008	New Ceramic Wall and Floor Tiles installed in Restrooms and Ceramic Floor Tiles in Classroom Wet Areas per information received from BUESD.
02/16/2018	New Flooring Finishes installed Summer 2017 per information received from the BUESD. New Suspended Ceiling Tiles installed.

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

PRESSED WOOD WALL PANEL

2,000 SF

03/08/2007	4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

07-041AAA

ASSUMED

NO SAMPLE

(NS)

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

15

HazMat Doc

AHERA Report B - Survey

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

PRESSED WOOD WALL PANEL MASTIC

2,000 SF

03/08/2007	Mastic/Adhesive for 4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

07-041AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

SINK UNDERCOATING

8 SF

10/20/2008	Grey Thermal Undercoating on Sink. (2 EA Sink). This Material is in GOOD condition as of this date. (Original Entry updated on 09/02/10.)		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

08-241AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

VINYL FLOOR TILE

2,450 SF

09/09/2005 9"x 9" Vinyl Floor Tile, (under Carpet in some areas). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

VINYL FLOOR TILE MASTIC

2,450 SF

09/09/2005 Mastic/Adhesive for 9"x 9" Vinyl Floor Tile, (under Carpet in some areas). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

VINYL WALL COVER MASTIC

2,000 SF

09/09/2005 Mastic/Adhesive for Vinyl Covering on 4'x 8' Pressed Wood Wall Panels (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

WINDOW SEALANT

10 SF

03/07/2017 Exterior and Interior Sealant on Exterior Windows. Material Condition is TBD as of this date.

03/07/2017 Sample 17-044-07 collected from Bldg, D, North Side, D6, Exterior Window Glazing Sealant. Sample 17-044-08 collected from Bldg, D, North Side, D6, Interior Window Glazing Sealant.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

17-044-07	ND	NONE DETECTED	(ND)
17-044-08	ND	NONE DETECTED	(ND)

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

189 SF

09/09/2005 Fire Door Core Insulation. (9 EA Doors). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

5,100 SF

09/09/2005 Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

20

HazMat Doc

AHERA Report B - Survey

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

5,100 SF

08/25/2006 Skim Coat for Gypsum Wallboard System Walls and Ceilings, (behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

06-223AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

EXTERIOR STORAGE ROOM (LOCATED IN CLASSROOM 1)

HEAT SHIELD

1 SF

09/09/2005 Round Light Fixture Heat Shield. (1 EA). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

3,000 SF

09/09/2005 Stucco Walls and Overhangs. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 01-02 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

3,000 SF

09/09/2005 Skim Coat for Stucco Walls and Overhangs. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 01-02 BUILDING

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

(TBD)

09/09/2005	Thermal System Insulation on Pipe Fittings. (in inaccessible areas). This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 03-14 BUILDING

CLASSROOMS 03-14 BUILDING

09/09/2005	BUILDING NOTES:
09/09/2005	Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. Existing Plaster Systems Removed and Replaced with new in-kind in Path-of-Construction. New Flooring Finishes per information received from the BUESD. New Suspended Ceiling Tiles installed.
11/06/2007	Classroom 7 experienced a Fire. Finishes replaced with new in kind.
10/20/2008	New Sinks with Thermal Undercoating installed in Classrooms. New Ceramic Floor Tiles installed in Classroom Wet Areas per information received from BUESD.
02/16/2018	New Flooring Finishes installed Summer 2017 per information received from the BUESD. New Suspended Ceiling Tiles installed.

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL

24,000 SF

03/08/2007	4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.
11/06/2007	1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL MASTIC

24,000 SF

03/08/2007 Mastic/Adhesive for 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.

11/06/2007 1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

07-041AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

VINYL WALL COVER MASTIC

24,000 SF

09/09/2005	Mastic/Adhesive for Vinyl Wall Covering on on 4'x 8' Pressed Wood Wall Panel (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.
11/06/2007	1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

05-212AAA

ASSUMED

NO SAMPLE

(NS)

CLASSROOMS 03-14 BUILDING

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE

1,296 SF

09/09/2005	9"x 9" Vinyl Floor Tiles. (Material also exists under Carpeting and New 12" x 12" Vinyl Floor Tile). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE MASTIC

1,296 SF

09/09/2005 Mastic/Adhesive for 9"x 9" Vinyl Floor Tiles. (Material also exists under Carpeting and New 12" x 12" Vinyl Floor Tile). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

672 SF

09/09/2005 Fire Door Core Insulation. (32 EA DOORS). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL MISCELLANEOUS

21,260 SF

09/09/2005 Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.

05/12/2009 Damage Observed. <5% Physical Damage in the Mechanical Room, next to Classroom 3, in the form of Damage on all Walls, due to punctures, holes, and cuts. Also, approx. 2 LF of separation observed in Mechanical Room, next to Classroom 7, on South Wall. Friability changed from NON to FRIABLE. This Material is in FAIR condition overall. No other changes as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/08/2009	Additional Damage observed in Storage Closet of Classroom 13 has 1 Wall to Wall crack on Ceiling in the form of Joint and Taping Mud separation. No other changes as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	(NS)

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL SURFACING

21,260 SF

09/09/2005	Skim Coat for Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.		
05/12/2009	Damage Observed. <5% Physical Damage in the Mechanical Room, next to Classroom 3, in the form of Damage on all Walls, due to punctures, holes, and cuts. Also, approx. 2 LF of separation observed in Mechanical Room, next to Classroom 7, on South Wall. Friability changed from NON to FRIABLE. This Material is in FAIR condition overall. No other changes as of this date.		
09/08/2009	Additional Damage Observed. Storage Closet of Classroom 13 has 1 Wall to Wall crack on Ceiling in the form of Joint and Taping Mud separation. No other changes as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

30

HazMat Doc

AHERA Report B - Survey

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
06-223AAA	ASSUMED	NO SAMPLE	(NS)

CLASSROOMS 03-14 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

4,400 SF

09/09/2005	Stucco Exterior Walls and Overhangs. This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

05-212AAA

ASSUMED

NO SAMPLE

(NS)

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 03-14 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

4,400 SF

09/09/2005	Skim Coat for Stucco Exterior Walls and Overhangs. This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

240 SF

09/09/2005	Cementitious Window Panels. This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	(NS)

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS CLASSROOM 5

WINDOW PUTTY/COMPOUND

24 SF

03/07/2017	Interior and Exterior Window Glazing Putty on Exterior Windows. Material Condition is TBD as of this date.		
03/07/2017	Sample 17-044-05 collected from Bldg. C, South Side, Classroom 5, Exterior Window Glazing Putty. Sample 17-044-06 collected from Bldg. C, South Side, Classroom 5, Interior Window Glazing Putty.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

17-044-05	<1	CHRYSTILE	(CH)
17-044-06	<1	CHRYSTILE	(CH)

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS CLASSROOM C3

WINDOW SEALANT

24 SF

03/07/2017	Interior and Exterior Window Glazing Sealant on Exterior Windows Material Condition is TBD as of this date.
03/07/2017	Sample 17-044-03 collected from South Side, C3, Exterior Window Glazing Sealant. Sample 17-044-04 collected from South Side, C3, Interior Window Glazing Sealant.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

17-044-03	ND	NONE DETECTED	(ND)
17-044-04	ND	NONE DETECTED	(ND)

CLASSROOMS 03-14 BUILDING

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

40 LF

09/09/2005	Thermal System Insulation on Pipe Fittings. (40 EA). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

HazMat Doc

AHERA Report B - Survey

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 03-14 BUILDING

STORAGE ROOM OF CLASSROOM 9, AND STORAGE OF CLASSROOM 13

HEAT SHIELD

4 SF

04/21/2008 Heat Shields for 2 light fixtures. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

08-075AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26 BUILDING

09/09/2005	BUILDING NOTES:
09/09/2005	Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. Existing Plaster Systems Removed and Replaced with new in-kind in Path-of-Construction. New Flooring Finishes per information received from the BUESD. New Suspended Ceiling Tiles installed.
10/20/2008	New Ceramic Floor Tiles installed in Classrooms Wet Areas per information received from BUESD. New Sinks with Thermal Undercoating installed in Classrooms.
02/16/2018	New Flooring Finishes installed Summer 2017 per information received from the BUESD. New Suspended Ceiling Tiles installed.
08/15/2018	Classrooms 17 and 34 have been converted to the Flexible Instructional Space (F.I.S.). Areas refinished with new materials Summer 2018.

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL

30,000 SF

03/08/2007	4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

07-041AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL MASTIC

30,000 SF

03/08/2007 Mastic/Adhesive for 4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

07-041AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

VINYL WALL COVER MASTIC

30,000 SF

09/09/2005	Mastic/Adhesive for Vinyl Wall Cover, (on 4'x8' Pressed Wood Wall Panel over Gypsum Wallboard). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	Additional Damage Observed. <5% Physical Damage in the form of 7 Holes on North Wall of Classroom 20. Material remains in FAIR condition overall. No other changes as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

546 SF

09/09/2005	Fire Door Core Insulation. (26 EA). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

22,000 SF

09/09/2005 **Gypsum Wallboard System Walls And Ceilings, (with Skim Coat, Behind Other Finishes). Existing Gypsum Wallboard Systems Removed And Replaced With New In-kind In Path-of-construction. This Material Is In Good Condition As Of This Date.**

05/12/2009 Damage Observed. <5% Physical Damage and <10% Water Damage due to separation and peeling observed in Mechanical Room, on North Wall, adjacent to Clasrooms 22 & 25. Material is in FAIR condition overall. No other changes as of this date.

08/31/2017 Additional Damage Observed. Classroom 16 now has 70 SF of Gypsum Wallboard cut out, this room is under Construction. Classroom 23 has 21 SF of Gypsum Wall Board cut out for Door Instalation. 8 LF of Mastic/Adhesive is Exposed. Material Condition changed from GOOD to FAIR. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

22,000 SF

08/25/2006 Skim Coat for Gypsum Wallboard System Walls and Ceilings, (behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.

05/12/2009 Damage Observed. <5% Physical Damage and <10% Water Damage due to separation and peeling observed in Mechanical Room, on North Wall, adjacent to Clasrooms 22 & 25. Material is in FAIR condition overall. No other changes as of this date.

08/31/2017 Additional Damage Observed. Classroom 16 now has 70 SF of Gypsum Wallboard cut out, this room is under Construction. Classroom 23 has 21 SF of Gypsum Wall Board cut out for Door Instalation. 8 LF of Mastic/Adhesive is Exposed. Material Condition changed from GOOD to FAIR. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

06-223AAA ASSUMED NO SAMPLE (NS)

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING

WINDOW SEALANT

24 SF

03/07/2017 Exterior and Interior Window Glazing Sealant on Exterior Windows. Material Condition is in GOOD Condition as of this date.

03/07/2017 Sample 17-044-09 collected from Bldg. A, South Side, Classroom 21, Exterior Window Glazing Sealant.
Sample 17-044-10 collected from Bldg. A, South Side, Classroom 21, Interior Window Glazing Sealant.
Sample 17-044-11 collected from Bldg. A, North Side, Classroom 25, Exterior Window Glazing Sealant.
Sample 17-044-12 collected from Bldg. A, North Side, Classroom 25, Interior Window Glazing Sealant.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

17-044-09 ND NONE DETECTED (ND)

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
17-044-10	ND	NONE DETECTED	(ND)
17-044-11	ND	NONE DETECTED	(ND)
17-044-12	ND	NONE DETECTED	(ND)

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

4,400 SF

09/09/2005	Stucco Exterior Walls and Overhangs. This Material is in GOOD condition as of this date.
05/12/2009	Damage Observed. <5% Physical Damage Approx. 5 SF of peeling and paint flaking due to heat and moisture observed in Mechanical Rooms, on North Wall, Adjacent to Classrooms 22 & 25. Material Condition changed from GOOD to FAIR overall as of this date. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/31/2017	Partial Repairs Observed. The Exterior Walls are in GOOD condition. The Overhangs remain in FAIR condition. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	Damage Observed. <5% Physical Damage in the form of 1 LF Crack on Overhang near East Entry into Classroom 21. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

4,400 SF

09/09/2005	Skim Coat for Stucco Exterior Walls and Overhangs. This Material is in GOOD condition as of this date.		
05/12/2009	Damage Observed. <5% Physical Damage Approx. 5 SF of peeling and paint flaking due to heat and moisture observed in Mechanical Rooms, on North Wall, Adjacent to Classrooms 22 & 25. Material Condition changed from GOOD to FAIR overall as of this date. Friability changed from Non-Friable to Friable. No other changes as of this date.		
08/31/2017	Partial Repairs Observed. The Exterior Walls are in GOOD condition. The Overhangs remain in FAIR condition. No other changes as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	Damage Observed. <5% Physical Damage in the form of 1 LF Crack on Overhang near East Entry into Classroom 21. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

05-212AAA

ASSUMED

NO SAMPLE

(NS)

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS 15-26 BUILDING

PLENUM AND INACCESSIBLE LOCATIONS

PIPE FITTING INSULATION

30 LF

09/09/2005	Thermal System Insulation on Pipe Fittings. (Additional Material may exist above Ceilings and inside Wall Cavities). This Material is in GOOD condition as of this date.		
01/31/2020	This Material is unchanged as of this date.		
09/01/2020	This Material is unchanged as of this date.		
02/12/2021	This Material is unchanged as of this date.		
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS P1-P2 PORTABLES BUILDING

CLASSROOMS P1-P2 PORTABLES BUILDING

09/05/2005 BUILDING NOTES:

09/05/2005 Manufacturer's TAG Info:
BY AMERICAN MODULAR SYSTEM; DATE: 07/95; OSA# 63229; SERIAL#'S PORTABLE 1 =
95-R212-001A, 95-R212-001B; PORTABLE 2 = 95-R212-002A, 95-R212-002B.
This entry for informational and tracking purposes.

CLASSROOMS P1-P2 PORTABLES BUILDING

CLASSROOMS P1-P2 PORTABLES BUILDING

PORTABLE BUILDING

1,920 SF

09/05/2005 New Construction Portable Building per Manufacturer's Tag Info.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212.NS	NEW	NO SAMPLE	(NS)
-----------	-----	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

08/25/2005 BUILDING NOTES:

08/25/2005 Manufacturer's TAG Info:
BY AMERICAN MODULAR SYSTEM; DSA# 01-017955. DATE: 04/06; SERIAL# 06-222-004A,
06-222-004B.
This entry for informational and tracking purposes.

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

CLASSROOM P3 (NEW UNIT)

PORTABLE BUILDING

960 SF

08/25/2005 New 2006 Construction Relocatable Building per Manufacturer's Tag information.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

06-223.NS	NEW	NO SAMPLE	(NS)
-----------	-----	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

CLASSROOMS Y1 AND Y2

CLASSROOMS Y1 AND Y2

09/09/2005 BUILDING NOTES:

09/09/2005 Manufacturer's TAG Info:
BY AMERICAN MODULAR SYSTEM; DATE: 08/98; DSA# 01-100822; SERIAL#S 98-R377-001A,
98-R377-001B, 98-R377-001C, 98-R377-001D.
This entry for informational and tracking purposes only.

CLASSROOMS Y1 AND Y2

CLASSROOMS Y1 AND Y2

PORTABLE BUILDING

1,960 SF

09/09/2005 New 1998 Construction Relocatable Building per Manufacturer's Tag information.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212.NS	NEW	NO SAMPLE	(NS)
-----------	-----	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

COVERED WALKWAY AND OVERHANGS

COVERED WALKWAY AND OVERHANGS

EXTERIOR CEILINGS

ROUGH CEILING

3,900 SF

09/09/2005 Stucco on Covered Walkways and Overhangs. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

COVERED WALKWAY AND OVERHANGS

EXTERIOR CEILINGS

ROUGH CEILING SURFACING

3,900 SF

09/09/2005 Skim Coat for Stucco on Covered Walkways and Overhangs. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/13/2021	This Material is unchanged as of this date.		
02/23/2022	This Material is unchanged as of this date.		
08/19/2022	This Material is unchanged as of this date.		
02/17/2023	This Material is unchanged as of this date.		
08/18/2023	This Material is unchanged as of this date.		
02/16/2024	This Material is unchanged as of this date.		
08/16/2024	This Material is unchanged as of this date.		
03/03/2025	This Material is unchanged as of this date.		
09/19/2025	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	(NS)

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER

05/12/2009 BUILDING NOTES:

05/12/2009 Metal Storage Containers. (1 EA Containers). Located next to field area.

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

336 SF

03/18/2016 Metal Storage Container. 1 EA, container.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

16-074.NS	ASSUMED	NO SAMPLE	(NS)
-----------	---------	-----------	--------

SURVEY REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

STORAGE SHED

STORAGE SHED

04/21/2007 BUILDING NOTES:

04/21/2007 Plastic Storage Shed. No Suspect Materials identified.

STORAGE SHED

STORAGE SHED

STORAGE BUILDING

60 SF

04/21/2008 Plastic Storage Structure. Non-ACM Material identified by the AHERA Accredited inspector.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

08-075AAA	NON-ACM	NO SAMPLE	(NS)
-----------	---------	-----------	--------

End Of Report, Total Of 51 Pages

HOMOGENEOUS MATERIALS IN LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

MATERIAL CATEGORY

LOCATION

MATERIAL TYPE

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MISCELLANEOUS MATERIAL

ADMINISTRATION OFFICE, AND LIBRARY
ENTIRE BUILDING
ENTIRE BUILDING

EXTERIOR WINDOWS
KITCHEN (COOKING AREA), AND SERVING AREA
KITCHEN (COOKING AREA), AND SERVING AREA
KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN
RESTROOM, LOUNGE, LIBRARY, AND OFFICES
KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN
RESTROOM, LOUNGE, OFFICES, AND LIBRARY
MULTIPURPOSE ROOM, AND STAGE
MULTIPURPOSE ROOM, AND STAGE
OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE
PATROL STORAGE

WINDOW SEALANT
FIRE DOOR CORE INSULATION
SMOOTH WALL
MISCELLANEOUS
CEMENTITIOUS WINDOW PANEL
CEILING TILE
CEILING TILE MASTIC
VINYL FLOOR TILE

VINYL FLOOR TILE MASTIC

CEILING TILE
CEILING TILE MASTIC
VINYL WALL COVER MASTIC
HEAT SHIELD

SURFACING MATERIAL

ENTIRE BUILDING
EXTERIOR WALLS AND OVERHANG
EXTERIOR WALLS AND OVERHANGS

SMOOTH WALL SURFACING
ROUGH WALL SURFACING
ROUGH WALL

THERMAL SYSTEM INSULATION

KITCHEN, ATTIC, AND PLENUM

PIPE FITTING INSULATION

CLASSROOMS 01-02 BUILDING

MISCELLANEOUS MATERIAL

CLASSROOMS 1 AND 2
CLASSROOMS 1 AND 2

CLASSROOMS 1 AND 2
CLASSROOMS 1 AND 2
CLASSROOMS 1 AND 2
CLASSROOMS 1 AND 2
CLASSROOMS 1 AND 2
ENTIRE BUILDING
ENTIRE BUILDING

EXTERIOR STORAGE ROOM (LOCATED IN CLASSROOM 1)

PRESSED WOOD WALL PANEL
PRESSED WOOD WALL PANEL
MASTIC
SINK UNDERCOATING
VINYL FLOOR TILE
VINYL FLOOR TILE MASTIC
VINYL WALL COVER MASTIC
WINDOW SEALANT
FIRE DOOR CORE INSULATION
SMOOTH WALL
MISCELLANEOUS
HEAT SHIELD

SURFACING MATERIAL

ENTIRE BUILDING
EXTERIOR WALLS AND OVERHANGS
EXTERIOR WALLS AND OVERHANGS

SMOOTH WALL SURFACING
ROUGH WALL
ROUGH WALL SURFACING

HOMOGENEOUS MATERIALS IN LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

MATERIAL CATEGORY

LOCATION

MATERIAL TYPE

THERMAL SYSTEM INSULATION

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

CLASSROOMS 03-14 BUILDING

MISCELLANEOUS MATERIAL

CLASSROOMS 3-14

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL

PRESSED WOOD WALL PANEL
MASTIC

CLASSROOMS 3-14

VINYL WALL COVER MASTIC

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE MASTIC

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL
MISCELLANEOUS

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

EXTERIOR WINDOWS CLASSROOM 5

WINDOW PUTTY/COMPOUND

EXTERIOR WINDOWS CLASSROOM C3

WINDOW SEALANT

STORAGE ROOM OF CLASSROOM 9, AND STORAGE OF CLASSROOM 13

HEAT SHIELD

SURFACING MATERIAL

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL SURFACING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

THERMAL SYSTEM INSULATION

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

CLASSROOMS 15-26 BUILDING

MISCELLANEOUS MATERIAL

CLASSROOMS 15-26

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL

PRESSED WOOD WALL PANEL
MASTIC

CLASSROOMS 15-26

VINYL WALL COVER MASTIC

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

ENTIRE BUILDING

SMOOTH WALL
MISCELLANEOUS

ENTIRE BUILDING

WINDOW SEALANT

SURFACING MATERIAL

ENTIRE BUILDING

SMOOTH WALL SURFACING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

THERMAL SYSTEM INSULATION

PLENUM AND INACCESSIBLE LOCATIONS

PIPE FITTING INSULATION

CLASSROOMS P1-P2 PORTABLES BUILDING

HOMOGENEOUS MATERIALS IN
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

MATERIAL CATEGORY

LOCATION

MATERIAL TYPE

MISCELLANEOUS MATERIAL

CLASSROOMS P1-P2 PORTABLES BUILDING

PORTABLE BUILDING

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

MISCELLANEOUS MATERIAL

CLASSROOM P3 (NEW UNIT)

PORTABLE BUILDING

CLASSROOMS Y1 AND Y2

MISCELLANEOUS MATERIAL

CLASSROOMS Y1 AND Y2

PORTABLE BUILDING

COVERED WALKWAY AND OVERHANGS

SURFACING MATERIAL

EXTERIOR CEILINGS

ROUGH CEILING

EXTERIOR CEILINGS

ROUGH CEILING SURFACING

METAL STORAGE CONTAINER

MISCELLANEOUS MATERIAL

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

STORAGE SHED

MISCELLANEOUS MATERIAL

STORAGE SHED

STORAGE BUILDING

End Of Report, Total Of 3 Pages

FRIABLE LOCATIONS IN LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	QTY (APPROXIMATE)	ASBESTOS CONTENT
MATERIAL TYPE			
ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING			
ENTIRE BUILDING	FIRE DOOR CORE INSULATION	672 SF	Assumed
ENTIRE BUILDING	SMOOTH WALL MISCELLANEOUS	26,100 SF	Assumed
ENTIRE BUILDING	SMOOTH WALL SURFACING	26,100 SF	Assumed
EXTERIOR WALLS AND OVERHANG	ROUGH WALL SURFACING	5,300 SF	Assumed
EXTERIOR WALLS AND OVERHANGS	ROUGH WALL	5,300 SF	Assumed
KITCHEN, ATTIC, AND PLENUM	PIPE FITTING INSULATION	32 LF	Assumed
KITCHEN (COOKING AREA), AND SERVING AREA	CEILING TILE	440 SF	Assumed
KITCHEN (COOKING AREA), AND SERVING AREA	CEILING TILE MASTIC	440 SF	Assumed
KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES	VINYL FLOOR TILE	4,184 SF	Assumed
KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, OFFICES, AND LIBRARY	VINYL FLOOR TILE MASTIC	4,184 SF	Assumed
MULTIPURPOSE ROOM, AND STAGE	CEILING TILE	4,080 SF	Assumed
MULTIPURPOSE ROOM, AND STAGE	CEILING TILE MASTIC	4,080 SF	Assumed
OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE	VINYL WALL COVER MASTIC	6,800 SF	Assumed
PATROL STORAGE	HEAT SHIELD	1 SF	Assumed

FRIABLE LOCATIONS IN LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME			
LOCATION		QTY	ASBESTOS
MATERIAL TYPE		(APPROXIMATE)	CONTENT
CLASSROOMS 01-02 BUILDING			
CLASSROOMS 1 AND 2			
PRESSED WOOD WALL PANEL		2,000 SF	Assumed
ENTIRE BUILDING			
FIRE DOOR CORE INSULATION		189 SF	Assumed
ENTIRE BUILDING			
SMOOTH WALL MISCELLANEOUS		5,100 SF	Assumed
ENTIRE BUILDING			
SMOOTH WALL SURFACING		5,100 SF	Assumed
EXTERIOR STORAGE ROOM (LOCATED IN CLASSROOM 1)			
HEAT SHIELD		1 SF	Assumed
PLENUM AND CONCEALED LOCATIONS			
PIPE FITTING INSULATION		(TBD)	Assumed
CLASSROOMS 03-14 BUILDING			
CLASSROOMS 3-14			
PRESSED WOOD WALL PANEL		24,000 SF	Assumed
CLASSROOMS 3-14			
PRESSED WOOD WALL PANEL MASTIC		24,000 SF	Assumed
CLASSROOMS 3-14			
VINYL WALL COVER MASTIC		24,000 SF	Assumed
ENTIRE BUILDING			
FIRE DOOR CORE INSULATION		672 SF	Assumed
ENTIRE BUILDING INCLUDING PLENUM			
SMOOTH WALL MISCELLANEOUS		21,260 SF	Assumed
ENTIRE BUILDING INCLUDING PLENUM			
SMOOTH WALL SURFACING		21,260 SF	Assumed
PLENUM AND CONCEALED LOCATIONS			
PIPE FITTING INSULATION		40 LF	Assumed
STORAGE ROOM OF CLASSROOM 9, AND STORAGE OF CLASSROOM 13			
HEAT SHIELD		4 SF	Assumed

FRIABLE LOCATIONS IN LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME			
LOCATION		QTY	ASBESTOS
MATERIAL TYPE		(APPROXIMATE)	CONTENT
CLASSROOMS 15-26 BUILDING			
CLASSROOMS 15-26			
PRESSED WOOD WALL PANEL		30,000 SF	Assumed
CLASSROOMS 15-26			
PRESSED WOOD WALL PANEL MASTIC		30,000 SF	Assumed
CLASSROOMS 15-26			
VINYL WALL COVER MASTIC		30,000 SF	Assumed
ENTIRE BUILDING			
FIRE DOOR CORE INSULATION		546 SF	Assumed
EXTERIOR WALLS AND OVERHANGS			
ROUGH WALL		4,400 SF	Assumed
EXTERIOR WALLS AND OVERHANGS			
ROUGH WALL SURFACING		4,400 SF	Assumed
PLENUM AND INACCESSIBLE LOCATIONS			
PIPE FITTING INSULATION		30 LF	Assumed
End Of Report, Total Of 3 Pages			

Non- Friable Locations In LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	QTY (APPROXIMATE)	ASBESTOS CONTENT
MATERIAL TYPE			
ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING			
	ADMINISTRATION OFFICE, AND LIBRARY WINDOW SEALANT	240 SF	Non Detected
	EXTERIOR WINDOWS CEMENTITIOUS WINDOW PANEL	400 SF	Assumed
CLASSROOMS 01-02 BUILDING			
	CLASSROOMS 1 AND 2 PRESSED WOOD WALL PANEL MASTIC	2,000 SF	Assumed
	CLASSROOMS 1 AND 2 SINK UNDERCOATING	8 SF	Assumed
	CLASSROOMS 1 AND 2 VINYL FLOOR TILE	2,450 SF	Assumed
	CLASSROOMS 1 AND 2 VINYL FLOOR TILE MASTIC	2,450 SF	Assumed
	CLASSROOMS 1 AND 2 VINYL WALL COVER MASTIC	2,000 SF	Assumed
	CLASSROOMS 1 AND 2 WINDOW SEALANT	10 SF	Non Detected
	EXTERIOR WALLS AND OVERHANGS ROUGH WALL	3,000 SF	Assumed
	EXTERIOR WALLS AND OVERHANGS ROUGH WALL SURFACING	3,000 SF	Assumed
CLASSROOMS 03-14 BUILDING			
	CLASSROOMS 9, 13, AND TWO STORAGE ROOMS VINYL FLOOR TILE	1,296 SF	Assumed
	CLASSROOMS 9, 13, AND TWO STORAGE ROOMS VINYL FLOOR TILE MASTIC	1,296 SF	Assumed
	EXTERIOR WALLS AND OVERHANGS ROUGH WALL	4,400 SF	Assumed
	EXTERIOR WALLS AND OVERHANGS ROUGH WALL SURFACING	4,400 SF	Assumed
	EXTERIOR WINDOWS CEMENTITIOUS WINDOW PANEL	240 SF	Assumed
	EXTERIOR WINDOWS CLASSROOM 5 WINDOW PUTTY/COMPOUND	24 SF	Less Than 1%
	EXTERIOR WINDOWS CLASSROOM C3 WINDOW SEALANT	24 SF	Non Detected

**Non- Friable Locations In
LANEVIEW ELEMENTARY SCHOOL**

BUILDING NAME			
LOCATION		QTY (APPROXIMATE)	ASBESTOS CONTENT
MATERIAL TYPE			
CLASSROOMS 15-26 BUILDING			
ENTIRE BUILDING			
SMOOTH WALL MISCELLANEOUS		22,000 SF	Assumed
ENTIRE BUILDING			
SMOOTH WALL SURFACING		22,000 SF	Assumed
ENTIRE BUILDING			
WINDOW SEALANT		24 SF	Non Detected
COVERED WALKWAY AND OVERHANGS			
EXTERIOR CEILINGS			
ROUGH CEILING		3,900 SF	Assumed
EXTERIOR CEILINGS			
ROUGH CEILING SURFACING		3,900 SF	Assumed
METAL STORAGE CONTAINER			

End Of Report, Total Of 2 Pages

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION OFFICE, AND LIBRARY

WINDOW SEALANT 240 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

FIRE DOOR CORE INSULATION 672 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS 26,100 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

SMOOTH WALL SURFACING 26,100 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

EXTERIOR WALLS AND OVERHANG

ROUGH WALL SURFACING

5,300 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

5,300 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

400 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

KITCHEN, ATTIC, AND PLENUM

PIPE FITTING INSULATION

32 LF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE

440 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE MASTIC

440 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES

VINYL FLOOR TILE

4,184 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, OFFICES, AND LIBRARY

VINYL FLOOR TILE MASTIC

4,184 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE

4,080 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE MASTIC

4,080 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE

VINYL WALL COVER MASTIC

6,800 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

PATROL STORAGE

HEAT SHIELD

1 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
 - (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2

PRESSED WOOD WALL PANEL 2,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 1 AND 2

PRESSED WOOD WALL PANEL MASTIC 2,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 1 AND 2

SINK UNDERCOATING 8 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 1 AND 2

VINYL FLOOR TILE 2,450 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

CLASSROOMS 1 AND 2

VINYL FLOOR TILE MASTIC

2,450 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 1 AND 2

VINYL WALL COVER MASTIC

2,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 1 AND 2

WINDOW SEALANT

10 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

189 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS 5,100 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

SMOOTH WALL SURFACING 5,100 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR STORAGE ROOM (LOCATED IN CLASSROOM 1)

HEAT SHIELD 1 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL 3,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME**LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

EXTERIOR WALLS AND OVERHANGS**ROUGH WALL SURFACING****3,000 SF**

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

PLENUM AND CONCEALED LOCATIONS**PIPE FITTING INSULATION****(TBD)**

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14**PRESSED WOOD WALL PANEL****24,000 SF**

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 3-14**PRESSED WOOD WALL PANEL MASTIC****24,000 SF**

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

CLASSROOMS 3-14

VINYL WALL COVER MASTIC

24,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE

1,296 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE MASTIC

1,296 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

672 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL MISCELLANEOUS 21,260 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL SURFACING 21,260 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL 4,400 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING 4,400 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

240 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WINDOWS CLASSROOM 5

WINDOW PUTTY/COMPOUND

24 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WINDOWS CLASSROOM C3

WINDOW SEALANT

24 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

40 LF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

STORAGE ROOM OF CLASSROOM 9, AND STORAGE OF CLASSROOM 13

HEAT SHIELD

4 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL

30,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL MASTIC

30,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

CLASSROOMS 15-26

VINYL WALL COVER MASTIC

30,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

546 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

22,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

SMOOTH WALL SURFACING

22,000 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

ENTIRE BUILDING

WINDOW SEALANT

24 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

4,400 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

4,400 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

PLENUM AND INACCESSIBLE LOCATIONS

PIPE FITTING INSULATION

30 LF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

CLASSROOMS P1-P2 PORTABLES BUILDING

CLASSROOMS P1-P2 PORTABLES BUILDING

PORTABLE BUILDING

1,920 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

CLASSROOM P3 (NEW UNIT)

PORTABLE BUILDING

960 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

CLASSROOMS Y1 AND Y2

CLASSROOMS Y1 AND Y2

PORTABLE BUILDING

1,960 SF

- (a) This is a replacement/new material.
- (b) The district should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the district's AHERA records.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

COVERED WALKWAY AND OVERHANGS

EXTERIOR CEILINGS

ROUGH CEILING

3,900 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

EXTERIOR CEILINGS

ROUGH CEILING SURFACING

3,900 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

336 SF

- (a) No abatement is necessary.
 - (b) Maintain the material in an intact and undamaged condition.
 - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
 - (d) Include this material in the long term surveillance and re-inspection program
 - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

RECOMMENDATIONS FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RECOMMENDATION

QTY

(APPROXIMATE)

STORAGE SHED

STORAGE SHED

STORAGE BUILDING

60 SF

This material has been deemed as Non-Asbestos Containing Material (Non-ACM) by the AHERA accredited Inspector. No recommendations are necessary.

End Of Report, Total Of 17 Pages

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION OFFICE, AND LIBRARY

WINDOW SEALANT

<u>17-044-01</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg B, South Elevation, Speech B20, Exterior Window Glazing Sealant.

<u>17-044-02</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg B, South Elevation, Speech B20, Interior Window Glazing Sealant.

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

<u>06-223AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WALLS AND OVERHANG

ROUGH WALL SURFACING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

EXTERIOR WINDOWS

CEMENTITIOUS WINDOW PANEL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, ATTIC, AND PLENUM

PIPE FITTING INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES

VINYL FLOOR TILE

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, OFFICES, AND LIBRARY

VINYL FLOOR TILE MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE

<u>12-185AAA</u>	10/9/2012	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE MASTIC

<u>12-185AAA</u>	10/9/2012	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE

VINYL WALL COVER MASTIC

<u>06-223AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

PATROL STORAGE

HEAT SHIELD

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

CLASSROOMS 01-02 BUILDING

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 PRESSED WOOD WALL PANEL

<u>07-041AAA</u>	3/10/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 PRESSED WOOD WALL PANEL MASTIC

<u>07-041AAA</u>	3/10/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 SINK UNDERCOATING

<u>08-241AAA</u>	10/20/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 VINYL FLOOR TILE

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 VINYL FLOOR TILE MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 VINYL WALL COVER MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

CLASSROOMS 1 AND 2
 WINDOW SEALANT

<u>17-044-07</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg. D, North Side, D6, Exterior Window Glazing Sealant.

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

<u>17-044-08</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
Bldg. D, North Side, D6, Interior Window Glazing Sealant.					

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING
 FIRE DOOR CORE INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING
 SMOOTH WALL MISCELLANEOUS

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

ENTIRE BUILDING
 SMOOTH WALL SURFACING

<u>06-223AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

EXTERIOR STORAGE ROOM (LOCATED IN CLASSROOM 1)
 HEAT SHIELD

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

EXTERIOR WALLS AND OVERHANGS
 ROUGH WALL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

EXTERIOR WALLS AND OVERHANGS
 ROUGH WALL SURFACING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 01-02 BUILDING

PLENUM AND CONCEALED LOCATIONS
 PIPE FITTING INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

CLASSROOMS 03-14 BUILDING

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL

<u>05-212AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL MASTIC

<u>07-041AAA</u>	3/8/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

VINYL WALL COVER MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

CLASSROOMS 9, 13, AND TWO STORAGE ROOMS

VINYL FLOOR TILE MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL MISCELLANEOUS

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM
 SMOOTH WALL SURFACING

<u>06-223AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

EXTERIOR WALLS AND OVERHANGS
 ROUGH WALL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

EXTERIOR WALLS AND OVERHANGS
 ROUGH WALL SURFACING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS
 CEMENTITIOUS WINDOW PANEL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS CLASSROOM 5
 WINDOW PUTTY/COMPOUND

<u>17-044-05</u>	3/7/2017	Positive	<1	CHRYBOTILE	CH
-------------------------	----------	----------	----	------------	----

Bldg. C, South Side, Classroom 5, Exterior Window Glazing Putty.

<u>17-044-06</u>	3/7/2017	Positive	<1	CHRYBOTILE	CH
-------------------------	----------	----------	----	------------	----

Bldg. C, South Side, Classroom 5, Interior Window Glazing Putty.

CLASSROOMS 03-14 BUILDING

EXTERIOR WINDOWS CLASSROOM C3
 WINDOW SEALANT

<u>17-044-03</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg. C, South Side, C3, Exterior Window Glazing Sealant.

<u>17-044-04</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg. C, South Side, C3, Exterior Window Glazing Sealant.

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
--------------------------------	-------------	---------------	-----------------------------	--------------------------	--------------------------

CLASSROOMS 03-14 BUILDING

PLENUM AND CONCEALED LOCATIONS

PIPE FITTING INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 03-14 BUILDING

STORAGE ROOM OF CLASSROOM 9, AND STORAGE OF CLASSROOM 13

HEAT SHIELD

<u>08-075AAA</u>	4/21/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME
LOCATION
MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26
 PRESSED WOOD WALL PANEL

<u>07-041AAA</u>	3/10/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26
 PRESSED WOOD WALL PANEL MASTIC

<u>07-041AAA</u>	3/8/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26
 VINYL WALL COVER MASTIC

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING
 FIRE DOOR CORE INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING
 SMOOTH WALL MISCELLANEOUS

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING
 SMOOTH WALL SURFACING

<u>06-223AAA</u>	8/25/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

ENTIRE BUILDING
 WINDOW SEALANT

<u>17-044-09</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
-------------------------	----------	----------	----	---------------	----

Bldg. A, South Side, Classroom 21, Exterior Window Glazing Sealant.

SAMPLES REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

<u>17-044-10</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
Bldg. A, South Side, Classroom 21, Interior Window Glazing Sealant.					

<u>17-044-11</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
Bldg. A, North Side, Classroom 25, Exterior Window Glazing Sealant.					

<u>17-044-12</u>	3/7/2017	Negative	ND	NONE DETECTED	ND
Bldg. A, North Side, Classroom 25, Interior Window Glazing Sealant.					

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

CLASSROOMS 15-26 BUILDING

PLENUM AND INACCESSIBLE LOCATIONS

PIPE FITTING INSULATION

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS					

CLASSROOMS P1-P2 PORTABLES BUILDING

CLASSROOMS P1-P2 PORTABLES BUILDING

CLASSROOMS P1-P2 PORTABLES BUILDING

PORTABLE BUILDING

05-212.NS

9/5/2005

Negative

NEW MATERIAL

NO SAMPLE

NS

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS					

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

CLASSROOMS P3 PORTABLE BUILDING (NEW UNIT)

CLASSROOM P3 (NEW UNIT)

PORTABLE BUILDING

06-223.NS

8/25/2006

Negative

NEW MATERIAL

NO SAMPLE

NS

New Relocatable 2006 Construction Relocatable Building per Manufacturer's Tag information.

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS					

CLASSROOMS Y1 AND Y2

CLASSROOMS Y1 AND Y2

CLASSROOMS Y1 AND Y2

PORTABLE BUILDING

05-212.NS

9/9/2005

Negative

NEW MATERIAL

NO SAMPLE

NS

New 1998 Construction Relocatable Building per Manufacturer's Tag information.

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS					

COVERED WALKWAY AND OVERHANGS

COVERED WALKWAY AND OVERHANGS

EXTERIOR CEILINGS

ROUGH CEILING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

COVERED WALKWAY AND OVERHANGS

EXTERIOR CEILINGS

ROUGH CEILING SURFACING

<u>05-212AAA</u>	9/9/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
--------------------------------	-------------	---------------	-----------------------------	--------------------------	--------------------------

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

16-074.NS

3/18/2016

Positive

ASSUMED

NO SAMPLE

NS

Metal Storage Structure.

SAMPLES REPORT FOR
LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE NO.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS					

STORAGE SHED

STORAGE SHED

STORAGE SHED

STORAGE BUILDING

08-075AAA

4/21/2008

Negative

NON-ACM

NO SAMPLE

NS

Non-ACM Plastic Storage Building identified by the AHERA Accredited inspector.

End Of Report, Total Of 16 Pages

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

26,100 SF

P: Less Than 5%

W: <10% Stains or Flaking

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date. <5% Physical Damage. ~ 4 SF Damaged in Mechanical Room in various spots on all walls. Material is Friable. This Material is in FAIR condition overall as of this date.
04/21/2008	<10% Water Damage in the form of 4 SF of Water Damage located under the 1'x1' Ceiling Tiles in the Kitchen. No other changes as of this date.
10/20/2008	Additional Damage due to Rolling Door in Kitchen. No other changes as of this date.
05/12/2009	Approximately 5 SF of Damage on Lower Walls of entry corridor in Kitchen, due to Physical contact. Lower Perimeter Walls are Damaged in the form of cuts and scratches, and debris observed, due to lunch benches being moved. No other changes as of this date.
08/31/2017	Additional Damages. Damage Observed in the form of 2 SF of Scrapes in the Electrical Room by the Staff Room. No other changes as of this date.
08/15/2018	Additional Damage Observed. 2 SF of Physical Damage in the form of Small Holes and Scrapes in Admin Area by Entry to Hallway. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

26,100 SF

P: Less Than 5%

W: <10% Stains or Flaking

DAMAGED FRIABLE SURFACING ACM

08/25/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date. <5% Physical Damage. ~ 4 SF Damaged in Mechanical Room in various spots on all walls. This Material is in FAIR condition overall as of this date.
04/21/2008	<10% Water Damage in the form of 4 SF of Water Damage located under the 1'x1' Ceiling Tiles in the Kitchen. No other changes as of this date.
10/20/2008	Additional Damage due to Rolling Door in Kitchen. No other changes as of this date.
05/12/2009	Approximately 5 SF of Damage on Lower Walls of entry corridor in Kitchen, due to Physical contact. Lower Perimeter Walls are Damaged in the form of cuts and scratches, and debris observed, due to lunch benches being moved. No other changes as of this date.
08/31/2017	Additional Damages Observed. Damage Observed in the form of 2 SF of Scrapes in the Electrical Room by the Staff Room. No other changes as of this date.
08/15/2018	Additional Damage Observed. 2 SF of Physical Damage in the form of Small Holes and Scrapes in Admin Area by Entry to Hallway. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE

440 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	1'x 1' White with a Light Brown sprinkle pattern Ceiling Tiles (with Smooth Texture). Tiles are Smooth, White. This Material is in GOOD condition as of this date.
09/08/2009	<5% Physical Damage. Damage Observed in the form of several Tiles with scratched and gouged surfaces. This Material is in FAIR condition overall. No other changes as of this date.
10/09/2012	Materials Removed during Renovation. Location Description changed from KITCHEN (COOKING AREA), SERVING AREA, LOUNGE, SPEECH ROOM, LIBRARY, HALLWAY, NURSES ROOM, AND OFFICES to KITCHEN (COOKING AREA), AND SERVING AREA. Quantity changed from 4,600 SF to 440 SF. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Additional Damage Observed. <5% Physical Damage in the form of a total of 2 Tiles with Scuffs above oven and 2 Tiles with Cracks near South Wall. Material remains in FAIR condition overall. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN (COOKING AREA), AND SERVING AREA

CEILING TILE MASTIC

440 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Mastic/Adhesive for 1'x 1' White with a Light Brown sprinkle pattern Ceiling Tiles (with Smooth Texture). Tiles are Smooth, White. This Material is in GOOD condition as of this date.
------------	--

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
09/08/2009				<5% Physical Damage. Damage Observed in the form of several Tiles with scratched and gouged surfaces. Material changed from Non to Friable. This Material is in FAIR condition overall. No other changes as of this date.		
10/09/2012				Materials Removed during Renovation. Location Description changed from KITCHEN (COOKING AREA), SERVING AREA, LOUNGE, SPEECH ROOM, LIBRARY, HALLWAY, NURSES ROOM, AND OFFICES to KITCHEN (COOKING AREA), AND SERVING AREA. Quantity changed from 4,600 SF to 440 SF. No other changes as of this date.		
01/31/2020				This Material is unchanged as of this date.		
09/01/2020				Additional Damage Observed. <5% Physical Damage in the form of a total of 2 Tiles with Scuffs above oven and 2 Tiles with Cracks near South Wall. Material remains in FAIR condition overall. No other changes as of this date.		
02/12/2021				This Material is unchanged as of this date.		
08/13/2021				This Material is unchanged as of this date.		
02/23/2022				This Material is unchanged as of this date.		
08/19/2022				This Material is unchanged as of this date.		
02/17/2023				This Material is unchanged as of this date.		
08/18/2023				This Material is unchanged as of this date.		
02/16/2024				This Material is unchanged as of this date.		
08/16/2024				This Material is unchanged as of this date.		
03/03/2025				This Material is unchanged as of this date.		
09/19/2025				This Material is unchanged as of this date.		

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES

VINYL FLOOR TILE

4,184 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	9"x 9" Vinyl Floor Tile. (Approximately 3,404 SF is under Carpet). <5% Physical Damage. Damages noticed by Entry Area (approx. 4 Tiles) and in Electrical Room (~10 Tiles). Material changed from NON to FRIABLE. This Material is in FAIR condition as of this date.
08/25/2006	Kitchen Restroom added to Location Description. 4 Tiles are broken and cracked by the Kitchen Entry Door. No other changes as of this date.
10/20/2008	Location Description changed from KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, AND KITCHEN RESTROOM to KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES. Material may be under carpet in Lounge, Offices and Library. No other changed as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

09/02/2010	Additional Damage observed in the form of 2 Tiles are Damaged at Entry to Kitchen. Material remains in <10% Physical Damage. No other changes as of this date.					
11/29/2011	Additional Damage observed - in the form of 4 Tiles are cracked and 3 Tiles are broken, next to Freezer Door, and Mastic/Adhesive is exposed. No other changes as of this date.					
02/16/2018	Additional Damage Observed. 25 Tiles are Cracked and Broken. 35 Tiles have been Replaced with Red 9"x9" Vinyl Floor Tiles. Remains in FAIR condition. No other changes as of this date.					
01/31/2020	This Material is unchanged as of this date.					
09/01/2020	This Material is unchanged as of this date.					
02/12/2021	This Material is unchanged as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					
08/16/2024	This Material is unchanged as of this date.					
03/03/2025	This Material is unchanged as of this date.					
09/19/2025	This Material is unchanged as of this date.					

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, OFFICES, AND LIBRARY

VINYL FLOOR TILE MASTIC

4,184 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Mastic/Adhesive for 9"x 9" Vinyl Floor Tile. (Approximately 3,404 SF is under Carpet). <5% Physical Damage. Damages noticed by Entry Area (approx. 4 Tiles) and in Electrical Room (~10 Tiles). Material changed from NON to FRIABLE. This Material is in FAIR condition as of this date.					
08/25/2006	Kitchen Restroom added to Location Description. 4 Tiles are broken and cracked by the Kitchen Entry Door. No other changes as of this date.					
10/20/2008	Location Description changed from KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, AND KITCHEN RESTROOM to KITCHEN, KITCHEN STORAGE, ENTRY AREA, ELECTRICAL ROOM, KITCHEN RESTROOM, LOUNGE, LIBRARY, AND OFFICES. Material may be under carpet in Lounge, Offices and Library. No other changed as of this date.					
09/02/2010	Additional Damage observed in the form of 2 Tiles are Damaged at Entry to Kitchen. Material remains in <10% Physical Damage. No other changes as of this date.					

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

11/29/2011	Additional Damage observed - in the form of 4 Tiles are cracked and 3 Tiles are broken, next to Freezer Door, and Mastic/Adhesive is exposed. No other changes as of this date.					
02/16/2018	Additional Damage Observed. 25 Tiles are Cracked and Broken. 35 Tiles have been Replaced with Red 9"x 9" Vinyl Floor Tiles. Remains in FAIR condition. No other changes as of this date.					
01/31/2020	This Material is unchanged as of this date.					
09/01/2020	This Material is unchanged as of this date.					
02/12/2021	This Material is unchanged as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					
08/16/2024	This Material is unchanged as of this date.					
03/03/2025	This Material is unchanged as of this date.					
09/19/2025	This Material is unchanged as of this date.					

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE	4,080 SF	P: Less Than 5% W: No Evidence
--------------	----------	---

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/09/2012	1'x 1' Ceiling Tiles. Tiles are White with a pitted mark form pattern. This Material is in GOOD condition as of this date. (Original Entry updated. 03/19/15.)				
01/31/2020	This Material is unchanged as of this date.				
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Tiles with Scuffs above Stage. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.				
02/12/2021	This Material is unchanged as of this date.				
08/13/2021	This Material is unchanged as of this date.				
02/23/2022	This Material is unchanged as of this date.				
08/19/2022	This Material is unchanged as of this date.				
02/17/2023	This Material is unchanged as of this date.				

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

RISK ASSESMENT CATEGORY

COMMENTS

QTY
(APPROXIMATE)

PHYSICAL DAMAGE (P:)
WATER DAMAGE (W:)

08/18/2023 This Material is unchanged as of this date.
02/16/2024 This Material is unchanged as of this date.
08/16/2024 This Material is unchanged as of this date.
03/03/2025 This Material is unchanged as of this date.
09/19/2025 This Material is unchanged as of this date.

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

MULTIPURPOSE ROOM, AND STAGE

CEILING TILE MASTIC

4,080 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/09/2012 Mastic/Adhesive for 1'x 1' Ceiling Tile. This Material is in GOOD condition as of this date.
01/31/2020 This Material is unchanged as of this date.
09/01/2020 Damage Observed. <5% Physical Damage in the form of 2 Tiles with Scuffs above Stage. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021 This Material is unchanged as of this date.
08/13/2021 This Material is unchanged as of this date.
02/23/2022 This Material is unchanged as of this date.
08/19/2022 This Material is unchanged as of this date.
02/17/2023 This Material is unchanged as of this date.
08/18/2023 This Material is unchanged as of this date.
02/16/2024 This Material is unchanged as of this date.
08/16/2024 This Material is unchanged as of this date.
03/03/2025 This Material is unchanged as of this date.
09/19/2025 This Material is unchanged as of this date.

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

OFFICES, HALLWAYS, LIBRARY, LOUNGE ROOM, AND HEALTH OFFICE

VINYL WALL COVER MASTIC

6,800 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

08/25/2006 Mastic/Adhesive for 4'x 10' and 4'x8' Vinyl Wall Panels (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

01/31/2020	This Material is unchanged as of this date.					
09/01/2020	This Material is unchanged as of this date.					
02/12/2021	Damage Observed. <5% Physical Damage in the form of 4 LF of Torn Vinyl Wall Cover in Hallway between MPR and Kitchen. 1/4 SF Missing Vinyl Wall Cover in Kitchen Hallway at East Entry into MPR and Kitchen. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					
08/16/2024	This Material is unchanged as of this date.					
03/03/2025	This Material is unchanged as of this date.					
09/19/2025	This Material is unchanged as of this date.					

ADMINISTRATION AND MULTI-PURPOSE ROOM BUILDING

PATROL STORAGE

HEAT SHIELD	1 SF	P: Less Than 50% No Debris W: No Evidence
-------------	------	--

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Round Light Fixture Heat Shield. (1 EA). <50% Physical Damage with No Debris. 1 in Patrol Storage is damaged and in POOR condition.					
01/31/2020	This Material is unchanged as of this date.					
09/01/2020	This Material is unchanged as of this date.					
02/12/2021	This Material is unchanged as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					
08/16/2024	This Material is unchanged as of this date.					

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME					
LOCATION					
MATERIAL TYPE			QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:)	
RISK ASSESMENT CATEGORY				WATER DAMAGE (W:)	
COMMENTS					

03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
RISK ASSESMENT CATEGORY	COMMENTS			

CLASSROOMS 03-14 BUILDING

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL

24,000 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

03/08/2007	4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.
11/06/2007	1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

PRESSED WOOD WALL PANEL MASTIC

24,000 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

03/08/2007	Mastic/Adhesive for 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.
11/06/2007	1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME		QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
LOCATION	MATERIAL TYPE		
RISK ASSESMENT CATEGORY			
COMMENTS			

01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

CLASSROOMS 03-14 BUILDING

CLASSROOMS 3-14

VINYL WALL COVER MASTIC

24,000 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Mastic/Adhesive for Vinyl Wall Covering on on 4'x 8' Pressed Wood Wall Panel (over Gypsum Wallboard System). This Material is in GOOD condition as of this date.
11/06/2007	1,000 SF of this Material was removed in Classroom 07 due to fire. (Material Replaced with New 4'x 8' Pressed Wood Wall Panel with Vinyl Wall Cover, (over Gypsum Wallboard System). No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 2 Panels with Holes on Wall with Whiteboard in Classroom 3. 2 Panels with Holes in Southwest Corner of Classroom 9. 1 Panel with 12 Holes near Whiteboard in Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL MISCELLANEOUS

21,260 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005 Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.

05/12/2009 Damage Observed. <5% Physical Damage in the Mechanical Room, next to Classroom 3, in the form of Damage on all Walls, due to punctures, holes, and cuts. Also, approx. 2 LF of separation observed in Mechanical Room, next to Classroom 7, on South Wall. Friability changed from NON to FRIABLE. This Material is in FAIR condition overall. No other changes as of this date.

09/08/2009 Additional Damage observed in Storage Closet of Classroom 13 has 1 Wall to Wall crack on Ceiling in the form of Joint and Taping Mud separation. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

CLASSROOMS 03-14 BUILDING

ENTIRE BUILDING INCLUDING PLENUM

SMOOTH WALL SURFACING

21,260 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Skim Coat for Gypsum Wallboard System Walls and Ceilings, (with Skim Coat, behind other finishes). Existing Gypsum Wallboard Systems Removed and Replaced with new in-kind in Path-of-Construction. This Material is in GOOD condition as of this date.
05/12/2009	Damage Observed. <5% Physical Damage in the Mechanical Room, next to Classroom 3, in the form of Damage on all Walls, due to punctures, holes, and cuts. Also, approx. 2 LF of separation observed in Mechanical Room, next to Classroom 7, on South Wall. Friability changed from NON to FRIABLE. This Material is in FAIR condition overall. No other changes as of this date.
09/08/2009	Additional Damage Observed. Storage Closet of Classroom 13 has 1 Wall to Wall crack on Ceiling in the form of Joint and Taping Mud separation. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
RISK ASSESSMENT CATEGORY	COMMENTS			

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL

30,000 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

03/08/2007	4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/12/2021	This Material is unchanged as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

PRESSED WOOD WALL PANEL MASTIC

30,000 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

03/08/2007	Mastic/Adhesive for 4'x 8' Pressed Wood Wall Panel over Gypsum Wallboard, (with Vinyl Wall Cover). This Material is in GOOD condition as of this date.
01/31/2020	This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

09/01/2020	Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.					
02/12/2021	This Material is unchanged as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					
08/16/2024	This Material is unchanged as of this date.					
03/03/2025	This Material is unchanged as of this date.					
09/19/2025	This Material is unchanged as of this date.					

CLASSROOMS 15-26 BUILDING

CLASSROOMS 15-26

VINYL WALL COVER MASTIC	30,000 SF	P: Less Than 5% W: No Evidence
-------------------------	-----------	-----------------------------------

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005	Mastic/Adhesive for Vinyl Wall Cover, (on 4'x8' Pressed Wood Wall Panel over Gypsum Wallboard). This Material is in GOOD condition as of this date.					
01/31/2020	This Material is unchanged as of this date.					
09/01/2020	Damage Observed. <5% Physical Damage in the form of 1 SF of Missing Material near Sink Area of Classroom 24. 2 Panels with Holes and Gouges in Classroom 19. 1 Detached Panel in Classroom 26. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.					
02/12/2021	Additional Damage Observed. <5% Physical Damage in the form of 7 Holes on North Wall of Classroom 20. Material remains in FAIR condition overall. No other changes as of this date.					
08/13/2021	This Material is unchanged as of this date.					
02/23/2022	This Material is unchanged as of this date.					
08/19/2022	This Material is unchanged as of this date.					
02/17/2023	This Material is unchanged as of this date.					
08/18/2023	This Material is unchanged as of this date.					
02/16/2024	This Material is unchanged as of this date.					

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME		QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
LOCATION	MATERIAL TYPE		
RISK ASSESMENT CATEGORY			
COMMENTS			

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL	4,400 SF	P: Less Than 5% W: No Evidence
------------	----------	---

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/09/2005 Stucco Exterior Walls and Overangs. This Material is in GOOD condition as of this date.

05/12/2009 Damage Observed. <5% Physical Damage Approx. 5 SF of peeling and paint flaking due to heat and moisture observed in Mechanical Rooms, on North Wall, Adjacent to Classrooms 22 & 25. Material Condition changed from GOOD to FAIR overall as of this date. Friability changed from Non-Friable to Friable. No other changes as of this date.

08/31/2017 Partial Repairs Observed. The Exterior Walls are in GOOD condition. The Overhangs remain in FAIR condition. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

09/01/2020 This Material is unchanged as of this date.

02/12/2021 Damage Observed. <5% Physical Damage in the form of 1 LF Crack on Overhang near East Entry into Classroom 21. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

08/13/2021 This Material is unchanged as of this date.

02/23/2022 This Material is unchanged as of this date.

08/19/2022 This Material is unchanged as of this date.

02/17/2023 This Material is unchanged as of this date.

08/18/2023 This Material is unchanged as of this date.

02/16/2024 This Material is unchanged as of this date.

08/16/2024 This Material is unchanged as of this date.

03/03/2025 This Material is unchanged as of this date.

09/19/2025 This Material is unchanged as of this date.

DAMAGE REPORT FOR

LANEVIEW ELEMENTARY SCHOOL

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

CLASSROOMS 15-26 BUILDING

EXTERIOR WALLS AND OVERHANGS

ROUGH WALL SURFACING

4,400 SF

P: Less Than 5%

W: No Evidence

DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM


09/09/2005	Skim Coat for Stucco Exterior Walls and Overhangs. This Material is in GOOD condition as of this date.
05/12/2009	Damage Observed. <5% Physical Damage Approx. 5 SF of peeling and paint flaking due to heat and moisture observed in Mechanical Rooms, on North Wall, Adjacent to Classrooms 22 & 25. Material Condition changed from GOOD to FAIR overall as of this date. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/31/2017	Partial Repairs Observed. The Exterior Walls are in GOOD condition. The Overhangs remain in FAIR condition. No other changes as of this date.
01/31/2020	This Material is unchanged as of this date.
09/01/2020	This Material is unchanged as of this date.
02/12/2021	Damage Observed. <5% Physical Damage in the form of 1 LF Crack on Overhang near East Entry into Classroom 21. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
08/13/2021	This Material is unchanged as of this date.
02/23/2022	This Material is unchanged as of this date.
08/19/2022	This Material is unchanged as of this date.
02/17/2023	This Material is unchanged as of this date.
08/18/2023	This Material is unchanged as of this date.
02/16/2024	This Material is unchanged as of this date.
08/16/2024	This Material is unchanged as of this date.
03/03/2025	This Material is unchanged as of this date.
09/19/2025	This Material is unchanged as of this date.

End Of Report, Total Of 17 Pages

Laneview Elementary School
2095 Warmwood Lane
San Jose, CA 95132

Blacktop area and Playground


Warmwood Lane



Laneview Elementary School
2095 Warmwood Lane
San Jose, CA 95132

Blacktop area and Playground

Warmwood Lane




Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 8-16-24

Blacktop area and Playground

Warmwood Lane




X - Indicates a Gate Entry/Exit
 ■ - Indicates a door

Kinder
 Playground

Laneview Elementary School
2095 Warmwood Lane
San Jose, CA 95132

Blacktop area and Playground

Warmwood Lane




Laneview Elementary School
2095 Warmwood Lane
San Jose, CA 95132

LAKEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 08-18-2023

Blacktop area and Playground


Warmwood Lane



LAKEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 2/17/23

Laneview Elementary School
2095 Warmwood Lane
San Jose, CA 95132


Blacktop area and Playground



Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 08-19-2022



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

BLDG "C"

Warmwood Lane


Port. 3	Port. 1	Port. 2
---------	---------	---------

SDC 1	SDC 2
-------	-------

K 1	K 2
-----	-----

Blacktop area and Playground

Warmwood Lane




Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON: 02-23-2022



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------

SDC 1	SDC 2
-------	-------

K 1	K 2
-----	-----


Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON:

8/13/11



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------

SDC	1
SDC	2

K	2
K	1


Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON:

12/21/2



* Gates open from 8 A.M. - 3 P.M.


S = storage
 M = mechanical
 RR = restroom

Warmwood Lane

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 9/1/20



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port 3
 Port 1
 Port 2

SDC 1
 SDC 2


K 1
 K 2

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON: 1-16-2020



* Gates open from 8 A.M. - 3 P.M.

S = storage

M = mechanical

RR = restroom

BLDG "B"

Warmwood Lane

K	2
K	1

SDC	1
SDC	2

Port. 1	Port. 2
---------	---------

Port. 3


Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON:

12-9-8



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------


SDC	SDC
1	2

K	K
2	1

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 02-08-2019



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port 3	Port 1	Port 2
--------	--------	--------


SDC	SDC
1	2

K	K
2	1

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 8/15/18



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

BLDG "C"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------


SDC 1	SDC 2
-------	-------

K 1	K 2
-----	-----

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 8/19/22



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port 3	Port 1	Port 2
--------	--------	--------


SDC	SDC
-----	-----

K	K
---	---

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 11/13/20



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port 3	Port 1	Port 2
--------	--------	--------

SDC 1	SDC 2
-------	-------


K 2	K 1
-----	-----

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON: 5/3/17



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------


SDC	1
SDC	2

K	2
K	1

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 9/16/16



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------

SDC	SDC
-----	-----


K	K
---	---

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL

INSPECTED ON: 02-18-2016



* Gates open from 8 A.M. - 3 P.M.

S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------


SDC	1
SDC	2

K	1
K	2

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 9-17-15



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

BLDG "C"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------


SDC	1
SDC	2

K	1
K	2

Laneview Elementary School
 2095 Warmwood Lane
 San Jose, CA 95132
 (408) 923-1920

Laneview Drive

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 03-19-2015



* Gates open from 8 A.M. - 3 P.M.
 S = storage
 M = mechanical
 RR = restroom

BLDG "B"

Warmwood Lane

Port. 3	Port. 1	Port. 2
---------	---------	---------

SDC	SDC
-----	-----

K	K
---	---

Krenz 1st Port. 3

Plastic Shed

Green House

Metal Container


YMCA

Welch 1 SDC	Shull 2 SDC
----------------	----------------

Melendez 1st Port. 1	Bates-1st Port. 2
----------------------	-------------------

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 08-29-2014

BLDG "D"




LANEVIEW ELEMENTARY SCHOOL

(408) 923-1920

2095 Warmwood Lane

San Jose, CA 95132-1298



P=Principal's Office
M=Mechanical room

*Gates open from
8 A.M. - 3 P.M.


BLDG "A"

LANEVIEW DRIVE


*gates open from
8 A.M. - 3 P.M.
S=storage

LANEVIEW DRIVE


LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 04-02-13



LANEVIEW ELEMENTARY SCHOOL
(408) 923-1920
2095 Wainwood Lane
San Jose, CA 95132-1298



*gates: open from
8 A.M. - 3 P.M.
S=storage
P=Principal's Office
M=Mechanical room



LANEVIEW DRIVE

Krenz 1st
Port. 3

Plastic Shed

Green House


Metal Container

YMCA

Welch 1 SDC	Shull 2 SDC
----------------	----------------


Melendez 1st Port. 1	Bates-1st Port. 2
-------------------------	----------------------

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 6-9-12



OPEN AIR CORRIDOR

Gates*




OPEN AIR CORRIDOR


Gates*

LANEVIEW ELEMENTARY SCHOOL
(408) 923-1920
2095 Warmwood Lane
San Jose, CA 95132-1298

*Gates open from
8 A.M. - 3 P.M.
S=Storage
P=Principal's Office
M=Mechanical room



LANEVIEW DRIVE



YMCA
Welch 1 SDC Shull 2 SDC

Krenz 1st Port. 3


Melendez 1st Port. 1 Bates-1st Port. 2

Plastic Shed


Green House

Metal Container


LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 11-29-11



OPEN AIR CORRIDOR



OPEN AIR CORRIDOR




LANEVIEW DRIVE


LANEVIEW ELEMENTARY SCHOOL
(408) 923.1920
2095 Warmwood Lane
San Jose, CA 95132.1298

*Gates: open from 8 A.M. - 3 P.M.
S=Storage
P=Principal's Office
M=Mechanical room

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 9/2/10



LANEVUE ELEMENTARY SCHOOL
(408) 923-1920
2095 Wainwood Lane
San Jose, CA 95132-1298




LANEVIEW DRIVE

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 3/9/10

YMCA

Welch	Shull
SDC	SDC



Plastic Storage shed

metal Storage

YMCA

Welch 1 SDC	Shull 2 SDC
----------------	----------------

Krenz 1st Port. 3


Melendez 1st Port. 1

Bates-1st Port. 2


LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 09-08-09

Green Hows

BLDG "D"




BLDG "C"



OPEN AIR CORRIDOR

BLDG "B"




OPEN AIR CORRIDOR

*Gates open from 8 A.M. - 3 P.M.
S=Storage

P=Principal's Office
M=Mechanical room

BLDG "A"



LANEVIEW DRIVE

LANEVIEW ELEMENTARY SCHOOL
(408) 923-1920
2095 Warmwood Lane
San Jose, CA 95132-1298


*gates open from
8 A.M. - 3 P.M.
S=storage
P=Principal's Office
M=mechanical room

Krenz 1st
Port. 3


YMCA	
Welch 1 SDC	Shull 2 SDC

Melendez 1st Port. 1	Bates-1st Port. 2
-------------------------	----------------------


LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 10/20/08



LANEVIEW ELEMENTARY SCHOOL
(408) 923.1920
2095 Warmwood Lane
San Jose, CA 95132.1298



P=Principal's Office
M=Mechanical room
*gates open from
8 A.M. - 3 P.M.
S=Storage




LANEVIEW DRIVE

Krenz 1st Port. 3


YMCA
Welch 1 SDC Shull 2 SDC

Melendez 1st Port. 1 Bates-1st Port. 2


LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON 4-21-08



OPEN AIR CORRIDOR



OPEN AIR CORRIDOR



LANEVIEW DRIVE


LANEVIEW ELEMENTARY SCHOOL
(408) 923.1920
2095 Warmwood Lane
San Jose, CA 95132.1298

Krenz 1st
Port. 3

YMCA
Welch 1 SDC
Shull 2 SDC


Melendez 1st Port. 1
Bates-1st Port. 2

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 11-06-07




OPEN AIR CORRIDOR

LANEVIEW ELEMENTARY SCHOOL
(408) 923-1920
2095 Warmwood Lane
San Jose, CA 95132-1298



OPEN AIR CORRIDOR

Gates*
*gates open from
8 A.M. - 3 P.M.
S=storage
P=Principal's Office
M=Mechanical room







LANEVIEW DRIVE

03/08/07



BERRYESSA UNIFIED
1376 PIEDMONT RD
SAN JOSE, CA 95132




COUNTY: SANTA CLARA
ACREAGE: N/A

SCHOOL NAME: LANEVIEW ELEMENTARY
ADDRESS: 2095 WARWOOD LANE
SCHOOL DISTRICT: BERRYESSA UNIFIED

LANEVIEW ELEMENTARY SCHOOL
 INSPECTED ON: 08-25-04



NOT TO SCALE








NAMING CONVENTION SITEPLAN

SCHOOL NAME: LANEVIEW ELEMENTARY
 ADDRESS: 2095 VARNWOOD LANE
 SCHOOL DISTRICT: BERRYESSA UNIFIED

COUNTY: SANTA CLARA
 ACREAGE: N/A

BERRYESSA UNIFIED
 1376 PIEDMONT RD
 SAN JOSE, CA 95132

LANEVIEW ELEMENTARY SCHOOL
INSPECTED ON: 04/20/06








NOT TO SCALE

NAMING CONVENTION SITEPLAN

SCHOOL NAME: LANEVIEW ELEMENTARY
ADDRESS: 2095 WARMWOOD LANE
SCHOOL DISTRICT: BERRYESSA UNIFIED

COUNTY: SANTA CLARA
ACREAGE: N/A

BERRYESSA UNIFIED
1376 PIEDMONT RD
SAN JOSE, CA 95132



NOT TO SCALE

NAMING CONVENTION SITEPLAN

SCHOOL NAME: LANEVIEW ELEMENTARY
ADDRESS: 2095 WARMWOOD LANE
SCHOOL DISTRICT: BERRYESSA UNIFIED

COUNTY: SANTA CLARA
ACREAGE: N/A

BERRYESSA UNIFIED
1376 PIEDMONT RD
SAN JOSE, CA 95132