

# **Sacramento County Office of Education**

## **2025-26 Williams Site Review Summary**

District: Robla School District  
School Site: Bell Avenue Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/27/2025  
Number of Areas Evaluated: 24

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Good  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

# **Sacramento County Office of Education**

## **2025-26 Williams Site Review Summary**

District: Robla School District  
School Site: Main Avenue Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/27/2025  
Number of Areas Evaluated: 20

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Good  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

# **Sacramento County Office of Education**

## **2025-26 Williams Site Review Summary**

District: Robla School District  
School Site: New Hope Charter

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/18/2025  
Number of Areas Evaluated: 12

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Fair  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

# **Sacramento County Office of Education**

## **2025-26 Williams Site Review Summary**

District: Robla School District  
School Site: Robla Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/28/2025  
Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Good  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

# **Sacramento County Office of Education**

## **2025-26 Williams Site Review Summary**

District: Robla School District  
School Site: Taylor Street Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/22/2025  
Number of Areas Evaluated: 21

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Fair  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.