

## **SIX-MONTH SURVEILLANCE AHERA REPORT**

**CHERRYWOOD ELEMENTARY SCHOOL  
2550 GREENGATE DRIVE  
SAN JOSE, CA 95131**

**PREPARED FOR:  
BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT  
981 RIDDER PARK DRIVE SAN JOSE, CA 95131  
SAN JOSE, CA 95132**

**INSPECTED ON:  
FEBRUARY 26, 2025**

**HAZMAT DOC PROJECT #25-036**

**PREPARED BY:  
HAZMAT DOC  
3080 OLCOTT STREET • SUITE D135  
SANTA CLARA, CA 95054  
Tel: 408.748.0055**

**BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**INSPECTED ON:**  
**FEBRUARY 26, 2025**

**INSPECTED BY:**



---

**Leland Kafeyan**  
**Cal/OSHA Certified Site Surveillance Technician**  
**Certification Number 06-4110**

**REPORTED BY:**

*Maheen B. Doctor*

---

**Maheen B. Doctor**  
**Cal/OSHA Certified Asbestos Consultant**  
**Certification Number 95-1798**

## **CONTENTS**

### **PART - I**

#### **LEGEND AND GLOSSARY OF TERMS**

### **PART – II**

#### **AHERA REPORT A – LIST OF BUILDINGS**

### **PART – III**

#### **AHERA REPORT B – SURVEY REPORT**

### **PART – IV**

#### **HOMOGENEOUS MATERIALS REPORT**

### **PART – V**

#### **FRIABLE LOCATIONS REPORT**

### **PART – VI**

#### **NON-FRIABLE LOCATIONS REPORT**

### **PART – VII**

#### **RECOMMENDATIONS REPORT**

### **PART – VIII**

#### **SAMPLES REPORT**

### **PART – IX**

#### **DAMAGE REPORT**

### **PART - X**

#### **SITE MAPS**

## **LEGEND**

**THE FOLLOWING IS A LIST OF ABBREVIATIONS USED IN THIS REPORT:**

### **Asbestos Sample Types**

|    |   |               |
|----|---|---------------|
| AC | = | ACTINOLITE    |
| AM | = | AMOSITE       |
| AN | = | ANTHOPHYLLITE |
| CH | = | CHRYSOTILE    |
| CR | = | CROCIDOLITE   |
| TR | = | TREMOLITE     |
| ND | = | NONE DETECTED |
| NS | = | NO SAMPLE     |

### **Measurements**

|         |   |                  |
|---------|---|------------------|
| APPROX. | = | APPROXIMATELY    |
| EA      | = | EACH             |
| I       | = | INCHES           |
| LF      | = | LINEAR FEET      |
| N       | = | NUMBER           |
| O.D.    | = | OUTSIDE DIAMETER |
| SF      | = | SQUARE FEET      |
| TBD     | = | TO BE DETERMINED |

# LIST OF BUILDINGS AT

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME                                                                                                                                   | BUILDING AREA<br>(APPROXIMATE)             |
|-------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| BUILDING USED AS<br>( #FLOORS ) CONSTRUCTION                                                                                                    |                                            |
| <b>BOILER ROOM AND STORAGE FACILITIES BUILDINGS</b>                                                                                             |                                            |
| Boiler Room<br>( 1 ) Wood, Gypsum Wallboard System, Concrete                                                                                    | 1,700 SF                                   |
| <b>CLASSROOMS 19 PORTABLE BUILDING</b>                                                                                                          |                                            |
| Classroom<br>( 1 ) Wood and Metal Portable                                                                                                      | 960 SF                                     |
| <b>CLASSROOMS 20 PORTABLE BUILDING</b>                                                                                                          |                                            |
| Classroom<br>( 1 ) Wood and Metal Portable                                                                                                      | 960 SF                                     |
| <b>CLASSROOMS 21-23 PORTABLE BUILDING</b>                                                                                                       |                                            |
| Classrooms<br>( 1 ) Wood and Metal                                                                                                              | 2,880 SF                                   |
| <b>CLASSROOMS 24-26 PORTABLE BUILDING</b>                                                                                                       |                                            |
| Classrooms<br>( 1 ) Wood and Metal Portables                                                                                                    | 2,880 SF                                   |
| <b>LIBRARY PORTABLE BUILDING</b>                                                                                                                |                                            |
| Library<br>( 1 ) Wood and Metal                                                                                                                 | 1,920 SF                                   |
| <b>MAIN BUILDING</b>                                                                                                                            |                                            |
| Classrooms, Multi-Purpose Room, Restrooms, Offices, Library, Kitchen, Storages<br>( 2 ) Wood, Metal, Plaster, Gypsum Wallboard System, Concrete | 32,000 SF                                  |
| <b>METAL STORAGE CONTAINER</b>                                                                                                                  |                                            |
| STORAGE<br>( 1 ) METAL                                                                                                                          | 160 SF                                     |
| <b>ROOM P1 AND P2 KINDERGARDEN BUILDING</b>                                                                                                     |                                            |
| Classrooms<br>( 1 ) Wood and Metal Portables                                                                                                    | 1,920 SF                                   |
| <b>WOOD STORAGE SHED</b>                                                                                                                        |                                            |
| Storage<br>( 1 ) Wood                                                                                                                           | 100 SF                                     |
| Total Number Of Buildings : <u>10</u>                                                                                                           | (Approximate) Total Sq Ft. : <u>45,480</u> |
| End Of Report, Total Of 1 Pages                                                                                                                 |                                            |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### BOILER ROOM AND STORAGE FACILITIES BUILDINGS

### BOILER ROOM AND STORAGE FACILITIES BUILDINGS

#### BOILER ROOM

#### SMOOTH WALL MISCELLANEOUS

900 SF

|            |                                                                                                          |
|------------|----------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Gypsum Wallboard Syste, Walls and Ceilings. This Material is in GOOD condition as of this date.          |
| 02/02/2010 | Samples 10-019 CW-21 (Joint Tape/Compound), and CW-22 (Drywall) collected on this date.                  |
| 09/01/2010 | Quantity Re-Assessed. Material Quantity changed from 700 SF to 900 SF. No other changes as of this date. |
| 01/31/2020 | This Material is unchanged as of this date.                                                              |
| 08/27/2020 | This Material is unchanged as of this date.                                                              |
| 02/09/2021 | This Material is unchanged as of this date.                                                              |
| 08/10/2021 | This Material is unchanged as of this date.                                                              |
| 02/17/2022 | This Material is unchanged as of this date.                                                              |
| 08/16/2022 | This Material is unchanged as of this date.                                                              |
| 02/14/2023 | This Material is unchanged as of this date.                                                              |
| 08/15/2023 | This Material is unchanged as of this date.                                                              |
| 02/13/2024 | This Material is unchanged as of this date.                                                              |
| 08/13/2024 | This Material is unchanged as of this date.                                                              |
| 02/26/2025 | This Material is unchanged as of this date.                                                              |

|              |    |               |        |
|--------------|----|---------------|--------|
| 10-019 CW-21 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-21 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-22 | ND | NONE DETECTED | ( ND ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

### CLASSROOMS 19 PORTABLE BUILDING

### CLASSROOMS 19 PORTABLE BUILDING

09/07/2005 BUILDING NOTES:

09/07/2005 Manufacturer's TAG info:  
BY AMERICAN MODULAR SYS; DATE 05-99; SERIAL# 99-R320-656A, 99-R320-656B.  
This entry for informational and tracking purposes.

03/08/2007 Building Name changed from PORTABLE 19 to CLASSROOMS 19 PORTABLE BUILDING.

### CLASSROOMS 19 PORTABLE BUILDING

PORTABLE 19

PORTABLE BUILDING

960 SF

09/07/2005 New 1999 Construction Relocatable Building per Manufacturer's tag information.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

### CLASSROOMS 20 PORTABLE BUILDING

### CLASSROOMS 20 PORTABLE BUILDING

03/06/2017 BUILDING NOTES:

09/07/2005 Manufacturer's TAG info:  
BY AMERICAN MODULAR SYS; DATE 07-96; OSA# 65133; SERIAL# 96-R243-005A, 96-R243-005B.  
This entry for informational and tracking purposes.

03/08/2007 Building Name changed from PORTABLE 20 to CLASSROOMS 20 PORTABLE BUILDING.

10/17/2008 Serial #'s changed from SERIAL# 96-R24-005A, 96-R24-005B TO SERIAL# 96-R243-005A, 96-R243-005B.

### CLASSROOMS 20 PORTABLE BUILDING

PORTABLE 20

PORTABLE BUILDING

960 SF

09/07/2005 New 1996 Construction Relocatable Building per manufacturer's tag information.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### CLASSROOMS 21-23 PORTABLE BUILDING

### CLASSROOMS 21-23 PORTABLE BUILDING

03/06/2017 BUILDING INFORMATION:

03/06/2017 Manufacturer's Tag Info:  
By American Modular System; Date 04-06; OSA # 01-107957; Serial #'s:  
Classroom 21 06-222-001A, 06-222-001B  
Classroom 22 06-222-002A, 06-222-002B  
Classroom 23 06-222-003A, 06-222-003B  
This entry for informational and tracking purposes.

### CLASSROOMS 21-23 PORTABLE BUILDING

PORTABLES 21-23

PORTABLE BUILDING

2,880 SF

10/17/2008 New 2006 Construction Relocatable Buildings per Manufacturer's Tag information.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|           |     |           |        |
|-----------|-----|-----------|--------|
| 08-241AAA | NEW | NO SAMPLE | ( NS ) |
|-----------|-----|-----------|--------|

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

### CLASSROOMS 24-26 PORTABLE BUILDING

### CLASSROOMS 24-26 PORTABLE BUILDING

09/07/2005 BUILDING NOTES:

09/07/2005 Manufacturer's TAG Info: BY AMERICAN MODULAR SYS; DATE 07-04; OSA# 02-106165; SERIAL#'S  
CLASSROOM 24 = 04-906-498A, 04-906-498B; CLASSROOM 25 = 04-906-497A, 04-906-497B;  
CLASSROOM 26 = 04-906-499A, 04-906-499B.  
This entry for informational and tracking purposes.

03/08/2007 Building Name changed from PORTABLES 24-26 to CLASSROOMS 24-26 PORTABLE BUILDING.

### CLASSROOMS 24-26 PORTABLE BUILDING

PORTABLES 24-26

PORTABLE BUILDING

2,880 SF

09/07/2005 New 2004 Construction Relocatable Building per Manufacturer's Tag information.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

### LIBRARY PORTABLE BUILDING

### LIBRARY PORTABLE BUILDING

09/07/2005 BUILDING NOTES:

09/07/2005 TAG: BY AMERICAN MODULAR SYS; DATE 04-06; SERIAL# 06-222-005A, 06-222-005B, 06-222-005C, 06-222-005D. This entry for informational and tracking purposes.

03/08/2007 Building Name changed from LIBRARY BUILDING (NEW) to LIBRARY PORTABLE BUILDING.

12/02/2011 DSA# 01-107922

### LIBRARY PORTABLE BUILDING

LIBRARY PORTABLE

PORTABLE BUILDING

1,920 SF

09/07/2005 New 2006 Construction Relocatable Building per Manufacturer's Tag information.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

### MAIN BUILDING

#### 2ND FLOOR

#### CARPET MASTIC

420 SF

|            |                                                                                                                                                                                                                                                                                                                                              |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive for Gray-Black Carpet. This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                   |
| 08/23/2006 | 20,000 SF of this Material Removed from First Level in all Classrooms, Offices, Common Areas, and Hallways and Replaced with new Mastic for Charcoal Colored Carpet as of this date. Quantity changed from 22,640 SF to 2,640 SF to reflect this fact. Location changed from Entire Building to 2nd Floor. No other changes as of this date. |
| 09/01/2010 | 8 SF of Carpet Removed; exposing the Mastic/Adhesive. Friability changed from Non-Friable to Friable. Damage <5% overall. No other changes as of this date.                                                                                                                                                                                  |
| 04/05/2013 | Material Condition Re-Assessed. Damages Repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                                                                                            |
| 09/12/2016 | Damage observed. Damage: <5% Physical Damage - 2 areas near Restrooms have Carpet removed; with some Mastic/Adhesive exposed. Material Condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.                                                                        |
| 03/28/2017 | Material Re-assessed. Quantity changed from 2,640 SF to 2624 SF. Removal of Carpet Mastic by Restrooms. No other changes as fo this date.                                                                                                                                                                                                    |
| 08/28/2017 | Additional Damage Observed. Hallway on the 2nd Floor now has half of the Carpet Wrikled or Loose. No other changes as of this date.                                                                                                                                                                                                          |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/17/2022 | Material Re-assessed. Quantity changed from 2,640 SF to 420 SF, Gray Black Carpet only found on stairs and Landing. No other chagnes as of this date.                                                                                                                                                                                        |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

#### 2ND FLOOR

##### VINYL SHEETING

2,640 SF

09/07/2005 Gray Vinyl Floor Covering and 6"x36" Light Brown Wood Design Vinyl Tile. This Material is in GOOD condition as of this date (Original Entry updated on 08/16/22).

10/17/2008 Location Description changed from 2ND FLOOR, AND ADMIN RECEPTIONIST AREA to 2ND FLOOR. No other changes as of this date.

09/09/2009 Vinyl Sheeting is Beige/Cream with Brown Speckles. Original entry updated. No other changes as of this date.

08/30/2017 Sample Collected 17-183-3C-22, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 Material Re-Assessed. Material not observed, Material may exist under current Gray Vinyl Floor Covering and 6"x36" Light Brown Wood Design Vinyl Tile. Half of the Second Story Floor is Gray Vinyl Floor Covering and other half is 6"x36" Light Brown Wood Design Vinyl Tile. No other changes as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |    |               |        |
|--------------|----|---------------|--------|
| 17-183 3C-22 | ND | NONE DETECTED | ( ND ) |
|--------------|----|---------------|--------|

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

#### 2ND FLOOR

VINYL SHEETING BACKING PAPER/MASTIC

2,160 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Backing Paper for Gray Vinyl Floor Covering and 6"x36" Light Brown Wood Design Vinyl Tile. This Material is in GOOD condition as of this date (Original Entry updated on 08/16/22).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 09/09/2009 | Vinyl Sheeting is Beige/Cream with Brown Speckles. Original entry updated. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 08/30/2017 | Sample Collected 17-183-3C-23-Sheet Flooring, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. Sample Collected 17-183-3C-23-Mastic, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. Sample Collected 17-183-3C-23-Leveler, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. Sample Collected 17-183-3C-24-Mastic, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. Sample Collected 17-183-3C-24-Leveler, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 08/16/2022 | Material Re-Assessed. Material not observed, Material may exist under current Gray Vinyl Floor Covering and 6"x36" Light Brown Wood Design Vinyl Tile. Half of the Second Story Floor is Gray Vinyl Floor Covering and other half is 6"x36" Light Brown Wood Design Vinyl Tile. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |

|                             |    |               |        |
|-----------------------------|----|---------------|--------|
| 17-183-3C-23-Sheet Flooring | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-23-Mastic         | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-23-Leveler        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-24-Mastic         | ND | NONE DETECTED | ( ND ) |

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO.           | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|----------------------|------------------|---------------|---------------|
| 17-183-3C-24-Leveler | ND               | NONE DETECTED | ( ND )        |

### MAIN BUILDING

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS (CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

2,620 SF

|            |                                                                                                                                                                                                                                                                                                             |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/09/2009 | Grout/Mortar for 4"x4" Multicolored Ceramic Wall Tiles. This Material is in GOOD condition as of this date.                                                                                                                                                                                                 |
| 03/12/2010 | Location Description changed from 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS) to 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS (CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING. Quantity changed from 280 SF to 2,620 SF. No other changes as of this date. |
| 08/30/2017 | Sample Collected 17-183-3C-01, Mezzanine, 200 Women Restroom, 4" Ceramic Wall Tile Grout. Sample Collected 17-183-3C-02, Mezzanine, 200 Women Restroom, 4" Ceramic Wall Tile Backing Board.                                                                                                                 |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 08/27/2020 | Damage Observed. <5% Physical Damage in the form of 6 Tiles with Holes in Girls Restroom next to Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                                                      |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                 |

|              |    |               |        |
|--------------|----|---------------|--------|
| 17-183 3C-01 | ND | NONE DETECTED | ( ND ) |
| 17-183 3C-02 | ND | NONE DETECTED | ( ND ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS' RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

1,270 SF

|            |                                                                                                                                                                                                                                                                                                                        |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/09/2009 | Grout/Mortar for 12"x12" Tan Ceramic Floor Tiles. This Material is in GOOD condition as of this date.                                                                                                                                                                                                                  |  |  |
| 03/12/2010 | Location Description changed from 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS) to 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS' RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING. Quantity changed from 220 SF to 1,270 SF. No other changes as of this date. |  |  |
| 08/30/2017 | Sample Collected 17-183-3C-03, Mezzanine, 200 Women Restroom, 12" Ceramic Floor Tile Grout. Sample Collected 17-183-3C-04, Mezzanine, 200 Women Restroom, 12" Ceramic Floor Tile Mortar Bed.                                                                                                                           |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                            |  |  |

|              |    |               |        |
|--------------|----|---------------|--------|
| 17-183 3C-03 | ND | NONE DETECTED | ( ND ) |
| 17-183 3C-04 | ND | NONE DETECTED | ( ND ) |

### MAIN BUILDING

2ND FLOOR STORAGE CLOSET AND ATTIC AREAS

DUCT WRAP TAPE

200 SF

|            |                                                                                                                                        |  |  |
|------------|----------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | White Duct Joint Tape and Tan Duct Joint Sealant (Original Entry Updated 8/16/22). This Material is in GOOD condition as of this date. |  |  |
|------------|----------------------------------------------------------------------------------------------------------------------------------------|--|--|

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                          | ASBESTOS NAME | ASBESTOS CODE |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 08/30/2017 | Sample Collected 17-183-3C-18, Mezzanine, Mech Room, Air Ductwork Joint Tape and Mastic. Sample Collected 17-183-3C-18-Joint Tape, Mezzanine, Mech Room, Air Ductwork Joint Tape and Mastic.                                              |               |               |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 08/16/2022 | Material Re-Assessed. White Duct Joint Tape and Sealant exists above Ceiling in Attic Area Only. Storage Closet has 3 LF of Red Brown Sealant on Ceiling and Wall where the Duct goes through the Wall. No other changes as of this date. |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                               |               |               |

|                         |    |               |        |
|-------------------------|----|---------------|--------|
| 17-183-3C-18-Mastic     | 10 | CHRYSTILE     | ( CH ) |
| 17-183-3C-18-Joint Tape | ND | NONE DETECTED | ( ND ) |

### MAIN BUILDING

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE

450 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                           |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Beige, Light Brown, and Gray Black 12"x12" Vinyl Floor Tile (Original Entry Updated 8/16/22). This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                         |
| 08/23/2006 | Material Removed in 2 Restrooms and Replaced with Hard Tile Material. Quantity originally passed in error. Quantity remains the same (530 SF). Location changed from STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, AND WOMENS RESTROOM to STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE. No other changes as of this date. |
| 03/08/2007 | Location Description changed from STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE to 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE. Quantity remains the same. No other changes as of this date.                                                                                                                                                            |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO.                     | ASBESTOS CONTENT                                                                                                                                                                                                                                                                                                                                          | ASBESTOS NAME | ASBESTOS CODE           |
|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------------|
| 10/12/2012                     | Damage: <5% Physical Damage and <10% Water Damage - in the form of approximately 80 SF of Material Removed in Supply Room, due to Water Leak. Mastic/Adhesive is exposed. Quantity changed from 530 SF to 450 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |               |                         |
| 04/05/2013                     | Damages Re-Assessed and Water Damage was located in Teacher's Lounge Room, not Supply Storage Room as previously noted. Damages to Floor and exposed Mastic/Adhesive have been covered with new Vinyl Sheeting. Material is now in GOOD condition overall as of this date.                                                                                |               |                         |
| 03/28/2017                     | Damage Observed. <5% Physical Damage - in the form of Broken Edges and Exposed Mastic by Women's Restroom at of Carpet. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.                                                                                                       |               |                         |
| 08/30/2017                     | Sample Collected 17-183-3C-16, Mezzanine, 205 Nurses Floor, 12" Beige Vinyl Floor Tile.                                                                                                                                                                                                                                                                   |               |                         |
| 08/08/2018                     | Material Re-assessed. New Vinyl Floor Tile in Nurse's Office and Teachers Lounge. No other changes as of this date.                                                                                                                                                                                                                                       |               |                         |
| 01/31/2020                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 08/27/2020                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 02/09/2021                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 08/10/2021                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 02/17/2022                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 08/16/2022                     | Material Re-Assessed. Material not observed in Nurses Office and Teachers Lounge, Material may exist under current Beige, Light Brown, and Gray Black 12"x12" Vinyl Floor Tile. No other changes as of this date.                                                                                                                                         |               |                         |
| 02/14/2023                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 08/15/2023                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 02/13/2024                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 08/13/2024                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| 02/26/2025                     | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                               |               |                         |
| <b>17-183-3C-16-Floor Tile</b> |                                                                                                                                                                                                                                                                                                                                                           | <b>3</b>      | <b>CHRYSTILE ( CH )</b> |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE MASTIC

530 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                           |  |  |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | Mastic/Adhesive Beige, Light Brown, and Gray Black 12"x12" Vinyl Floor Tile (Original Entry Updated 8/16/22). This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                         |  |  |
| 08/23/2006 | Material Removed in 2 Restrooms and Replaced with Hard Tile Material. Quantity originally passed in error. Quantity remains the same (530 SF). Location changed from STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, AND WOMENS RESTROOM to STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE. No other changes as of this date. |  |  |
| 03/08/2007 | Location Description changed from STAFF MENS RESTROOM, SECOND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE to 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE. Quantity remains the same. No other changes as of this date.                                                                                                                                                            |  |  |
| 10/12/2012 | Damage Observed. <5% Physical Damage and <10% Water Damage - in the form of approximately 80 SF of Material Removed in Supply Room, due to Water Leak. Mastic/Adhesive is exposed. Quantity changed from 530 SF to 450 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.                                        |  |  |
| 04/05/2013 | Damages Re-Assessed and Water Damage was located in Teacher's Lounge Room, not Supply Storage Room as previously noted. Damages to Floor and exposed Mastic/Adhesive have been covered with new Vinyl Sheeting. Material is now in GOOD condition overall as of this date.                                                                                                                                |  |  |
| 03/28/2017 | Damage Observed. <5% Physical Damage - in the form of Broken Edges and Exposed Mastic by Women's Restroom at of Carpet. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.                                                                                                                                                       |  |  |
| 08/30/2017 | Sample Collected 17-183-3C-16-Mastic, Mezzanine, 205 Nurses Room, 12" Beige Vinyl Floor Tile Mastic.<br>Sample Collected 17-183-3C-17-Mastic, Mezzanine, 205 Nurses Room, 12" Beige Vinyl Floor Tile Mastic.<br>Sample Collected 17-183-3C-17-Leveler, Mezzanine, 205 Nurses Room, 12" Beige Vinyl Floor Tile Mastic.                                                                                     |  |  |
| 08/08/2018 | Material Re-assessed. New Vinyl Floor Tile in Nurse's Office and Teachers Lounge. No other changes as of this date.                                                                                                                                                                                                                                                                                       |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 08/16/2022 | Material Re-Assessed. Material not observed in Nurses Office and Teachers Lounge, Material may exist under current Beige, Light Brown, and Gray Black 12"x12" Vinyl Floor Tile. No other changes as of this date.                                                                                                                                                                                         |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|                      |    |               |        |
|----------------------|----|---------------|--------|
| 17-183-3C-16         | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-17-Mastic  | 5  | CHRYSTILE     | ( CH ) |
| 17-183-3C-17-Leveler | 2  | CHRYSTILE     | ( CH ) |

### MAIN BUILDING

2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

900 SF

02/26/2025 Brown and Gray Vinyl Floor Sheeting. This Material is in GOOD condition as of this date.

|           |     |           |        |
|-----------|-----|-----------|--------|
| 25-036.NS | NEW | NO SAMPLE | ( NS ) |
|-----------|-----|-----------|--------|

### MAIN BUILDING

2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

900 SF

02/26/2025 Backing Paper/Adhesive for Brown and Gray Vinyl Floor Sheeting. This Material is in GOOD condition as of this date.

|           |     |           |        |
|-----------|-----|-----------|--------|
| 25-036.NS | NEW | NO SAMPLE | ( NS ) |
|-----------|-----|-----------|--------|

### MAIN BUILDING

ALL CLASSROOMS, 1ST LEVEL, LIBRARY, LIBRARY OFFICES

CARPET MASTIC

20,000 SF

08/08/2018 Mastic/Adhesive for Black and Grey Carpet, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|           |     |               |        |
|-----------|-----|---------------|--------|
| 18-127AAA | NEW | NONE DETECTED | ( ND ) |
|-----------|-----|---------------|--------|

### MAIN BUILDING

ALL CLASSROOMS, AND MULTI-USE ROOM

WALL MASTIC

8,900 SF

09/07/2005 Mastic/Adhesive for 4'X8' Glued Wall Panels. This Material is in GOOD condition as of this date.

08/23/2006 Offices (Administration Section) added to Location. 4,500 SF added to quantity. Material Quantity changed from 11,200 SF to 15,700 SF to reflect this fact. No other changes as of this date.

11/08/2007 Material Re-Assessed. Damage Observed. <5% Physical Damage - due to approximately 1 SF cut and removed in 2nd Floor Hallway. Friability changed from Low to Moderate. Recommendation changed to reflect this fact. No other changes as of this date.

09/09/2009 Material remains in FAIR condition overall with several holes, cuts and gouging. This Material is unchanged as of this date.

09/01/2010 Material Re-Assessed. Location changed from ALL CLASSROOMS, AND OFFICES (ADMINISTRATION SECTION) to ALL CLASSROOMS, AND MULTI-USE ROOM. Quantity changed from 15,700 SF to 8,900 SF. Panels are on the Walls and Ceiling. No other changes as of this date.

09/12/2016 Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.

08/28/2017 Damage Observed. <5% Physical Damage - in the form of 3 Small Holes in the Wall Panel by the Ramp in the Hallway to MPR. Material Condition changed from GOOD to FAIR. Friability changed from NON to LOW. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

16

***HazMat Doc***

AHERA Report B - Survey

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                            | ASBESTOS NAME | ASBESTOS CODE |
|------------|---------------------------------------------|---------------|---------------|
| 08/10/2021 | This Material is unchanged as of this date. |               |               |
| 02/17/2022 | This Material is unchanged as of this date. |               |               |
| 08/16/2022 | This Material is unchanged as of this date. |               |               |
| 02/14/2023 | This Material is unchanged as of this date. |               |               |
| 08/15/2023 | This Material is unchanged as of this date. |               |               |
| 02/13/2024 | This Material is unchanged as of this date. |               |               |
| 08/13/2024 | This Material is unchanged as of this date. |               |               |
| 02/26/2025 | This Material is unchanged as of this date. |               |               |

### MAIN BUILDING

ALL CLASSROOMS, AND MULTI-USE ROOM

WALL PANEL

8,900 SF

|            |                                                                                                                                                                                                                                                             |  |  |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | 4'X8' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.                                                                                                                                                                            |  |  |
| 08/23/2006 | Offices (Administration Section) added to Location. 4,500 SF added to quantity. Material Quantity changed from 11,200 SF to 15,700 SF to reflect this fact. No other changes as of this date.                                                               |  |  |
| 11/08/2007 | Material Re-Assessed. Damage: <5% Physical Damage - due to approximately 1 SF cut and removed in 2nd Floor Hallway. Recommendation changed to reflect this fact. No other changes as of this date.                                                          |  |  |
| 09/09/2009 | Material remains in FAIR condition overall with several holes, cuts and gouging. This Material is unchanged as of this date.                                                                                                                                |  |  |
| 02/02/2010 | Samples 10-019 CW-07 and CW-10 collected on this date.                                                                                                                                                                                                      |  |  |
| 09/01/2010 | Material Re-Assessed. Location changed from ALL CLASSROOMS, AND OFFICES (ADMINISTRATION SECTION) to ALL CLASSROOMS, AND MULTI-USE ROOM. Quantity changed from 15,700 SF to 8,900 SF. Panels are on the Walls and Ceiling. No other changes as of this date. |  |  |
| 09/12/2016 | Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                         |  |  |
| 08/28/2017 | Damage Observed. <5% Physical Damage - in the form of 3 Small Holes in the Wall Panel by the Ramp located in the Hallway to MPR. Material Condition changed from GOOD to FAIR. No othe changes as of this date.                                             |  |  |
| 01/31/2020 | Repairs Observed. All Damage Repaired. Material Condition changed from FAIR to GOOD. Friability updated from Friable to Non-Friable. No other changes as of this date.                                                                                      |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO.   | ASBESTOS CONTENT                            | ASBESTOS NAME | ASBESTOS CODE |
|--------------|---------------------------------------------|---------------|---------------|
| 08/27/2020   | This Material is unchanged as of this date. |               |               |
| 02/09/2021   | This Material is unchanged as of this date. |               |               |
| 08/10/2021   | This Material is unchanged as of this date. |               |               |
| 02/17/2022   | This Material is unchanged as of this date. |               |               |
| 08/16/2022   | This Material is unchanged as of this date. |               |               |
| 02/14/2023   | This Material is unchanged as of this date. |               |               |
| 08/15/2023   | This Material is unchanged as of this date. |               |               |
| 02/13/2024   | This Material is unchanged as of this date. |               |               |
| 08/13/2024   | This Material is unchanged as of this date. |               |               |
| 02/26/2025   | This Material is unchanged as of this date. |               |               |
| 10-019 CW-07 | ND                                          | NONE DETECTED | ( ND )        |
| 10-019 CW-10 | ND                                          | NONE DETECTED | ( ND )        |

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING MASTIC

23,350 SF

|            |                                                                                                                                                                                    |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive FOR 1'X1' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.                                                                               |
| 08/23/2006 | Administration Offices added to Location. 2,000 SF added to quantity. Quantity changed from 21,350 SF to 23,350 SF to reflect this fact. No other changes as of this date.         |
| 10/17/2008 | Room 4 has 5 Tiles Water Stained. Friability changed from Non-Friable to Friable to reflect this fact. No other changes as of this date.                                           |
| 05/15/2009 | Mastic/Adhesive damaged and exposed where 1 Tile is missing in the 2nd FLOOR Staff Room. Water damage is still present. This Material is in FAIR condition as of this date.        |
| 09/09/2009 | Material remains in <5% physical damage and <10% water damage. This Material is unchanged as of this date.                                                                         |
| 02/02/2010 | Samples 10-019 CW-09 and 10-019 CW-16 collected on this date.                                                                                                                      |
| 09/01/2010 | This Material is on the Walls and Ceiling. Room 5 has 10 Tiles missing, exposing the Mastic and Room 16 has 1 Tile missing, exposing the Mastic. No other changes as of this date. |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                                                      | ASBESTOS NAME | ASBESTOS CODE |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 12/02/2011 | Additional Damage - in the form of Classroom 9 has 4 Tiles Water stained, and Classroom 4 has 8 Tiles Water Damaged. Previously noted Room 5 Damage with 10 Tiles missing has been Repaired. Material remains in FAIR condition as of this date.                      |               |               |
| 10/12/2012 | Additional Damage - in the form of Classroom 16 has 1 Tile missing and Mastic/Adhesive is exposed. No other changes as of this date.                                                                                                                                  |               |               |
| 04/05/2013 | Material condition Re-Assessed. Damaged Tiles in Classroom 09 have been Removed and Replaced with new Tiles. Material remains in FAIR condition overall as of this date.                                                                                              |               |               |
| 08/29/2014 | Material Re-Assessed. Classroom 2 has 1 Ceiling Tile Broken. Classroom 5 has 2 Ceiling Tiles Broken. No other changes as of this date.                                                                                                                                |               |               |
| 03/16/2015 | Classroom 1 has 1 Tile missing and Brown Mastic/Adhesive is exposed. No other changes as of this date.                                                                                                                                                                |               |               |
| 09/12/2016 | Additional Damage observed. Prep Room has 2 broken Tiles. Room 13 has 3 Tiles coming loose. No other changes as of this date.                                                                                                                                         |               |               |
| 03/28/2017 | Material Re-assessed. 75% of Material has been removed from Classroom 11, currently undergoing Construction.                                                                                                                                                          |               |               |
| 08/28/2017 | Additional Damage and Repairs Observed. Classroom 4 now has 7 Tiles with Water Damage. Staff Lounge (Located in the 2nd Floor) now has 1 Tile Missing. Mastic/Adhesive is exposed. All the Tiles in Classroom 11 have been Removed. No other changes as of this date. |               |               |
| 02/13/2018 | Material Re-assessed. All Tiles in Classroom 11 have been Replaced. Other Damage still present. No other changes as of this date.                                                                                                                                     |               |               |
| 08/08/2018 | Additional Damage Observed. 8 Tiles now have Water Damage in Classroom 4. Several Tiles have Chipped Corners in Classroom 1 and in Scattered Locations. No other changes as of this date.                                                                             |               |               |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 08/27/2020 | Damage Observed. <5% Physical Damage in the form of 6 Tiles with Holes in Girls Restroom next to Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                           |               |               |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |    |               |        |
|--------------|----|---------------|--------|
| 10-019 CW-16 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-09 | ND | NONE DETECTED | ( ND ) |

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING TILE

23,350 SF

09/07/2005 1'X1' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.

08/23/2006 Administration Offices added to Location. 2,000 SF added to quantity. Quantity changed from 21,350 SF to 23,350 SF to reflect this fact. No other changes as of this date.

10/17/2008 Room 4 has 5 Tiles Water Stained. No other changes as of this date.

05/15/2009 1 Tile is missing in the 2nd FLOOR Staff Room. Water Damage is still present. This Material is in FAIR condition as of this date.

09/09/2009 Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.

02/02/2010 Samples 10-019 CW-08 and 10-019 CW-15 collected on this date.

09/01/2010 This Material is on the Walls and Ceiling. Room 5 has 10 Tiles missing, exposing the Mastic/Adhesive and Room 16 has 1 Tile missing, exposing the Mastic/Adhesive. No other changes as of this date.

12/02/2011 Additional Damage - in the form of Classroom 9 has 4 Tiles Water stained, and Classroom 4 has 8 Tiles Water Damaged. Previously noted Room 5 with 10 Tiles missing has been repaired. Material remains in FAIR condition as of this date.

10/12/2012 Additional Damage - in the form of Classroom 16 has 1 Tile missing and Mastic is exposed. No other changes as of this date.

04/05/2013 Material condition Re-Assessed. Damaged Tiles in Classroom 09 have been Removed and Replaced with new Tiles. Material remains in FAIR condition overall as of this date.

03/04/2014 1 Tile Broken in Classroom 15 and 3 Tiles have holes in Classroom 6. Friability changed from Low to High. No other changes as of this date.

08/29/2014 Material Re-Assessed. Classroom 2 has 1 Broken Ceiling Tile. Classroom 5 has 2 Ceiling Tiles Broken. No other changes as of this date.

03/16/2015 Classroom 1 has 1 Tile missing and Brown Mastic/Adhesive is exposed. No other changes as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

20

**HazMat Doc**

AHERA Report B - Survey

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO.   | ASBESTOS CONTENT                                                                                                                                                                                                                                                                          | ASBESTOS NAME | ASBESTOS CODE |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 09/12/2016   | Additional Damage observed. Prep Room has 2 broken Tiles. Room 13 has 3 Tiles coming loose. No other changes as of this date.                                                                                                                                                             |               |               |
| 08/28/2017   | Additional Damage and Repairs Observed. Classroom 4 now has 7 Tiles with Water Damage. Staff Lounge (Located in the 2nd Floor) now has 1 Tile Missing. Mastic/Adhesive is exposed. All the Tiles in Classroom 11 have been Removed. No other changes as of this date.                     |               |               |
| 08/30/2017   | Sample Collected 17-183 3C-05, Mezzanine, 201 Computer Area, 1'X'1 Ceiling Tile. Sample Collected 17-183 3C-06, Mezzanine, 201 Computer Area, 1'X'1 Ceiling Tile, Brown Mastic. Sample Collected 17-183 3C-07, Mezzanine, 201 Computer Area, (Under 1'X'1 Ceiling Tile) Acoustic Texture. |               |               |
| 02/13/2018   | Additional Damage Observed. 8 Tiles now have Water Damage in Classroom 4. Several Tiles have Chipped Corners in Classroom 1 and in Scattered Locations. No other changes as of this date.                                                                                                 |               |               |
| 01/31/2020   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 08/27/2020   | Damage Observed. <5% Physical Damage in the form of 6 Tiles with Holes in Girls Restroom next to Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                                    |               |               |
| 02/09/2021   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 08/10/2021   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 02/17/2022   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 08/16/2022   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 02/14/2023   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 08/15/2023   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 02/13/2024   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 08/13/2024   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 02/26/2025   | This Material is unchanged as of this date.                                                                                                                                                                                                                                               |               |               |
| 10-019 CW-15 | ND                                                                                                                                                                                                                                                                                        | NONE DETECTED | ( ND )        |
| 10-019 CW-08 | ND                                                                                                                                                                                                                                                                                        | NONE DETECTED | ( ND )        |
| 17-183 3C-05 | ND                                                                                                                                                                                                                                                                                        | NONE DETECTED | ( ND )        |
| 17-183 3C-06 | ND                                                                                                                                                                                                                                                                                        | NONE DETECTED | ( ND )        |
| 17-183 3C-07 | ND                                                                                                                                                                                                                                                                                        | NONE DETECTED | ( ND )        |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE

VINYL FLOOR TILE

4,700 SF

|            |                                                                                                                                                                                                                                                                  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/08/2018 | 12"x12" Off White, Beige and Gray Vinyl Floor Tile, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date.                                                                                                                    |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 Tile Missing in Corner Dark Brown Mastic Exposed in Lab Room 18. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |

18-127AAA

NEW

NONE DETECTED

( ND )

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE

VINYL FLOOR TILE MASTIC

4,700 SF

|            |                                                                                                                                                                                                                                                                  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/08/2018 | Mastic/Adhesive for 12"x12" Off White, Beige and Gray Vinyl Floor Tile, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date.                                                                                                |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 Tile Missing in Corner Dark Brown Mastic Exposed in Lab Room 18. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                            | ASBESTOS NAME | ASBESTOS CODE |
|------------|---------------------------------------------|---------------|---------------|
| 08/10/2021 | This Material is unchanged as of this date. |               |               |
| 02/17/2022 | This Material is unchanged as of this date. |               |               |
| 08/16/2022 | This Material is unchanged as of this date. |               |               |
| 02/14/2023 | This Material is unchanged as of this date. |               |               |
| 08/15/2023 | This Material is unchanged as of this date. |               |               |
| 02/13/2024 | This Material is unchanged as of this date. |               |               |
| 08/13/2024 | This Material is unchanged as of this date. |               |               |
| 02/26/2025 | This Material is unchanged as of this date. |               |               |
| 18-127AAA  | NEW                                         | NONE DETECTED | ( ND )        |

### MAIN BUILDING

ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE

SINK UNDERCOATING

80 SF

|            |                                                                                                                                                                                                                                                               |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 10/17/2008 | Black and Beige Thermal Undercoating on Sink (19 EA Sink). This Material is in GOOD condition as of this date.                                                                                                                                                |
| 05/15/2009 | Additional Material identified. Location changed from ALL CLASSROOMS, TEACHER LOUNGE, AND NURSE'S OFFICE to ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE. Quantity changed from 76 SF to 80 SF. No other changes as of this date. |
| 04/10/2012 | Undercoating is Black. No other changes as of this date.                                                                                                                                                                                                      |
| 10/12/2012 | Thermal Undercoating is Black and Beige. Original entry updated. No other changes as of this date.                                                                                                                                                            |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                   |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 08-241AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

BOILER ROOM

BOILER INSULATION

0 SF

09/07/2005 Boiler Insulation. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 Inspector was not able to locate this area during this inspection. No other Chages as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 Material not Observed. Boiler Unit not Observed in Boiler Room, only Water Heater Tank. Material Quantity changed from 50 SF to 0 SF. No other changes as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 23-093REM | REMOVED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)

VINYL FLOOR TILE

1,200 SF

08/08/2018 12"x12" Off White, Beige, Grey, Blue, Light Brown and Black Vinyl Floor Tile (Original Entry Updated 8/16/22). This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT                                                                          | ASBESTOS NAME | ASBESTOS CODE |
|------------|-------------------------------------------------------------------------------------------|---------------|---------------|
| 02/09/2021 | This Material is unchanged as of this date.                                               |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                               |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                               |               |               |
| 08/16/2022 | Material Re-Assessed. Stage has Black Vinyl Floor Tile. No other changes as of this date. |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                               |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                               |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                               |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                               |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                               |               |               |
| 18-127AAA  | NEW                                                                                       | NONE DETECTED | ( ND )        |

### MAIN BUILDING

CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)

VINYL FLOOR TILE MASTIC

1,200 SF

|            |                                                                                                                                                                                        |  |  |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 08/08/2018 | Mastic/Adhesive for 12"x12" Off White, Beige, Grey, Blue, Light Brown and Black Vinyl Floor Tile (Original Entry Updated 8/16/22). This Material is in GOOD condition as of this date. |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 08/16/2022 | Material Re-Assessed. Stage has Black Vinyl Floor Tile. No other changes as of this date.                                                                                              |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                            |  |  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                            |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/26/2025 This Material is unchanged as of this date.

|           |     |               |        |
|-----------|-----|---------------|--------|
| 18-127AAA | NEW | NONE DETECTED | ( ND ) |
|-----------|-----|---------------|--------|

### MAIN BUILDING

CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER

11,000 SF

09/01/2010 Vinyl Wall Cover. This Material is in GOOD condition as of this date.

03/28/2017 Damage Observed. <5% Physical Damage - in the form of 2 LF Separation at seam outside of Classroom 15. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

08/28/2017 Additional Damage Observed. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in Vinyl. No other changes as of this date.

08/30/2017 Sample Collected 17-183-3C-19, Mezzanine, 208 Reception Wall, Vinyl Wall Covered Only.

04/19/2019 Construction Note: Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 Additional Damage Observed. 1 SF of Torn Vinyl on Upper Wall of Classroom 18. No other changes as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |         |               |        |
|--------------|---------|---------------|--------|
| 10-174AAA    | ASSUMED | NO SAMPLE     | ( NS ) |
| 10-019 CW05  | ND      | NONE DETECTED | ( ND ) |
| 15-100-00-10 | ND      | NONE DETECTED | ( ND ) |

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO.   | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|--------------|------------------|---------------|---------------|
| 17-183 3C-19 | ND               | NONE DETECTED | ( ND )        |

### MAIN BUILDING

CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER MASTIC

11,000 SF

|            |                                                                                                                                                                                                                                    |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/01/2010 | Mastic/Adhesive for Vinyl Wall Cover. This Material is in GOOD condition as of this date.                                                                                                                                          |
| 03/28/2017 | Damage Observed. <5% Physical Damage - in the form of 2 LF Separation at seam outside of Classroom 15. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date. |
| 08/28/2017 | Additional Damage Observed. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in Vinyl. No other changes as of this date.                                                                                             |
| 08/30/2017 | Sample Collected, 17-183-3C-20, Mezzanine, 205 Nurses Wall, Vinyl Wall Covered Adhesive only.                                                                                                                                      |
| 04/19/2019 | Construction Note: Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.          |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 02/09/2021 | Additional Damage Observed. 1 SF of Torn Vinyl on Upper Wall of Classroom 18. No other changes as of this date.                                                                                                                    |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                        |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                        |

|              |         |               |        |
|--------------|---------|---------------|--------|
| 10-174AAA    | ASSUMED | NO SAMPLE     | ( NS ) |
| 10-019 CW06  | ND      | NONE DETECTED | ( ND ) |
| 10-019 CW06  | <1      | CHRYSTILE     | ( CH ) |
| 17-183 3C-20 | ND      | NONE DETECTED | ( ND ) |

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

ENTIRE 1ST LEVEL

BASEBOARD MASTIC

3,850 SF

|            |                                                                                                                                          |
|------------|------------------------------------------------------------------------------------------------------------------------------------------|
| 08/08/2018 | Mastic/Adhesive for 4" and 6" Brown Baseboard, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date. |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                              |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                              |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                              |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                              |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                              |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                              |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                              |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                              |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                              |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                              |
| 02/26/2025 | Material Re-assessed. 4" Dark Brown Baseboard is found on 1st level expt in Kitchen. 4" and 6" Brown Baseboard Observed in Kitchen.      |

|           |     |               |        |
|-----------|-----|---------------|--------|
| 18-127AAA | NEW | NONE DETECTED | ( ND ) |
|-----------|-----|---------------|--------|

### MAIN BUILDING

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

67,000 SF

|            |                                                                                                                                                                                                                                                     |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.                                                                                                                                                     |
| 03/08/2007 | Material Re-Assessed. Damage Observed. <5% Physical Damage - in the form of approximately 10-15 SF of Joint/Tape seam separation in Center Work Rooms of Classrooms 7-9. Friability changed from Low to Moderate. No other changes as of this date. |
| 02/02/2010 | Samples 10-019 CW-03, CW-13 and CW-19 (Joint Tape), CW-03, CW-13 and CW-19 (Joint Compound), and CW-04, CW-14 and CW-20 (Drywall) collected on this date.                                                                                           |
| 09/01/2010 | Additional Damage observed. 10 SF Damaged at patched area in Room 5. No other changes as of this date.                                                                                                                                              |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                                                                   | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 12/02/2011 | Additional Damage - in the form of Teachers Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.                                                                                                                             |               |               |
| 10/12/2012 | Material condition Re-Assessed. Due to Water Leak, new Material installed in Hallway, Located between Boys' Restroom and ESL Room, and approximately 144 SF of Ceiling Material Removed and Replaced. No other changes as of this date.                                            |               |               |
| 08/29/2014 | Teacher's Work Room by Classroom 3-5 has <10% Water Damage - in the form of 5 SF of Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 by the Light Wall Board System is Damaged. No other changes as of this date.                                        |               |               |
| 03/16/2015 | Additional Damage observed. 2 SF hole on Ceiling of 1st Floor Storage Room by Elevator. No other changes as of this date.                                                                                                                                                          |               |               |
| 09/12/2016 | Additional Damage observed and Partial Repairs observed. Closet by Office has 2 LF of Physical Damage on the wall due to torn Skimcoat. Damages noted on 08/29/14 have been Repaired. No other changes as of this date.                                                            |               |               |
| 08/28/2017 | Additional Damage Observed. 1 SF of Physical Damage in the form of a Hole in the Hallway near the Girls Restroom. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in the Wall. No other changes as of this date.                                                    |               |               |
| 08/30/2017 | Sample Collected 17-183-3C-11, Mezzanine, 202 Conference, Wall Joint Tape and Mud (for Gypsum Wallboard). Sample Collected 17-183-3C-11, Mezzanine, 202 Conference, Wall Gypsum Board. Sample Collected 17-183-3C-36, Main Building, Multi-Purpose Room 144, Ceiling Gypsum Board. |               |               |
| 04/19/2019 | Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.                                                                             |               |               |
| 01/31/2020 | Additional Damage Observed. 2 SF of Water Damage and are Cracks in Classroom 15. No other changes as of this date.                                                                                                                                                                 |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |
| 02/17/2022 | Additional Damage Observed. 8 SF of Water Stain in Classroom 15 Work Room. No other changes as of this date.                                                                                                                                                                       |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |
| 02/14/2023 | Additional Damage Observed. 1 SF of Missing Drywall in Book Room. 1 SF of Scuffs and Missing Skim Coat with Drywall Board Exposed in Storage Closet next to LSH Room in Multi-Purpose Room. No other changes as of this date.                                                      |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |               |               |

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |    |               |        |
|--------------|----|---------------|--------|
| 10-019CW-03  | ND | NONE DETECTED | ( ND ) |
| 10-019CW-03  | <1 | CHRYSTILE     | ( CH ) |
| 10-019CW-04  | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-13 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-13 | <1 | CHRYSTILE     | ( CH ) |
| 10-019 CW-14 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-19 | <1 | NONE DETECTED | ( ND ) |
| 10-019 CW-19 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-20 | ND | NONE DETECTED | ( ND ) |
| 17-183 3C-12 | ND | CHRYSTILE     | ( CH ) |
| 17-183 3C-11 | 2  | NONE DETECTED | ( ND ) |
| 17-183-3C-36 | ND | NONE DETECTED | ( ND ) |

### MAIN BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

62,760 SF

08/23/2006 Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.

03/08/2007 Material Re-Assessed. Damage: <5% Physical Damage - in the form of approximately 10-15 SF of Joint/Tape seam separation in Center Work Rooms of Classrooms 7-9. Friability changed from Low to Moderate. No other changes as of this date.

02/02/2010 Samples 10-019 CW-12 and CW-18 collected on this date.

09/01/2010 Additional Damage observed. 10 SF Damaged at patched area in Room 5. No other changes as of this date.

12/02/2011 Additional Damage - in the form of Teachers Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.

10/12/2012 Material condition Re-Assessed. Due to Water Leak, new Material installed in Hallway, Located between Boys' Restroom and ESL Room, and approximately 144 SF of Ceiling Material Removed and Replaced. No other changes as of this date.

08/29/2014 Teacher's Work Room by Classroom 3-5 has <10% Water Damage - in the form of 5 SF of Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 by the Light Wall Board System is Damaged. No other changes as of this date.

03/16/2015 Quantity changed from 67,000 SF to 62,760 SF. No other changes as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                | ASBESTOS NAME | ASBESTOS CODE |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 09/12/2016 | Additional Damage observed and Partial Repairs observed. Closet by Office has 2 LF of Physical Damage on the wall due to torn Skimcoat. Damages noted on 08/29/14 have been Repaired. No other changes as of this date.         |               |               |
| 08/28/2017 | Additional Damage Observed. 1 SF of Physical Damage in the form of a Hole in the Hallway near the Girls Restroom. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in the Wall. No other changes as of this date. |               |               |
| 08/30/2017 | Sample Collected 17-183-3C-10, Mezzanine, 202 Conference, Wall Skimcoat and Paint (for Gypsum Wallboard). Sample Collected 17-183-3C-35, Main Building, Multi-Purpose Room 144, Ceiling Joint Tape and Mud (For Gypsum Board).  |               |               |
| 04/19/2019 | Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.                          |               |               |
| 01/31/2020 | Additional Damage Observed. 2 SF of Water Damage and are Cracks in Classroom 15. No other changes as of this date.                                                                                                              |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 02/17/2022 | Additional Damage Observed. 8 SF of Water Stain in Classroom 15 Work Room. No other changes as of this date.                                                                                                                    |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 02/14/2023 | Additional Damage Observed. 1 SF of Missing Drywall in Book Room. 1 SF of Scuffs and Missing Skim Coat with Drywall Board Exposed in Storage Closet next to LSH Room in Multi-Purpose Room. No other changes as of this date.   |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                     |               |               |

|              |    |               |        |
|--------------|----|---------------|--------|
| 10-019 CW-12 | ND | NONE DETECTED | ( ND ) |
| 10-019 CW-18 | <1 | CHRYSTILE     | ( CH ) |
| 17-183 3C-10 | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-35 | 2  | CHRYSTILE     | ( CH ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

ENTIRE BUILDING

WINDOW SEALANT

88 LF

08/30/2017 Putty/Sealant on Interior side of Exterior Windows. Sample Collected 17-183 3C-13, Mezzanine, 202 Conference, North Side Interior Window Gray Sealant. Sample Collected 17-183-3C-15, Mezzanine, 205 Nurses, South Side Interior Window Gray Sealant. Sample Collected 17-183-3C-53, Main Building, Classroom 5 (130), Interior Window Black Sealant. Sample Collected 17-183-3C-58, Main Building, Classroom 8 (124), Interior Window Black Sealant. Sample Collected 17-183-3C-63, Main Building, Classroom 1 (117), Interior Window Black and Gray Sealant. Sample Collected 17-183-3C-70, Main Building, Classroom 14 (112), Interior Window Black and Gray Sealant. Sample Collected 17-183-3C-75, Main Building, Kindergarten 16 (102), Interior Window Gray Sealant.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |    |               |        |
|--------------|----|---------------|--------|
| 17-183 3C-13 | <1 | CHRYSTILE     | ( CH ) |
| 17-183 3C-15 | 8  | CHRYSTILE     | ( CH ) |
| 17-183-3C-53 | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-58 | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-63 | 4  | CHRYSTILE     | ( CH ) |
| 17-183-3C-70 | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-75 | 8  | CHRYSTILE     | ( CH ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

ENTIRE BUILDING IN DESIGNATED AREAS

SPRAY ON CEILING

3,840 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | Spray-On Ceiling. This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |  |  |
| 11/08/2007 | Material is Located in KITCHEN, PREP ROOMS (2), ENTRY AREAS (2), COMPUTER LAB, ENTRY COMMON AREA, ROOMS 15-16, PREP ROOMS, STAGE, LIBRARY, MPR ENTRY AREA, 2ND FLOOR ELEV. EQUIP. ROOM, CUSTODIAL ROOM, AND PRINCIPALS OFFICE. Entry Areas (2) added to Pod 07-09 and Pod 13-15. Material Quantity changed from 3,790 SF to 4,390 SF. Material Re-Assessed. Damage: <5% Physical Damage - in the form of approximately 4 SF of separation; Water Damage - 25 SF noticed in Pod 07-09. Friability changed from Low to Moderate. No other changes as of this date. |  |  |
| 05/15/2009 | Additional Damage observed. A 4" cut observed in the Storage Room next to the Elevator Equipment Room and Water Damage observed in Pod 1-5. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| 02/02/2010 | Samples 10-019 CW-01 and CW-11 collected on this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |  |  |
| 09/01/2010 | This Material is also visible above the Ceiling Tiles in Classroom 5. This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  |
| 12/02/2011 | Additional Damage - in the form of Teacher's Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                          |  |  |
| 10/12/2012 | Material condition Re-Assessed. Approximately 150 SF of Material has been Removed, due to Water Leak, in Hallway, located between Boys Restroom and ESL Room. New Drywall has been installed. Quantity changed from 4,390 SF to 4,240 SF. No other changes as of this date.                                                                                                                                                                                                                                                                                      |  |  |
| 09/27/2013 | Material Re-Assessed. Material changed from GOOD to FAIR condition. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                            |  |  |
| 08/29/2014 | Teacher's Work Room by Classrooms 3-5 has Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 has 2 SF of Damage. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                       |  |  |
| 03/16/2015 | Additional Damage observed. 2 SF hole on Ceiling of 1st Floor Storage Room by Elevator. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                        |  |  |
| 03/28/2017 | Material Re-assessed. Quantity changed from 4,240 SF to 3,840 SF based on Material Removed from Workroom between Classrooms 9 and 11. No other changes as fo this date                                                                                                                                                                                                                                                                                                                                                                                           |  |  |
| 08/28/2017 | Partial Repairs Observed. Water Damage by the Teacher's Work Room has been Repaired. Hole in the Ceiling of the Storage Room (Located in the First Floor) has been Repaired. Material remains in FAIR condition as of this date.                                                                                                                                                                                                                                                                                                                                 |  |  |
| 08/30/2017 | Sample Collected 17-183 3C-14, Mezzanine, 203 Principal, Ceiling Acoustic Texture.                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |  |  |
| 08/27/2020 | Additional Damage Observed. <10% Water Damage in the form of 6 SF of Water Stains in Work Room of Classroom 17. Material remains in FAIR condition overall. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                    |  |  |

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

33

***HazMat Doc***

AHERA Report B - Survey

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                | ASBESTOS NAME | ASBESTOS CODE |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 08/16/2022 | Additional Damage Observed. <5% Physical Damage in the form of 2 LF Crack and Loose Ceiling Texture in Work Room of Classroom 17. Material remains in FAIR condition overall. No other changes as of this date. |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                     |               |               |

|              |    |           |        |
|--------------|----|-----------|--------|
| 10-019CW-01  | <1 | CHRYSTILE | ( CH ) |
| 10-019 CW-11 | <1 | CHRYSTILE | ( CH ) |
| 17-183 3C-14 | 2  | CHRYSTILE | ( CH ) |

### MAIN BUILDING

#### ENTIRE FIRST LEVEL

#### BASEBOARD MASTIC

3,850 LF

|            |                                                                                                                                                                                                                                                                                                |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 08/23/2006 | Mastic/Adhesive for 4" and 6" Brown Baseboards (Apparent New Material identified by the AHERA Accredited Inspector). Mastic is Beige. This Material is in GOOD condition as of this date (Original entry updated on 05/15/09).                                                                 |  |  |
| 05/15/2009 | Baseboards are Brown. Original entry updated. No other changes as of this date.                                                                                                                                                                                                                |  |  |
| 10/12/2012 | Damage Observed. <5% Physical Damage and <10% Water Damage - due to Water Leak on Second Floor, First Floor Damage in Hallway, located between Boys Restroom and ESL Room. Mastic/Adhesive is exposed. Material condition changed from GOOD to FAIR overall. No other changes as of this date. |  |  |
| 09/17/2015 | Additional Damage observed and New Material installed. Classroom 1 has 3 LF of Baseboard missing. Classroom 1 has 6" Black Baseboard Installed, (Old Material may be behind New Material). No other changes as of this date.                                                                   |  |  |
| 03/17/2016 | Partial Repairs made and Additional Damage observed. Damage in Hallway has been Repaired. Additional Damage observed in the form of 3 LF of Baseboard missing in Cafeteria exposing Mastic/Adhesive. No other changes as of this date.                                                         |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/28/2017 Additional Damages and Partial Repairs Observed. 3 LF of Baseboard Missing in the Cafeteria have been Repaired. Classroom 13 has 1 SF of Physical Damage in the form of Broken Baseboard. Multi-Purpose Room has 1 SF of Physical Damage in the form of Broken Baseboard. Material remains in FAIR condition as of this date.

08/30/2017 Sample Collected 17-183-3C-25, Main Building, Reception 154, 4" Baseboard Beige Mastic. Sample Collected 17-183-3C-37, Main Building, Multi-Purpose Room 144, 6" Baseboard Beige Mastic. Sample Collected 17-183-3C-54, Main Building, Classroom 5 (130), 6" Baseboard Beige Mastic. Sample Collected 17-183-3C-59, Main Building, Classroom 8 (124), 6" Baseboard Off-White Mastic. Sample Collected 17-183-3C-64, Main Building, Classroom 1 (117), 6" Baseboard Beige Mastic Only. Sample Collected 17-183-3C-71, Main Building, Classroom 14 (112), 6" Baseboard Beige Mastic Only. Sample Collected 17-183-3C-76-Beige Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard Beige and Brown Mastic Only. Sample Collected 17-183-3C-76-Brown Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard Beige and Brown Mastic Only.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|                           |    |               |        |
|---------------------------|----|---------------|--------|
| 17-183 3C-25              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-37              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-54              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-59              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-64              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-71              | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-76-Beige Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-76-Brown Mastic | ND | NONE DETECTED | ( ND ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

#### ENTRY AREAS (2)

##### SMOOTH WALL SURFACING

660 SF

09/07/2005 Skim Coat/ Texture on Concrete. This Material is in GOOD condition as of this date.

08/29/2014 This Material is unchanged as of this date..

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

#### EXTERIOR WALLS AND OVERHANG

##### ROUGH WALL

15,000 SF

09/07/2005 Stucco Walls and Overhang. This Material is in GOOD condition as of this date.

08/13/2019 Damages Observed. <5% Physical Damage in the form of 1 SF of Holes on the Overhang by Entry to Classroom 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                                                           | ASBESTOS NAME | ASBESTOS CODE |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 SF of Missing Stucco and Paint on South Wall next to Girls Restroom Entry. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |               |               |

### MAIN BUILDING

#### EXTERIOR WALLS AND OVERHANG

##### ROUGH WALL SURFACING

15,000 SF

|            |                                                                                                                                                                                                                                                                            |  |  |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | Skim Coat for Stucco Walls and Overhang. This Material is in GOOD condition as of this date.                                                                                                                                                                               |  |  |
| 08/13/2019 | Damages Observed. <5% Physical Damage in the form of 1 SF of Holes on the Overhang by Entry to Classroom 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                        |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 SF of Missing Stucco and Paint on South Wall next to Girls Restroom Entry. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN

VINYL SHEETING

384 SF

08/23/2006 **12"x12" White, Grey, Blue and Begie Vinyl Floor Tile (2/13/2024 Updated Entry Beige Vinyl Sheeting) (Apparent New Material identified by the AHERA Accredited Inspector). This Material is in GOOD condition as of this date.**

10/17/2008 Location Description changed from KITCHEN, AND CAFETERIA to KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN. Material Quantity changed from 1,400 SF to 1,600 SF to reflect this fact. No other changes as of this date.

10/12/2012 Damage: <10% Water Damage - in the form of approximately 144 SF of Material Removed in Hallway, located between Boys' Restroom and ESL Room. Damage due to Water Leak. Quantity changed from 1,600 SF to 1,456 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

04/05/2013 Material Condition Re-Assessed. Damages Repaired as of this date. Material Condition changed from FAIR to GOOD. Friability changed from Low to Non. No other changes as of this date.

09/17/2015 Damage observed. Cafeteria has <5% Physical Damage- in the form of 2 LF Damage. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.

08/30/2017 Sample Collected 17-183-3C-38, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting. Sample Collected 17-183-3C-46, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting.

08/08/2018 Material Re-assessed. Quantity changed from 1,456 SF to 384 SF of old Vinyl Floor Tiles Remaining in Kitchen. Location discription changed from KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN to KITCHEN. No other changes as of this date.

01/31/2020 Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.

02/07/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO.   | ASBESTOS CONTENT                                                                                                                                                                         | ASBESTOS NAME | ASBESTOS CODE |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 08/16/2022   | This Material is unchanged as of this date.                                                                                                                                              |               |               |
| 02/14/2023   | This Material is unchanged as of this date.                                                                                                                                              |               |               |
| 08/15/2023   | This Material is unchanged as of this date.                                                                                                                                              |               |               |
| 02/13/2024   | Material Re-assessed. Material Replaced now 12"x12" White, Grey, Blue and Beige Vinyl Floor Tile. Mastic/Adhesive may still Exist Underneath material. No other changes as of this date. |               |               |
| 08/13/2024   | This Material is unchanged as of this date.                                                                                                                                              |               |               |
| 02/26/2025   | This Material is unchanged as of this date.                                                                                                                                              |               |               |
| 17-183-3C-38 | ND                                                                                                                                                                                       | NONE DETECTED | ( ND )        |
| 17-183-3C-46 | ND                                                                                                                                                                                       | NONE DETECTED | ( ND )        |

### MAIN BUILDING

KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

384 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 08/23/2006 | <b>Mastic/Adhesive for 12"x12" White, Grey, Blue and Beige. (2/13/2024 Updated Entry Vinyl Floor Tile Backing Paper/adhesive for Beige Vinyl Sheeting) (Apparent New Material identified by the AHERA Accredited Inspector). This Material is in GOOD condition as of this date.</b>                                                                                                                                                                                                                                                                                                                 |  |  |
| 10/17/2008 | Location Description changed from KITCHEN, AND CAFETERIA to KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN. Material Quantity changed from 1,400 SF to 1,600 SF to reflect this fact. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |  |  |
| 10/12/2012 | Damage: <10% Water Damage - in the form of approximately 144 SF of Material Removed in Hallway, located between Boys' Restroom and ESL Room. Damage due to Water Leak. Quantity changed from 1,600 SF to 1,456 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.                                                                                                                                                                                                                                           |  |  |
| 04/05/2013 | Material Condition Re-Assessed. Damages Repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| 09/17/2015 | Damage observed. Cafeteria has <5% Physical Damage- in the form of 2 LF Damage. Material condition changed from GOOD to FAIR overall. Friability changed from Moderate to High. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                    |  |  |
| 08/30/2017 | Sample Collected 17-183-3C-39, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting Backing Paper. Sample Collected 17-183-3C-40, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting Adhesive. Sample Collected 17-183-3C-41, Main Building, Multi-Purpose Room 144, Floor Under Vinyl, White Compound. Sample Collected 17-183-3C-47-Paper Backing, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive. Sample Collected 17-183-3C-47-Adhesive, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive. |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                           | ASBESTOS NAME | ASBESTOS CODE |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 08/08/2018 | Material Re-assessed. Quantity changed from 1,456 SF to 384 SF of old Vinyl Floor Tiles Remaining in Kitchen. Location discription changed from KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN to KITCHEN. No other changes as of this date. |               |               |
| 01/31/2020 | Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                        |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 02/13/2024 | Material Re-assessed. Material Replaced now 12"x12" White, Grey, Blue and Begie Vinyl Floor Tile. Mastic/Adheisve may still Exist Underneath material. No other changes as of this date.                                                   |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                |               |               |

|                            |    |               |        |
|----------------------------|----|---------------|--------|
| 17-183-3C-39               | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-40               | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-41               | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-47-Paper Backing | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-47-Adhesive      | ND | NONE DETECTED | ( ND ) |

### MAIN BUILDING

#### MULTI-PURPOSE ROOM

#### CEILING MASTIC

5,360 SF

|            |                                                                                                                  |
|------------|------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive for 4'X8' Glued-On Ceiling Panels. This Material is in GOOD condition as of this date.           |
| 10/17/2008 | Material Quantity Re-Assessed. Quantity changed from 1,200 SF to 5,360 SF. No other changes as of this date.     |
| 08/30/2017 | Sample Collected 17-183-3C-34, Main Building, Multi-Purpose Room 144, 4'X10' Tectum Ceiling Panel, Black Mastic. |
| 01/31/2020 | This Material is unchanged as of this date.                                                                      |

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|              |   |           |        |
|--------------|---|-----------|--------|
| 17-183-3C-34 | 5 | CHRYSTILE | ( CH ) |
|--------------|---|-----------|--------|

### MAIN BUILDING

MULTI-PURPOSE ROOM

CEILING PANEL

5,360 SF

09/07/2005 4'X8' Glued-On Ceiling Panels. This Material is in GOOD condition as of this date.

04/16/2008 Tiles have a Fibrous Hard Surface. No other changes as of this date.

10/17/2008 Material Quantity Re-Assessed. Quantity changed from 1,200 SF to 5,360 SF. No other changes as of this date.

08/30/2017 Sample Collected 17-183-3C-33, Main Building, Multi-Purpose Room 144, 4'X10' Tectum Ceiling Panel.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

17-183-3C-33 ND NONE DETECTED ( ND )

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

GLUED TILES

600 SF

10/17/2008 4'x8' Glued-on Wall Tile. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

08-241AAA ASSUMED NO SAMPLE ( NS )

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE

1,020 SF

10/17/2008 1'x1' Glued-on Wall Tile. This Material is in GOOD condition as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT                                                           | ASBESTOS NAME | ASBESTOS CODE |
|------------|----------------------------------------------------------------------------|---------------|---------------|
| 03/04/2014 | Friability changed from Non to Moderate. No other changes as of this date. |               |               |
| 01/31/2020 | This Material is unchanged as of this date.                                |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                |               |               |
| 08-241AAA  | ASSUMED                                                                    | NO SAMPLE     | ( NS )        |

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE MASTIC

1,020 SF

|            |                                                                                                   |
|------------|---------------------------------------------------------------------------------------------------|
| 10/17/2008 | Mastic/Adhesive for 1'x1' Glued-on Wall Tile. This Material is in GOOD condition as of this date. |
| 01/31/2020 | This Material is unchanged as of this date.                                                       |
| 08/27/2020 | This Material is unchanged as of this date.                                                       |
| 02/09/2021 | This Material is unchanged as of this date.                                                       |
| 08/10/2021 | This Material is unchanged as of this date.                                                       |
| 02/17/2022 | This Material is unchanged as of this date.                                                       |
| 08/16/2022 | This Material is unchanged as of this date.                                                       |
| 02/14/2023 | This Material is unchanged as of this date.                                                       |
| 08/15/2023 | This Material is unchanged as of this date.                                                       |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 08-241AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE MASTIC

600 SF

10/17/2008 Mastic/Adhesive for 4'x8' Glued-on Wall Tile. This Material is in GOOD condition as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 08-241AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

OFFICES, WORKROOM, HALLWAY

SUSPENDED CEILING TILE

3,500 SF

09/01/2010 '2'x2' and 2'X4' Suspended Ceiling Tiles. This Material is in GOOD condition as of this date. (Original entry updated 09/17/15.)

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                                   | ASBESTOS NAME | ASBESTOS CODE |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 09/17/2015 | Material Description Re-Assessed. Material comes in 2'x4' and 2'x2' sizes. Material Description changed from '2'X4' Suspended Ceiling Tile' to '2'x2' and 2'X4' Suspended Ceiling Tiles'. Original entry updated. No other change as of this date. |               |               |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                        |               |               |

|             |         |               |        |
|-------------|---------|---------------|--------|
| 10-174AAA   | ASSUMED | NO SAMPLE     | ( NS ) |
| 10-019 CW17 | ND      | NONE DETECTED | ( ND ) |

### MAIN BUILDING

STAFF MENS RESTROOM, 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, WOMENS RESTROOM, PRINCIPALS OFFICE, AND STORAGE ROOMS

BASEBOARD MASTIC

730 LF

|            |                                                                                                                                                                                                                                                                                    |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 09/07/2005 | Mastic/Adhesive for 4" Brown Baseboard. This Material is in GOOD condition as of this date.                                                                                                                                                                                        |  |  |
| 10/12/2012 | Damage Observed. <10% Physical Damage - in the form of approximately 44 LF of Material is missing due to Removal of Vinyl Sheeting on 2nd Floor. Mastic/Adhesive is exposed. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. |  |  |
| 08/30/2017 | Sample Collected 17-183-3C-21, Mezzanine, 205 Nurses Wall, 4" Baseboard Brown Mastic.                                                                                                                                                                                              |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |  |  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO.   | ASBESTOS CONTENT                            | ASBESTOS NAME | ASBESTOS CODE |
|--------------|---------------------------------------------|---------------|---------------|
| 08/10/2021   | This Material is unchanged as of this date. |               |               |
| 02/17/2022   | This Material is unchanged as of this date. |               |               |
| 08/16/2022   | This Material is unchanged as of this date. |               |               |
| 02/14/2023   | This Material is unchanged as of this date. |               |               |
| 08/15/2023   | This Material is unchanged as of this date. |               |               |
| 02/13/2024   | This Material is unchanged as of this date. |               |               |
| 08/13/2024   | This Material is unchanged as of this date. |               |               |
| 02/26/2025   | This Material is unchanged as of this date. |               |               |
| 17-183 3C-21 | ND                                          | NONE DETECTED | ( ND )        |

### MAIN BUILDING

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING

385 SF

|            |                                                                                                                                                                                                                                              |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 04/05/2013 | Beige and White Vinyl Floor Sheeting. This Material is in GOOD condition as of this date (Original Entry updated on 03/04/14).                                                                                                               |
| 03/04/2014 | Vinyl Sheeting is Beige and White. Original entry updated. No other changes as of this date.                                                                                                                                                 |
| 03/28/2017 | Damage Observed. <10% Water Damage - in the form of 2 SF Water Stains in 2nd Floor Teacher's Lounge. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |
| 08/30/2017 | Sample Collected 17-183 3C-08, Mezzanine, 201 Computer Area, Floor Covering, Off-White Vinyl Sheeting.                                                                                                                                       |
| 01/31/2020 | Material Re-assessed. 215 SF of Vinyl Floor Tile has been Removed. Quantity changed from 600 SF to 385 SF. No other changes as of this date.                                                                                                 |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                  |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO.   | ASBESTOS CONTENT                                                                                                                                        | ASBESTOS NAME | ASBESTOS CODE |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 08/15/2023   | This Material is unchanged as of this date.                                                                                                             |               |               |
| 02/13/2024   | This Material is unchanged as of this date.                                                                                                             |               |               |
| 08/13/2024   | This Material is unchanged as of this date.                                                                                                             |               |               |
| 02/26/2025   | Material Re-assessed. Material Only Observed in Storage Room. Material may Exist under new Floor Tile in Other Areas. No other changes as of this date. |               |               |
| 13-038AAA    | ASSUMED                                                                                                                                                 | NO SAMPLE     | ( NS )        |
| 17-183 3C-08 | ND                                                                                                                                                      | NONE DETECTED | ( ND )        |

### MAIN BUILDING

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING BACKING PAPER/MASTIC

385 SF

|            |                                                                                                                                                                                                                                                        |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 04/05/2013 | Backing Paper/Adhesive for Beige and White Vinyl Floor Sheeting. This Material is in GOOD condition as of this date. (Original Entry updated on 03/04/14.)                                                                                             |
| 03/04/2014 | Vinyl Sheeting is Beige and White. Friability changed from Non-Friable to Friable. Original entry updated. No other changes as of this date.                                                                                                           |
| 03/28/2017 | Damage Observed. <10% Water Damage - in the form of 2 SF Water Stains in 2nd Floor Teacher's Lounge. Material condition changed from GOOD to FAIR overall. Friability changed from Moderate to High. No other changes as of this date.                 |
| 08/30/2017 | Sample Collected 17-183-09-Paper Backing, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Backing Paper Mastic. Sample Collected 17-183-09-Mastic, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Mastic. |
| 01/31/2020 | Material Re-assessed. 215 SF of Vinyl Floor Tile has been Removed. Quantity changed from 600 SF to 385 SF. No other changes as of this date.                                                                                                           |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                            |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                            |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/13/2024 This Material is unchanged as of this date.

02/26/2025 Material Re-assessed. Material Only Observed in Storage Room. Material may Exist under new Floor Tile in Other Areas. No other changes as of this date.

|              |         |               |        |
|--------------|---------|---------------|--------|
| 13-038AAA    | ASSUMED | NO SAMPLE     | ( NS ) |
| 17-183 3C-09 | ND      | NONE DETECTED | ( ND ) |

### MAIN BUILDING

STORAGE ROOM NEXT TO RESTROOM, MULTI-PURPOSE ROOM, ELEVATOR EQUIPMENT ROOM, PRINCIPALS OFFICE, AND NURSES ROOM

FIRE DOOR CORE INSULATION

252 SF

09/07/2005 Fire Door Core Insulation (12 EA FIRE DOORS). This Material is in GOOD condition as of this date.

02/05/2019 Material Re-assessed. 2nd Floor Elevator Mechanical Room Door Nob is Missing, White Core Insulation is Exposed. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

#### STORAGE ROOMS

##### VINYL FLOOR TILE

275 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |  |  |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 08/23/2006 | 12"X12" Multi-Colored (Beige, Peach Orange, Green and Light Gray) Vinyl Floor Tile (Apparent New Material identified by the AHERA Accredited Inspector). Mastic in Black. This Material is in good condition as of this date (Original Entry Update 8/30/17).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 12/02/2011 | Damage Observed. <5% Physical Damage - in the form of Music Storage Room has 8 Tiles broken and Mastic is exposed. Material condition changed from GOOD to FAIR. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |  |  |
| 10/12/2012 | Additional Damage: <10% Water Damage - in the form of Water Leak observed on 2nd Floor, and Vinyl Floor Tile removed in ESL Room. Mastic/Adhesive is exposed. Material is present under electrical switchboard. Quantity changed from 4,600 SF to 4,475 SF. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  |
| 09/27/2013 | Friability changed from Moderate to Low. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |  |  |
| 08/29/2014 | Material Re-Assessed. Storage Room next to Office has 1 Vinyl Floor Tile Missing and 1 is Loose. Black Mastic/Adhesive is exposed. Classroom 13 has 2 Vinyl Floor Tile Damage. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |  |  |
| 08/28/2017 | Additional Damage Observed. Staff Lounge now has 2 Broken Tiles. Mastic/Adhesive is Exposed. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |  |  |
| 08/30/2017 | Material Description changed from '12"X12" Cream Vinyl Floor Tile' to '12"X12" Multi-Colored (Beige, Green and Light Gray) Vinyl Floor Tile'. No other changes as of this date. Sample Collected 17-183-3C-27-Floor Tile, Main Building, Teacher Work Area 157, 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-28-Floor Tile, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile. Sample Collected 17-183-3C-29, Main Building, Teacher Work Area 157, 12" Multi-Color Vinyl Floor Tile. Sample Collected 17-183-3C-30-Floor Tile, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile. Sample Collected 17-183-3C-31-Floor Tile, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile. Sample Collected 17-183-3C-32-Floor Tile, Main Building, Teacher Work Area 157, 12" Gold Vinyl Floor Tile. Sample Collected 17-183-3C-44, Main Building, Storage 147, 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-50, Main Building, Classroom 1 (135), Beige Vinyl Floor Tile. Sample Collected 17-183-3C-56, Main Building, Classroom 5 (130), 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-61, Main Building, Classroom 8 (124), 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-66, Main Building, Work Room (119), 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-73, Main Building, Classroom 14 (112), 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-77-Floor Tile, Main Building, Kindergarten 16 (102), 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-78-Floor Tile, Main Building, Kindergarten 16 (102), 12" Light Gray Vinyl Floor Tile. Sample Collected 17-183-3C-79-Floor Tile, Main Building, Kindergarten 16 (102), 12" Light Green Vinyl Floor Tile. Sample Collected 17-183-3C-80-Floor Tile, Main Building, Kindergarten 16 (103), 12" Peach Orange Vinyl Floor Tile. Sample Collected 17-183-3C-83-Floor Tile, Main Building, Kindergarten 18 (103), 12" Gold Vinyl Floor Tile. |  |  |
| 08/08/2018 | Material Re-assessed. Only the Storage Rooms now have old Multi-Colored Vinyl Floor Tiles. Every other Location has been Replaced. Quantity changed from 4,475 SF to 275 SF. Location changed from ALL CLASSROOMS, SINK AND ENTRY AREAS, STORAGE ROOMS, PREP ROOMS, HALLWAYS, AND NEW ADMINISTRATION OFFICES to STORAGE ROOMS.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |  |  |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |  |  |

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

08/27/2020 Additional Damage Observed. <10% Water Damage in the form of 3 Tiles with Water Stains in Custodian Room (Storage Room # 149). Material remains in FAIR condition overall. No other changes as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

|                         |    |               |        |
|-------------------------|----|---------------|--------|
| 17-183-3C-27-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-28-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-29            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-30-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-31-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-32-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-44            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-50            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-56            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-61            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-66            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-73            | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-77-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-78-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-79-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-80-Floor Tile | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-83-Floor Tile | ND | NONE DETECTED | ( ND ) |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

#### STORAGE ROOMS

#### VINYL FLOOR TILE MASTIC

275 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/23/2006 | Mastic/Adhesive for 12"X12" Multi-Colored (Beige, Peach Orange, Green and Light Gray) Vinyl Floor Tile (Apparent New Material identified by the AHERA Accredited Inspector). Mastic is Black. This Material is in good condition as of this date (Original Entry Updated on 8/30/2017).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 03/08/2007 | This Material unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 12/02/2011 | Damage: <5% Physical Damage - in the form of Music Storage Room has 8 Tiles broken and Mastic is exposed. Material condition changed from GOOD to FAIR. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 10/12/2012 | Additional Damage: <10% Water Damage - in the form of Water Leak observed on 2nd Floor, and Vinyl Floor Tile removed in ESL Room. Mastic/Adhesive is exposed. Material is present under electrical switchboard. Quantity changed from 4,600 SF to 4,475 SF. Friability changed from Low to Moderate. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 09/27/2013 | Friability changed from Moderate to Low. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 08/29/2014 | Material Re-Assessed. Storage Room next to Office has 1 Vinyl Floor Tile Missing and 1 is Loose. Black Mastic/Adhesive is exposed. Classroom 13 has 2 Vinyl Floor Tile Damage. No other changes as of this date..                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 08/28/2017 | Additional Damage Observed. Staff Lounge now has 2 Broken Tiles. Mastic/Adhesive is Exposed. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| 08/30/2017 | Material Description changed from 'Mastic/Adhesive for 12"X12" Cream Vinyl Floor Tile' to 'Mastic/Adhesive for 12"X12" Multi-Colored (Beige, Green and Light Gray) Vinyl Floor Tile'. Sample Collected 17-183-3C-27-Mastic, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile Mastic. Sample Collected 17-183-3C-30-Mastic, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile Mastic. Sample Collected 17-183-3C-31-Mastic, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile Mastic. Sample Collected 17-183-3C-32-Mastic, Main Building, Teacher Work Area 157, 12" Gold Vinyl Floor Tile. Sample Collected 17-183-3C-45, Main Building, Storage 147, 12" Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-51, Main Building, Classroom 1 (135), Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-57, Main Building, Classroom 5 (130), 12" Beige Vinyl Floor Tile Black Mastic. Sample Collected 17-183-3C-62, Main Building, Classroom 8 (124), 12" Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-67, Main Building, Work Room (119), 12" Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-74, Main Building, Classroom 14 (112), 12" Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-77-Mastic, Main Building, Kindergarten 16 (102), 12" Beige Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-78-Mastic Main Building, Kindergarten 16 (102), 12" Light Gray Vinyl Floor Tile. Sample Collected 17-183-3C-79-Mastic, Main Building, Kindergarten 16 (102), 12" Light Green Vinyl Floor Tile. Sample Collected 17-183-3C-80-Mastic, Main Building, Kindergarten 16 (102), 12" Peach Orange Vinyl Floor Tile. Sample Collected 17-183-3C-81, Main Building, Kindergarten 16 (102), 12" Multi-Color Vinyl Floor Tile, Black Mastic. Sample Collected 17-183-3C-83-Mastic, Main Building, Kindergarten 18 (103), 12" Gold Vinyl Floor Tile. |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

| SAMPLE NO. | ASBESTOS CONTENT                                                                                                                                                                                                                                                                                                               | ASBESTOS NAME | ASBESTOS CODE |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------|
| 08/08/2018 | Material Re-assessed. Only the Stroage Rooms now have old Multi-Colored Vinyl Floor Tiles. Every other Location has been Replaced. Quantity changed from 4,475 SF to 275 SF. Location changed from ALL CLASSROOMS, SINK AND ENTRY AREAS, STORAGE ROOMS, PREP ROOMS, HALLWAYS, AND NEW ADMINISTRATION OFFICES to STORAGE ROOMS. |               |               |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 08/27/2020 | Additional Damage Observed. <10% Water Damage in the form of 3 Tiles with Water Stains in Custodian Room (Storage Room # 149). Material remains in FAIR condition overall. No other changes as of this date.                                                                                                                   |               |               |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                    |               |               |

|                     |    |               |        |
|---------------------|----|---------------|--------|
| 17-183-3C-27-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-28-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-30-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-31-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-32-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-45        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-51        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-57        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-62        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-67        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-74        | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-77-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-79-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-78-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-80-Mastic | ND | NONE DETECTED | ( ND ) |
| 17-183-3C-81        | ND | NONE DETECTED | ( ND ) |

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
| 12-185AAA  | ASSUMED          | NO SAMPLE     | ( NS )        |

### MAIN BUILDING

#### STUDENT RESTROOMS (2) (1ST FLOOR)

CEMENTITIOUS WALL PANEL

1,650 SF

|            |                                                                                                                                                                                                         |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 10/12/2012 | Cementitious Wall Panel. Damage Observed. <5% Physical Damage - in the form of 2 panels are broken in Boys Restroom, due to Removal of Vinyl Wall Panel. Material is in FAIR condition as of this date. |
| 04/05/2013 | Material condition Re-Assessed. Damaged section of Material may exist under 4'x8' Vinyl Wall Panel. This Material is unchanged as of this date.                                                         |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                             |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                             |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                             |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                             |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                             |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                             |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                             |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                             |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                             |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                             |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                             |

|           |         |           |        |
|-----------|---------|-----------|--------|
| 12-185AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

#### STUDENT RESTROOMS (2) (1ST FLOOR)

WALL MASTIC

1,650 SF

|            |                                                                                                                                                                                                                             |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 10/12/2012 | Mastic/Adhesive for Cementitious Wall Panel. Damage Observed. <5% Physical Damage - in the form of 2 panels are broken in Boys Restroom, due to Removal of Vinyl Wall Panel. Material is in FAIR condition as of this date. |
| 04/05/2013 | Material condition Re-Assessed. Damaged section of Material may exist under 4'x8' Vinyl Wall Panel. No other changes as of this date.                                                                                       |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                 |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

|            |                                             |
|------------|---------------------------------------------|
| 08/27/2020 | This Material is unchanged as of this date. |
| 02/09/2021 | This Material is unchanged as of this date. |
| 08/10/2021 | This Material is unchanged as of this date. |
| 02/17/2022 | This Material is unchanged as of this date. |
| 08/16/2022 | This Material is unchanged as of this date. |
| 02/14/2023 | This Material is unchanged as of this date. |
| 08/15/2023 | This Material is unchanged as of this date. |
| 02/13/2024 | This Material is unchanged as of this date. |
| 08/13/2024 | This Material is unchanged as of this date. |
| 02/26/2025 | This Material is unchanged as of this date. |

|           |         |           |        |
|-----------|---------|-----------|--------|
| 12-185AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

STUDENT RESTROOMS (2) (ON 1ST FLOOR)

MORTAR MISCELLANEOUS

450 SF

|            |                                                                                                       |
|------------|-------------------------------------------------------------------------------------------------------|
| 09/09/2009 | Grout/Mortar for 2"x2" Brown Ceramic Floor Tiles. This Material is in GOOD condition as of this date. |
| 01/31/2020 | This Material is unchanged as of this date.                                                           |
| 08/27/2020 | This Material is unchanged as of this date.                                                           |
| 02/09/2021 | This Material is unchanged as of this date.                                                           |
| 08/10/2021 | This Material is unchanged as of this date.                                                           |
| 02/17/2022 | This Material is unchanged as of this date.                                                           |
| 08/16/2022 | This Material is unchanged as of this date.                                                           |
| 02/14/2023 | This Material is unchanged as of this date.                                                           |
| 08/15/2023 | This Material is unchanged as of this date.                                                           |
| 02/13/2024 | This Material is unchanged as of this date.                                                           |
| 08/13/2024 | This Material is unchanged as of this date.                                                           |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

02/26/2025 This Material is unchanged as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 09-212AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

### MAIN BUILDING

STUDENT RESTROOMS (2) (ON 1ST FLOOR)

VINYL WALL COVER

1,650 SF

09/09/2009 Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). This Material is in GOOD condition as of this date.

10/12/2012 Material Description changed from ' Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). ' to ' Vinyl Wall Cover, (Wall Panel)'. Damage Observed. <5% Physical Damage - in the form of approximately 825 SF Removed in Boys Restroom, and Mastic is exposed. Quantity changed from 1,650 SF to 825 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.

04/05/2013 Material Condition Re-Assessed. Damages Repaired as of this date. Approximately 825 SF of Material has been Replaced. Quantity changed from 825 SF to 1,650 SF. Material Condition changed from FAIR to GOOD. Friability changed from Low to Non. No other changes as of this date.

08/29/2014 This Material is unchanged as of this date..

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 Damage Observed. <5% Physical Damage - in the form of 3 LF of Detached Wall Panel Near Stall Area, Drywall Exposed in Boys Restroom. No other changes as of this date.

|           |         |           |        |
|-----------|---------|-----------|--------|
| 09-212AAA | ASSUMED | NO SAMPLE | ( NS ) |
|-----------|---------|-----------|--------|

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### MAIN BUILDING

#### STUDENT RESTROOMS (2) (ON 1ST FLOOR)

VINYL WALL COVER MASTIC

2,475 SF

|            |                                                                                                                                                                                                                                                                                                                                                                                                                             |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/09/2009 | Mastic/Adhesive for Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                                                              |
| 10/12/2012 | Material Description changed from ' Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). ' to ' Vinyl Wall Cover, (Wall Panel)'. Damage: <5% Physical Damage - in the form of approximately 825 SF Removed in Boys Restroom, and Mastic is exposed. Quantity changed from 1,650 SF to 825 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date. |
| 04/05/2013 | Material Condition Re-Assessed. Damages Repaired as of this date. Approximately 825 SF of Material has been Replaced. Quantity changed from 825 SF to 1,650 SF. Material Condition changed from FAIR to GOOD. Friability changed from Low to Non. No other changes as of this date.                                                                                                                                         |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                 |
| 02/26/2025 | Damage Observed. <5% Physical Damage - in the form of 3 LF of Detached Wall Panel Near Stall Area, Drywall Exposed in Boys Restroom. No other changes as of this date.                                                                                                                                                                                                                                                      |

09-212AAA

ASSUMED

NO SAMPLE

( NS )

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER

09/01/2010 Building Notes:

09/01/2010 Metal Storage Container (1 EA).

METAL STORAGE CONTAINER

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

275 SF

03/17/2016 Metal Storage Container. 1 EA, 160 SF.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

08/10/2021 Quantity and Location Re-Assessed. There are 2 Metal Storage Containers at the time of this site visit. Both Containers are Located near the Daycare Portable. Material Quantity changed from 160 SF to 275 SF. No other changes as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

16-074.NS

ASSUMED

NO SAMPLE

( NS )

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

| SAMPLE NO. | ASBESTOS CONTENT | ASBESTOS NAME | ASBESTOS CODE |
|------------|------------------|---------------|---------------|
|------------|------------------|---------------|---------------|

### ROOM P1 AND P2 KINDERGARDEN BUILDING

### ROOM P1 AND P2 KINDERGARDEN BUILDING

|            |                                                                                                                                                                                                         |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | BUILDING NOTES:                                                                                                                                                                                         |
| 09/07/2005 | Manufacturer's TAG Info:<br>BY AMERICAN MODULAR SYS; DATE 08-98; OSA# 01-100822; SERIAL# 98-R377-002A, 98-R377-002B, 98-R377-002C, 98-R377-002D.<br>This Entry for informational and tracking purposes. |
| 03/08/2007 | Building Name changed from DAYCARE to DAYCARE PORTABLE BUILDING.                                                                                                                                        |
| 10/17/2008 | Serial #'s changed from # 98-R377-002A, 98-R377-002B to SERIAL# 98-R377-002A, 98-R377-002B, 98-R377-002C, 98-R377-002D.                                                                                 |
| 02/26/2025 | Building Name changed from DAYCARE PORTABLE BUILDING to ROOM P1 AND P2 KINDERGARDEN BUILDING.                                                                                                           |

### ROOM P1 AND P2 KINDERGARDEN BUILDING

CHILDCARE PORTABLE

PORTABLE BUILDING

1,920 SF

|            |                                                                                |
|------------|--------------------------------------------------------------------------------|
| 09/07/2005 | New 1998 Construction Relocatable Building per Manufacturer's Tag information. |
| 08/27/2020 | This Material is unchanged as of this date.                                    |
| 02/09/2021 | This Material is unchanged as of this date.                                    |
| 08/10/2021 | This Material is unchanged as of this date.                                    |
| 02/17/2022 | This Material is unchanged as of this date.                                    |
| 08/16/2022 | This Material is unchanged as of this date.                                    |
| 02/14/2023 | This Material is unchanged as of this date.                                    |
| 08/15/2023 | This Material is unchanged as of this date.                                    |
| 02/13/2024 | This Material is unchanged as of this date.                                    |
| 08/13/2024 | This Material is unchanged as of this date.                                    |
| 02/26/2025 | This Material is unchanged as of this date.                                    |

# SURVEY REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.

ASBESTOS CONTENT

ASBESTOS NAME

ASBESTOS CODE

WOOD STORAGE SHED

WOOD STORAGE SHED

02/14/2023 BUILDING NOTES:

02/14/2023 Storage Shed located next to Daycare Portable.

WOOD STORAGE SHED

WOOD STORAGE SHED

STORAGE BUILDING

TBD

02/14/2023 Wood Storage Shed.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

23-026.NS

NEW

NO SAMPLE

( NS )

End Of Report, Total Of 59 Pages

# HOMOGENEOUS MATERIALS IN CHERRYWOOD ELEMENTARY SCHOOL

## BUILDING NAME

### MATERIAL CATEGORY

### LOCATION

### MATERIAL TYPE

## BOILER ROOM AND STORAGE FACILITIES BUILDINGS

MISCELLANEOUS MATERIAL

BOILER ROOM

SMOOTH WALL  
MISCELLANEOUS

## CLASSROOMS 19 PORTABLE BUILDING

MISCELLANEOUS MATERIAL

PORTABLE 19

PORTABLE BUILDING

## CLASSROOMS 20 PORTABLE BUILDING

MISCELLANEOUS MATERIAL

PORTABLE 20

PORTABLE BUILDING

## CLASSROOMS 21-23 PORTABLE BUILDING

MISCELLANEOUS MATERIAL

PORTABLES 21-23

PORTABLE BUILDING

## CLASSROOMS 24-26 PORTABLE BUILDING

MISCELLANEOUS MATERIAL

PORTABLES 24-26

PORTABLE BUILDING

## LIBRARY PORTABLE BUILDING

MISCELLANEOUS MATERIAL

LIBRARY PORTABLE

PORTABLE BUILDING

## MAIN BUILDING

MISCELLANEOUS MATERIAL

2ND FLOOR

2ND FLOOR

2ND FLOOR

CARPET MASTIC

VINYL SHEETING

VINYL SHEETING BACKING  
PAPER/MASTIC

MORTAR MISCELLANEOUS

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS  
(CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED  
OUTSIDE OF BUILDING

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS'  
RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS,  
LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

2ND FLOOR TEACHERS LOUNGE

2ND FLOOR TEACHERS LOUNGE

ALL CLASSROOMS, 1ST LEVEL, LIBRARY, LIBRARY OFFICES

ALL CLASSROOMS, AND MULTI-USE ROOM

ALL CLASSROOMS, AND MULTI-USE ROOM

VINYL FLOOR TILE

VINYL FLOOR TILE MASTIC

VINYL SHEETING

VINYL SHEETING

CARPET MASTIC

WALL MASTIC

WALL PANEL

# HOMOGENEOUS MATERIALS IN CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME                                                                                                                               |  |                           |
|---------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------------|
| MATERIAL CATEGORY                                                                                                                           |  |                           |
| LOCATION                                                                                                                                    |  | MATERIAL TYPE             |
| ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES                                                                                 |  | CEILING MASTIC            |
| ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES                                                                                 |  | CEILING TILE              |
| ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE                                                                      |  | VINYL FLOOR TILE          |
| ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE                                                                      |  | VINYL FLOOR TILE MASTIC   |
| ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE                                                                    |  | SINK UNDERCOATING         |
| CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)                                                                          |  | VINYL FLOOR TILE          |
| CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)                                                                          |  | VINYL FLOOR TILE MASTIC   |
| CLASSROOMS, MULTI-USE ROOM AND WORKROOM                                                                                                     |  | VINYL WALL COVER          |
| CLASSROOMS, MULTI-USE ROOM AND WORKROOM                                                                                                     |  | VINYL WALL COVER MASTIC   |
| ENTIRE 1ST LEVEL                                                                                                                            |  | BASEBOARD MASTIC          |
| ENTIRE BUILDING                                                                                                                             |  | SMOOTH WALL               |
|                                                                                                                                             |  | MISCELLANEOUS             |
| ENTIRE BUILDING                                                                                                                             |  | WINDOW SEALANT            |
| ENTIRE FIRST LEVEL                                                                                                                          |  | BASEBOARD MASTIC          |
| KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN                                                                                                |  | VINYL SHEETING            |
| KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN                                                                                                 |  | VINYL SHEETING BACKING    |
|                                                                                                                                             |  | PAPER/MASTIC              |
| MULTI-PURPOSE ROOM                                                                                                                          |  | CEILING MASTIC            |
| MULTI-PURPOSE ROOM                                                                                                                          |  | CEILING PANEL             |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |  | GLUED TILES               |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |  | WALL TILE                 |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |  | WALL TILE MASTIC          |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |  | WALL TILE MASTIC          |
| OFFICES, WORKROOM, HALLWAY                                                                                                                  |  | SUSPENDED CEILING TILE    |
| STAFF MENS RESTROOM, 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, WOMENS RESTROOM, PRINCIPALS OFFICE, AND STORAGE ROOMS |  | BASEBOARD MASTIC          |
| STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))                                                                       |  | VINYL SHEETING            |
| STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))                                                                       |  | VINYL SHEETING BACKING    |
| STORAGE ROOM NEXT TO RESTROOM, MULTI-PURPOSE ROOM, ELEVATOR EQUIPMENT ROOM, PRINCIPALS OFFICE, AND NURSES ROOM                              |  | PAPER/MASTIC              |
|                                                                                                                                             |  | FIRE DOOR CORE INSULATION |
| STORAGE ROOMS                                                                                                                               |  | VINYL FLOOR TILE          |
| STORAGE ROOMS                                                                                                                               |  | VINYL FLOOR TILE MASTIC   |
| STUDENT RESTROOMS (2) (1ST FLOOR)                                                                                                           |  | CEMENTITIOUS WALL PANEL   |
| STUDENT RESTROOMS (2) (1ST FLOOR)                                                                                                           |  | WALL MASTIC               |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR)                                                                                                        |  | MORTAR MISCELLANEOUS      |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR)                                                                                                        |  | VINYL WALL COVER          |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR)                                                                                                        |  | VINYL WALL COVER MASTIC   |
| SURFACING MATERIAL                                                                                                                          |  |                           |
| ENTIRE BUILDING                                                                                                                             |  | SMOOTH WALL SURFACING     |
| ENTIRE BUILDING IN DESIGNATED AREAS                                                                                                         |  | SPRAY ON CEILING          |
| ENTRY AREAS (2)                                                                                                                             |  | SMOOTH WALL SURFACING     |
| EXTERIOR WALLS AND OVERHANG                                                                                                                 |  | ROUGH WALL                |
| EXTERIOR WALLS AND OVERHANG                                                                                                                 |  | ROUGH WALL SURFACING      |

**HOMOGENEOUS MATERIALS IN**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**MATERIAL CATEGORY**

**LOCATION**

**MATERIAL TYPE**

THERMAL SYSTEM INSULATION

2ND FLOOR STORAGE CLOSET AND ATTIC AREAS

BOILER ROOM

DUCT WRAP TAPE

BOILER INSULATION

**METAL STORAGE CONTAINER**

MISCELLANEOUS MATERIAL

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

**ROOM P1 AND P2 KINDERGARDEN BUILDING**

MISCELLANEOUS MATERIAL

CHILDCARE PORTABLE

PORTABLE BUILDING

**WOOD STORAGE SHED**

MISCELLANEOUS MATERIAL

WOOD STORAGE SHED

STORAGE BUILDING

**End Of Report, Total Of 3 Pages**

# FRIABLE LOCATIONS IN CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME                                                          | LOCATION                            | QTY<br>(APPROXIMATE) | ASBESTOS<br>CONTENT |
|------------------------------------------------------------------------|-------------------------------------|----------------------|---------------------|
| MATERIAL TYPE                                                          |                                     |                      |                     |
| <b>BOILER ROOM AND STORAGE FACILITIES BUILDINGS</b>                    |                                     |                      |                     |
| BOILER ROOM                                                            | SMOOTH WALL MISCELLANEOUS           | 900 SF               | Assumed             |
| <b>MAIN BUILDING</b>                                                   |                                     |                      |                     |
| 2ND FLOOR                                                              | CARPET MASTIC                       | 420 SF               | Assumed             |
| 2ND FLOOR                                                              | VINYL SHEETING BACKING PAPER/MASTIC | 2,160 SF             | Non Detected        |
| 2ND FLOOR STORAGE CLOSET AND ATTIC AREAS                               | DUCT WRAP TAPE                      | 200 SF               | Greater Than 1%     |
| ALL CLASSROOMS, AND MULTI-USE ROOM                                     | WALL MASTIC                         | 8,900 SF             | Assumed             |
| ALL CLASSROOMS, AND MULTI-USE ROOM                                     | WALL PANEL                          | 8,900 SF             | Non Detected        |
| ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES            | CEILING MASTIC                      | 23,350 SF            | Non Detected        |
| ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES            | CEILING TILE                        | 23,350 SF            | Non Detected        |
| ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE | VINYL FLOOR TILE                    | 4,700 SF             | Assumed             |
| ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE | VINYL FLOOR TILE MASTIC             | 4,700 SF             | Assumed             |
| BOILER ROOM                                                            | BOILER INSULATION                   | 0 SF                 | Assumed             |
| CLASSROOMS, MULTI-USE ROOM AND WORKROOM                                | VINYL WALL COVER                    | 11,000 SF            | Non Detected        |
| CLASSROOMS, MULTI-USE ROOM AND WORKROOM                                | VINYL WALL COVER MASTIC             | 11,000 SF            | Non Detected        |
| ENTIRE BUILDING                                                        | SMOOTH WALL MISCELLANEOUS           | 67,000 SF            | Greater Than 1%     |
| ENTIRE BUILDING                                                        | SMOOTH WALL SURFACING               | 62,760 SF            | Greater Than 1%     |
| ENTIRE BUILDING IN DESIGNATED AREAS                                    | SPRAY ON CEILING                    | 3,840 SF             | Greater Than 1%     |

# FRIABLE LOCATIONS IN CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION                                                                                                                                    | QTY<br>(APPROXIMATE) | ASBESTOS<br>CONTENT |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|
|               | MATERIAL TYPE                                                                                                                               |                      |                     |
|               | ENTIRE FIRST LEVEL                                                                                                                          |                      |                     |
|               | BASEBOARD MASTIC                                                                                                                            | 3,850 LF             | Non Detected        |
|               | EXTERIOR WALLS AND OVERHANG                                                                                                                 |                      |                     |
|               | ROUGH WALL                                                                                                                                  | 15,000 SF            | Assumed             |
|               | EXTERIOR WALLS AND OVERHANG                                                                                                                 |                      |                     |
|               | ROUGH WALL SURFACING                                                                                                                        | 15,000 SF            | Assumed             |
|               | KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN                                                                                                |                      |                     |
|               | VINYL SHEETING                                                                                                                              | 384 SF               | Non Detected        |
|               | KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN                                                                                                 |                      |                     |
|               | VINYL SHEETING BACKING PAPER/MASTIC                                                                                                         | 384 SF               | Non Detected        |
|               | MULTI-PURPOSE ROOM                                                                                                                          |                      |                     |
|               | CEILING PANEL                                                                                                                               | 5,360 SF             | Non Detected        |
|               | MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |                      |                     |
|               | GLUED TILES                                                                                                                                 | 600 SF               | Assumed             |
|               | MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                            |                      |                     |
|               | WALL TILE                                                                                                                                   | 1,020 SF             | Assumed             |
|               | OFFICES, WORKROOM, HALLWAY                                                                                                                  |                      |                     |
|               | SUSPENDED CEILING TILE                                                                                                                      | 3,500 SF             | Assumed             |
|               | STAFF MENS RESTROOM, 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, WOMENS RESTROOM, PRINCIPALS OFFICE, AND STORAGE ROOMS |                      |                     |
|               | BASEBOARD MASTIC                                                                                                                            | 730 LF               | Non Detected        |
|               | STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))                                                                       |                      |                     |
|               | VINYL SHEETING                                                                                                                              | 385 SF               | Non Detected        |
|               | STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))                                                                       |                      |                     |
|               | VINYL SHEETING BACKING PAPER/MASTIC                                                                                                         | 385 SF               | Non Detected        |
|               | STORAGE ROOM NEXT TO RESTROOM, MULTI-PURPOSE ROOM, ELEVATOR EQUIPMENT ROOM, PRINCIPALS OFFICE, AND NURSES ROOM                              |                      |                     |
|               | FIRE DOOR CORE INSULATION                                                                                                                   | 252 SF               | Assumed             |
|               | STORAGE ROOMS                                                                                                                               |                      |                     |
|               | VINYL FLOOR TILE                                                                                                                            | 275 SF               | Non Detected        |
|               | STORAGE ROOMS                                                                                                                               |                      |                     |
|               | VINYL FLOOR TILE MASTIC                                                                                                                     | 275 SF               | Non Detected        |
|               | STUDENT RESTROOMS (2) (1ST FLOOR)                                                                                                           |                      |                     |
|               | CEMENTITIOUS WALL PANEL                                                                                                                     | 1,650 SF             | Assumed             |
|               | STUDENT RESTROOMS (2) (1ST FLOOR)                                                                                                           |                      |                     |
|               | WALL MASTIC                                                                                                                                 | 1,650 SF             | Assumed             |

S= Sq. Ft, I=Inches, L=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

**FRIABLE LOCATIONS IN  
CHERRYWOOD ELEMENTARY SCHOOL**

| BUILDING NAME                        |  |  |                      |
|--------------------------------------|--|--|----------------------|
| LOCATION                             |  |  |                      |
| MATERIAL TYPE                        |  |  |                      |
|                                      |  |  | QTY<br>(APPROXIMATE) |
|                                      |  |  | ASBESTOS<br>CONTENT  |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR) |  |  |                      |
| VINYL WALL COVER                     |  |  | 1,650 SF             |
|                                      |  |  | Assumed              |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR) |  |  |                      |
| VINYL WALL COVER MASTIC              |  |  | 2,475 SF             |
|                                      |  |  | Assumed              |
| End Of Report, Total Of 3 Pages      |  |  |                      |

# Non- Friable Locations In CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME                                                                                                                                           | LOCATION                | QTY<br>(APPROXIMATE) | ASBESTOS<br>CONTENT |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------------------|---------------------|
| MATERIAL TYPE                                                                                                                                           |                         |                      |                     |
| <b>MAIN BUILDING</b>                                                                                                                                    |                         |                      |                     |
| 2ND FLOOR                                                                                                                                               |                         |                      |                     |
|                                                                                                                                                         | VINYL SHEETING          | 2,640 SF             | Non Detected        |
| 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS (CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING            |                         |                      |                     |
|                                                                                                                                                         | MORTAR MISCELLANEOUS    | 2,620 SF             | Non Detected        |
| 2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS' RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING |                         |                      |                     |
|                                                                                                                                                         | MORTAR MISCELLANEOUS    | 1,270 SF             | Non Detected        |
| 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE                                                                                               |                         |                      |                     |
|                                                                                                                                                         | VINYL FLOOR TILE        | 450 SF               | Assumed             |
| 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE                                                                                               |                         |                      |                     |
|                                                                                                                                                         | VINYL FLOOR TILE MASTIC | 530 SF               | Assumed             |
| 2ND FLOOR TEACHERS LOUNGE                                                                                                                               |                         |                      |                     |
|                                                                                                                                                         | VINYL SHEETING          | 900 SF               | New Material        |
| 2ND FLOOR TEACHERS LOUNGE                                                                                                                               |                         |                      |                     |
|                                                                                                                                                         | VINYL SHEETING          | 900 SF               | New Material        |
| ALL CLASSROOMS, 1ST LEVEL, LIBRARY, LIBRARY OFFICES                                                                                                     |                         |                      |                     |
|                                                                                                                                                         | CARPET MASTIC           | 20,000 SF            | New Material        |
| ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE                                                                                |                         |                      |                     |
|                                                                                                                                                         | SINK UNDERCOATING       | 80 SF                | Assumed             |
| CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)                                                                                      |                         |                      |                     |
|                                                                                                                                                         | VINYL FLOOR TILE        | 1,200 SF             | New Material        |
| CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)                                                                                      |                         |                      |                     |
|                                                                                                                                                         | VINYL FLOOR TILE MASTIC | 1,200 SF             | New Material        |
| ENTIRE 1ST LEVEL                                                                                                                                        |                         |                      |                     |
|                                                                                                                                                         | BASEBOARD MASTIC        | 3,850 SF             | New Material        |
| ENTIRE BUILDING                                                                                                                                         |                         |                      |                     |
|                                                                                                                                                         | WINDOW SEALANT          | 88 LF                | Greater Than 1%     |
| ENTRY AREAS (2)                                                                                                                                         |                         |                      |                     |
|                                                                                                                                                         | SMOOTH WALL SURFACING   | 660 SF               | Assumed             |
| MULTI-PURPOSE ROOM                                                                                                                                      |                         |                      |                     |
|                                                                                                                                                         | CEILING MASTIC          | 5,360 SF             | Greater Than 1%     |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                                        |                         |                      |                     |
|                                                                                                                                                         | WALL TILE MASTIC        | 1,020 SF             | Assumed             |
| MULTI-PURPOSE ROOM (OLD LIBRARY)                                                                                                                        |                         |                      |                     |
|                                                                                                                                                         | WALL TILE MASTIC        | 600 SF               | Assumed             |
| STUDENT RESTROOMS (2) (ON 1ST FLOOR)                                                                                                                    |                         |                      |                     |
|                                                                                                                                                         | MORTAR MISCELLANEOUS    | 450 SF               | Assumed             |

**Non- Friable Locations In**  
**CHERRYWOOD ELEMENTARY SCHOOL**

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY**

**(APPROXIMATE)**

**ASBESTOS**

**CONTENT**

---

**METAL STORAGE CONTAINER**

**WOOD STORAGE SHED**

WOOD STORAGE SHED

STORAGE BUILDING

TBD

Assumed

---

**End Of Report, Total Of 2 Pages**

---

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**BOILER ROOM AND STORAGE FACILITIES BUILDINGS**

**BOILER ROOM**

SMOOTH WALL MISCELLANEOUS 900 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**CLASSROOMS 19 PORTABLE BUILDING**

**PORTABLE 19**

PORTABLE BUILDING 960 SF

- (a) This is a replacement/new material.
- (b) The district should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the district's AHERA records.

**CLASSROOMS 20 PORTABLE BUILDING**

**PORTABLE 20**

PORTABLE BUILDING 960 SF

- (a) This is a replacement/new material.
- (b) The district should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the district's AHERA records.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**CLASSROOMS 21-23 PORTABLE BUILDING**

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**PORTABLES 21-23**

PORTABLE BUILDING

2,880 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

**CLASSROOMS 24-26 PORTABLE BUILDING**

**PORTABLES 24-26**

PORTABLE BUILDING

2,880 SF

- (a) This is a replacement/new material.
- (b) The district should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the district's AHERA records.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**LIBRARY PORTABLE BUILDING**

**LIBRARY PORTABLE**

PORTABLE BUILDING

1,920 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

**MAIN BUILDING**

**2ND FLOOR**

CARPET MASTIC

420 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**2ND FLOOR**

VINYL SHEETING

2,640 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**2ND FLOOR**

VINYL SHEETING BACKING PAPER/MASTIC

2,160 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS (CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

2,620 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS' RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

1,270 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

2ND FLOOR STORAGE CLOSET AND ATTIC AREAS

DUCT WRAP TAPE

200 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE

450 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE MASTIC

530 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### 2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

900 SF

### 2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

900 SF

### ALL CLASSROOMS, 1ST LEVEL, LIBRARY, LIBRARY OFFICES

CARPET MASTIC

20,000 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

### ALL CLASSROOMS, AND MULTI-USE ROOM

WALL MASTIC

8,900 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### ALL CLASSROOMS, AND MULTI-USE ROOM

WALL PANEL

8,900 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING MASTIC

23,350 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING TILE

23,350 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE

VINYL FLOOR TILE

4,700 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE**

VINYL FLOOR TILE MASTIC

4,700 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

---

**ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE**

SINK UNDERCOATING

80 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**BOILER ROOM**

BOILER INSULATION

0 SF

The material has been removed. No further recommendation is required.

---

**CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)**

VINYL FLOOR TILE

1,200 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

---

**CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)**

VINYL FLOOR TILE MASTIC

1,200 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

### BUILDING NAME

### LOCATION

### MATERIAL TYPE

### RECOMMENDATION

### QTY

### (APPROXIMATE)

#### CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER 11,000 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

#### CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER MASTIC 11,000 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

#### ENTIRE 1ST LEVEL

BASEBOARD MASTIC 3,850 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

#### ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS 67,000 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### ENTIRE BUILDING

SMOOTH WALL SURFACING 62,760 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ENTIRE BUILDING

WINDOW SEALANT 88 LF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ENTIRE BUILDING IN DESIGNATED AREAS

SPRAY ON CEILING 3,840 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### ENTIRE FIRST LEVEL

BASEBOARD MASTIC 3,850 LF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### ENTRY AREAS (2)

SMOOTH WALL SURFACING 660 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### EXTERIOR WALLS AND OVERHANG

ROUGH WALL 15,000 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### EXTERIOR WALLS AND OVERHANG

ROUGH WALL SURFACING 15,000 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

### KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN

VINYL SHEETING 384 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

---

**BUILDING NAME**
**LOCATION**
**MATERIAL TYPE**
**RECOMMENDATION**
**QTY**
**(APPROXIMATE)**


---

**KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN**
**VINYL SHEETING BACKING PAPER/MASTIC**
**384 SF**

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
- 

**MULTI-PURPOSE ROOM**
**CEILING MASTIC**
**5,360 SF**

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

**MULTI-PURPOSE ROOM**
**CEILING PANEL**
**5,360 SF**

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

**MULTI-PURPOSE ROOM (OLD LIBRARY)**
**GLUED TILES**
**600 SF**

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**MULTI-PURPOSE ROOM (OLD LIBRARY)****WALL TILE**

1,020 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

**MULTI-PURPOSE ROOM (OLD LIBRARY)****WALL TILE MASTIC**

1,020 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

**MULTI-PURPOSE ROOM (OLD LIBRARY)****WALL TILE MASTIC**

600 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

---

**OFFICES, WORKROOM, HALLWAY****SUSPENDED CEILING TILE**

3,500 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

STAFF MENS RESTROOM, 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, WOMENS RESTROOM, PRINCIPALS OFFICE, AND STORAGE ROOMS

BASEBOARD MASTIC

730 LF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING

385 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING BACKING PAPER/MASTIC

385 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

STORAGE ROOM NEXT TO RESTROOM, MULTI-PURPOSE ROOM, ELEVATOR EQUIPMENT ROOM, PRINCIPALS OFFICE, AND NURSES ROOM

FIRE DOOR CORE INSULATION

252 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**STORAGE ROOMS**

VINYL FLOOR TILE

275 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

**STORAGE ROOMS**

VINYL FLOOR TILE MASTIC

275 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

**STUDENT RESTROOMS (2) (1ST FLOOR)**

CEMENTITIOUS WALL PANEL

1,650 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**STUDENT RESTROOMS (2) (1ST FLOOR)**

WALL MASTIC

1,650 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**STUDENT RESTROOMS (2) (ON 1ST FLOOR)**

MORTAR MISCELLANEOUS

450 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**STUDENT RESTROOMS (2) (ON 1ST FLOOR)**

VINYL WALL COVER

1,650 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**STUDENT RESTROOMS (2) (ON 1ST FLOOR)**

VINYL WALL COVER MASTIC

2,475 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**METAL STORAGE CONTAINER**

**METAL STORAGE CONTAINER (1 EA)**

STORAGE CONTAINER

275 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**ROOM P1 AND P2 KINDERGARDEN BUILDING**

**CHILDCARE PORTABLE**

PORTABLE BUILDING

1,920 SF

- (a) This is a replacement/new material.
- (b) The district should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the district's AHERA records.

**RECOMMENDATIONS FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

**WOOD STORAGE SHED**

---

**WOOD STORAGE SHED**

STORAGE BUILDING

TBD

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
- 

---

**End Of Report, Total Of 17 Pages**

---

**SAMPLES REPORT FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

| <b>SAMPLE No.</b> | <b>DATE</b> | <b>RESULT</b> | <b>ASBESTOS<br/>CONTENT</b> | <b>ASBESTOS<br/>NAME</b> | <b>ASBESTOS<br/>TYPE</b> |
|-------------------|-------------|---------------|-----------------------------|--------------------------|--------------------------|
| <b>COMMENTS</b>   |             |               |                             |                          |                          |

**BOILER ROOM AND STORAGE FACILITIES BUILDINGS**

**BOILER ROOM AND STORAGE FACILITIES BUILDINGS**

BOILER ROOM

SMOOTH WALL MISCELLANEOUS

**10-019 CW-21**

2/2/2010

Negative

ND

NONE DETECTED

ND

Joint Tape

**10-019 CW-21**

2/2/2010

Negative

ND

NONE DETECTED

ND

Joint Compound

**10-019 CW-22**

2/2/2010

Negative

ND

NONE DETECTED

ND

Drywall

**SAMPLES REPORT FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

| <b>SAMPLE NO.<br/>COMMENTS</b> | <b>DATE</b> | <b>RESULT</b> | <b>ASBESTOS<br/>CONTENT</b> | <b>ASBESTOS<br/>NAME</b> | <b>ASBESTOS<br/>TYPE</b> |
|--------------------------------|-------------|---------------|-----------------------------|--------------------------|--------------------------|
|--------------------------------|-------------|---------------|-----------------------------|--------------------------|--------------------------|

**CLASSROOMS 21-23 PORTABLE BUILDING**

**CLASSROOMS 21-23 PORTABLE BUILDING**

PORTABLES 21-23

PORTABLE BUILDING

**08-241AAA**

10/17/2008 Negative

NEW MATERIAL

NO SAMPLE

NS

New 2006 Construction Relocatable Buildings per Manufacturer's Tag information.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

### MAIN BUILDING

2ND FLOOR  
 VINYL SHEETING

|                                                                                                  |           |          |    |               |    |
|--------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-22</u></b>                                                                       | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-22, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting. |           |          |    |               |    |

### MAIN BUILDING

2ND FLOOR  
 VINYL SHEETING BACKING PAPER/MASTIC

|                                                                                                                                                     |           |          |    |               |    |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-23-Leveler</u></b>                                                                                                                  | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-23-Leveler, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. |           |          |    |               |    |

|                                                                                                                                                    |           |          |    |               |    |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-23-Mastic</u></b>                                                                                                                  | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-23-Mastic, Mezzanine, 205 Nurses Floor, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. |           |          |    |               |    |

|                                                                                                                                                           |           |          |    |               |    |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-23-Sheet</u></b>                                                                                                                          | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-23-Sheet Flooring, Mezzanine, 205 Nurses Room, Floor Covering Beige Vinyl Sheeting, Backing Paper, Yellow Mastic and Compound. |           |          |    |               |    |

|                                                                                                                         |           |          |    |               |    |
|-------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-24-Leveler</u></b>                                                                                      | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-240-Leveler, Mezzanine, 205 Nurses Floor, Floor Carpet, Yellow Brown Mastic and White Compound. |           |          |    |               |    |

|                                                                                                                          |           |          |    |               |    |
|--------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-24-Mastic</u></b>                                                                                        | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-24-Mastic, Mezzanine, 205 Nurses Floor, Floor Carpet, Yellow Brown Mastic and White Compound. |           |          |    |               |    |

### MAIN BUILDING

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 RESTROOMS (CLASSROOMS 16, 17 AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING  
 MORTAR MISCELLANEOUS

|                                                                                            |           |          |    |               |    |
|--------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-01</u></b>                                                                 | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-01. Mezzanine, 200 Women Restroom - 4" Ceramic Wall Tile Grout. |           |          |    |               |    |

|                                                                                                   |           |          |    |               |    |
|---------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-02</u></b>                                                                        | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| Sample Collected 17-183-3C-02, Mezzanine, 200 Women Restroom. 4" Ceramic Wall Tile Backing Board. |           |          |    |               |    |

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME****LOCATION****MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

**MAIN BUILDING**

2ND FLOOR, STAFF RESTROOMS (MENS AND WOMENS), 3 STUDENTS' RESTROOMS (CLASSROOMS 16, 17, AND 18), AND 6 STUDENTS' RESTROOMS, LOCATED OUTSIDE OF BUILDING

MORTAR MISCELLANEOUS

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-03</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183 3C-03, Mezzanine, 200 Women Restroom, 12" Ceramic Floor Tile Grout.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-04</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183 3C-04, Mezzanine, 200 Women Restroom, 12" Ceramic Floor Tile Mortar Bed.

**MAIN BUILDING**

2ND FLOOR STORAGE CLOSET AND ATTIC AREAS

DUCT WRAP TAPE

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-18-Joint Tape</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-18-Mastic, Mezzanine, Mech Room, Air Ductwock Joint Tape and Mastic.

|                                   |           |          |    |           |    |
|-----------------------------------|-----------|----------|----|-----------|----|
| <b><u>17-183-3C-18-Mastic</u></b> | 8/30/2017 | Positive | 10 | CHRYSTILE | CH |
|-----------------------------------|-----------|----------|----|-----------|----|

Sample Collected 17-183 3C-18, Mezzanine, Mech Room, Air Ductwock Joint Tape and Mastic.

**MAIN BUILDING**

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE

|                                       |           |          |   |           |    |
|---------------------------------------|-----------|----------|---|-----------|----|
| <b><u>17-183-3C-16-Floor Tile</u></b> | 8/30/2017 | Positive | 3 | CHRYSTILE | CH |
|---------------------------------------|-----------|----------|---|-----------|----|

Sample Collected 17-183 3C-16, Mezzanine, 205 Nurses Floor, 12" Beige Vinyl Floor Tile.

**MAIN BUILDING**

2ND FLOOR SUPPLY ROOM, NURSES OFFICE, AND TEACHERS LOUNGE

VINYL FLOOR TILE MASTIC

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-16</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-16-Mastic, Mezzanine, 205 Nurses Floor, 12" Beige Vinyl Floor Tile Mastic.

|                                    |           |          |   |           |    |
|------------------------------------|-----------|----------|---|-----------|----|
| <b><u>17-183-3C-17-Leveler</u></b> | 8/30/2017 | Positive | 2 | CHRYSTILE | CH |
|------------------------------------|-----------|----------|---|-----------|----|

Sample Collected 17-183 3C-17-Leveler, Mezzanine, 205, Nurses Floor, 12" Beige Vinyl Floor Tile, Black Mastic.

|                                   |           |          |   |           |    |
|-----------------------------------|-----------|----------|---|-----------|----|
| <b><u>17-183-3C-17-Mastic</u></b> | 8/30/2017 | Positive | 5 | CHRYSTILE | CH |
|-----------------------------------|-----------|----------|---|-----------|----|

Sample Collected 17-183-3C-17-Mastic, Mezzanine, 205 Nurses, 12" Beige Vinyl Floor Tile Black Mastic.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

### BUILDING NAME

### LOCATION

### MATERIAL TYPE

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

|                         |           |          |              |           |    |
|-------------------------|-----------|----------|--------------|-----------|----|
| <b><u>25-036.NS</u></b> | 2/26/2025 | Negative | NEW MATERIAL | NO SAMPLE | NS |
|-------------------------|-----------|----------|--------------|-----------|----|

### MAIN BUILDING

2ND FLOOR TEACHERS LOUNGE

VINYL SHEETING

|                         |           |          |              |           |    |
|-------------------------|-----------|----------|--------------|-----------|----|
| <b><u>25-036.NS</u></b> | 2/26/2025 | Negative | NEW MATERIAL | NO SAMPLE | NS |
|-------------------------|-----------|----------|--------------|-----------|----|

### MAIN BUILDING

ALL CLASSROOMS, 1ST LEVEL, LIBRARY, LIBRARY OFFICES

CARPET MASTIC

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

### MAIN BUILDING

ALL CLASSROOMS, AND MULTI-USE ROOM

WALL PANEL

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-07</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

Sample 10-019 CW-07 collected from Workroom Area 119 Wall.

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-10</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

Sample 10-019 CW-10 collected from Workroom Area 119 Wall.

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING MASTIC

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-09</u></b> | 9/7/2005 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-16</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING TILE

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-08</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-15</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------|----------|----------|----|---------------|----|

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-05</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-05, Mezzanine, 201 Computer Area, 1'X1' Ceiling Tile.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-06</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-06. Mezzanine, 201 Computer Area, 1'X1' Ceiling Tile, Brown Mastic.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-07</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-07, Mezzanine, 201 Computer Room, (Under 1'X1' Ceiling Tile) Acoustic Texture.

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE  
 VINYL FLOOR TILE

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE  
 VINYL FLOOR TILE MASTIC

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

### MAIN BUILDING

ALL CLASSROOMS, TEACHER LOUNGE, NURSE'S OFFICE AND 2ND FLOOR KITCHENETTE  
 SINK UNDERCOATING

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>08-241AAA</u></b> | 10/17/2008 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

### MAIN BUILDING

BOILER ROOM  
 BOILER INSULATION

|                         |           |          |         |           |    |
|-------------------------|-----------|----------|---------|-----------|----|
| <b><u>23-093REM</u></b> | 8/15/2023 | Negative | REMOVED | NO SAMPLE | NS |
|-------------------------|-----------|----------|---------|-----------|----|

### MAIN BUILDING

CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)  
 VINYL FLOOR TILE

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

### MAIN BUILDING

CAFETERIA/MULTI-PURPOSE ROOM AND KIDS KITCHEN(OLD LIBRARY KITCHEN)  
 VINYL FLOOR TILE MASTIC

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

CLASSROOMS, MULTI-USE ROOM AND WORKROOM  
 VINYL WALL COVER

|                                                                                    |           |          |         |               |    |
|------------------------------------------------------------------------------------|-----------|----------|---------|---------------|----|
| <b><u>10-019 CW05</u></b>                                                          | 2/2/2010  | Negative | ND      | NONE DETECTED | ND |
| <b><u>10-174AAA</u></b>                                                            | 9/1/2010  | Positive | ASSUMED | NO SAMPLE     | NS |
| <b><u>17-183 3C-19</u></b>                                                         | 8/30/2017 | Negative | ND      | NONE DETECTED | ND |
| Sample Collected 17-183-3C-19, Mezzanine, Reception Wall, Vinyl Wall Covered Only. |           |          |         |               |    |

### MAIN BUILDING

CLASSROOMS, MULTI-USE ROOM AND WORKROOM  
 VINYL WALL COVER MASTIC

|                                                                                               |           |          |         |               |    |
|-----------------------------------------------------------------------------------------------|-----------|----------|---------|---------------|----|
| <b><u>10-019 CW06</u></b>                                                                     | 2/2/2010  | Negative | ND      | NONE DETECTED | ND |
| Mastic                                                                                        |           |          |         |               |    |
| <b><u>10-019 CW06</u></b>                                                                     | 2/2/2010  | Positive | <1      | CHRYSTILE     | CH |
| Joint Compound                                                                                |           |          |         |               |    |
| <b><u>10-174AAA</u></b>                                                                       | 9/1/2010  | Positive | ASSUMED | NO SAMPLE     | NS |
| <b><u>17-183 3C-20</u></b>                                                                    | 8/30/2017 | Negative | ND      | NONE DETECTED | ND |
| Sample Collected, 17-183-3C-20, Mezzanine, 205 Nurses Wall, Vinyl Wall Covered Adhesive Only. |           |          |         |               |    |

### MAIN BUILDING

ENTIRE 1ST LEVEL  
 BASEBOARD MASTIC

|                         |          |          |              |               |    |
|-------------------------|----------|----------|--------------|---------------|----|
| <b><u>18-127AAA</u></b> | 8/8/2018 | Negative | NEW MATERIAL | NONE DETECTED | ND |
|-------------------------|----------|----------|--------------|---------------|----|

### MAIN BUILDING

ENTIRE BUILDING  
 SMOOTH WALL MISCELLANEOUS

|                            |          |          |    |               |    |
|----------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW-13</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
| Joint Tape                 |          |          |    |               |    |
| <b><u>10-019 CW-13</u></b> | 2/2/2010 | Positive | <1 | CHRYSTILE     | CH |
| Joint Compound             |          |          |    |               |    |

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

|                                |          |          |    |               |    |
|--------------------------------|----------|----------|----|---------------|----|
| <b>10-019 CW-14</b><br>Drywall | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|--------------------------------|----------|----------|----|---------------|----|

|                                       |          |          |    |               |    |
|---------------------------------------|----------|----------|----|---------------|----|
| <b>10-019 CW-19</b><br>Joint Compound | 2/2/2010 | Positive | <1 | NONE DETECTED | ND |
|---------------------------------------|----------|----------|----|---------------|----|

|                                   |          |          |    |               |    |
|-----------------------------------|----------|----------|----|---------------|----|
| <b>10-019 CW-19</b><br>Joint Tape | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|-----------------------------------|----------|----------|----|---------------|----|

|                                |          |          |    |               |    |
|--------------------------------|----------|----------|----|---------------|----|
| <b>10-019 CW-20</b><br>Drywall | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|--------------------------------|----------|----------|----|---------------|----|

|                                  |          |          |    |               |    |
|----------------------------------|----------|----------|----|---------------|----|
| <b>10-019CW-03</b><br>Joint Tape | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|----------------------------------|----------|----------|----|---------------|----|

|                                      |          |          |    |           |    |
|--------------------------------------|----------|----------|----|-----------|----|
| <b>10-019CW-03</b><br>Joint Compound | 2/2/2010 | Positive | <1 | CHRYSTILE | CH |
|--------------------------------------|----------|----------|----|-----------|----|

|                               |          |          |    |               |    |
|-------------------------------|----------|----------|----|---------------|----|
| <b>10-019CW-04</b><br>Drywall | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|-------------------------------|----------|----------|----|---------------|----|

|                                                                                                                              |           |          |   |               |    |
|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|---|---------------|----|
| <b>17-183 3C-11</b><br>Sample Collected 17-183 3C-11, Mezzanine, 202 Conference, Wall Joint Tape and Mud (For Gypsum Board). | 8/30/2017 | Positive | 2 | NONE DETECTED | ND |
|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|---|---------------|----|

|                                                                                                     |           |          |    |           |    |
|-----------------------------------------------------------------------------------------------------|-----------|----------|----|-----------|----|
| <b>17-183 3C-12</b><br>Sample Collected 17-183 3C-12, Mezzanine, 202 Conference, Wall Gypsum Board. | 8/30/2017 | Negative | ND | CHRYSTILE | CH |
|-----------------------------------------------------------------------------------------------------|-----------|----------|----|-----------|----|

|                                                                                                                    |           |          |    |               |    |
|--------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b>17-183-3C-36</b><br>Sample Collected 17-183-3C-36, Main Building, Multi-Purpose Room 144, Ceiling Gypsum Board. | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|--------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|

### MAIN BUILDING

ENTIRE BUILDING

SMOOTH WALL SURFACING

|                     |          |          |    |               |    |
|---------------------|----------|----------|----|---------------|----|
| <b>10-019 CW-12</b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|---------------------|----------|----------|----|---------------|----|

|                     |          |          |    |           |    |
|---------------------|----------|----------|----|-----------|----|
| <b>10-019 CW-18</b> | 2/2/2010 | Positive | <1 | CHRYSTILE | CH |
|---------------------|----------|----------|----|-----------|----|

|                                                                                                                              |           |          |    |               |    |
|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b>17-183 3C-10</b><br>Sample Collected 17-183-3C-10, Mezzanine, 202 Conference, Wall Skimcoat and Paint (for Gypsum Board). | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

BUILDING NAME

LOCATION

MATERIAL TYPE

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### **17-183-3C-35**

8/30/2017

Positive

2

CHRYSTILE

CH

Sample Collected 17-183-3C-35, Main Building, Multi-Purpose Room 144, Ceiling Joint Tape and Mud (For Gypsum Board).

### MAIN BUILDING

ENTIRE BUILDING

WINDOW SEALANT

### **17-183 3C-13**

8/30/2017

Positive

<1

CHRYSTILE

CH

Sample Collected 17-183-3C-13, Mezzanine, 202 Conference, North Side Interior Window Gray Sealant.

### **17-183 3C-15**

8/30/2017

Positive

8

CHRYSTILE

CH

Sample Collected 17-183 3C-15, Mezzanine, 205 Nurses, South Side Interior Window Gray Sealant.

### **17-183-3C-53**

8/30/2017

Negative

ND

NONE DETECTED

ND

Sample Collected 17-183-3C-53, Main Building, Classroom 5 (130), Interior Window Black Sealant.

### **17-183-3C-58**

8/30/2017

Negative

ND

NONE DETECTED

ND

Sample Collected 17-183-3C-58, Main Building, Classroom 8 (124), Interior Window Black Sealant.

### **17-183-3C-63**

8/30/2017

Positive

4

CHRYSTILE

CH

Sample Collected 17-183-3C-63, Main Building, Classroom 1 (117), Interior Window Black and Gray Sealant.

### **17-183-3C-70**

8/30/2017

Negative

ND

NONE DETECTED

ND

Sample Collected 17-183-3C-70, Main Building, Classroom 14 (112), Interior Window Black and Gray Sealant.

### **17-183-3C-75**

8/30/2017

Positive

8

CHRYSTILE

CH

Sample Collected 17-183-3C-75, Main Building, Kindergarten 16 (102), Interior Window Gray Sealant.

### MAIN BUILDING

ENTIRE BUILDING IN DESIGNATED AREAS

SPRAY ON CEILING

### **10-019 CW-11**

2/2/2010

Positive

<1

CHRYSTILE

CH

### **10-019CW-01**

2/2/2010

Positive

<1

CHRYSTILE

CH

### **17-183 3C-14**

8/30/2017

Positive

2

CHRYSTILE

CH

Sample Collected 17-183 3C-14, Mezzanine, 203 Principal, Ceiling Acoustic Texture.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

ENTIRE FIRST LEVEL  
 BASEBOARD MASTIC

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-25</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-25, Main Building, Reception 154, 4" Baseboard Beige Mastic.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-37</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-37, Main Building, Multi-Purpose Room 144, 6" Baseboard Beige Mastic.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-54</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-54, Main Building, Classroom 5 (130), 6" Baseboard Beige Mastic.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-59</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-59, Main Building, Classroom 8 (124), 6" Baseboard Off-White Mastic.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-64</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-64, Main Building, Classroom 1 (117), 6" Baseboard Beige Mastic Only.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-71</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-71, Main Building, Classroom 14 (112), 6" Baseboard Beige Mastic Only.

|                                  |           |          |    |               |    |
|----------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-76-Beige</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-76-Beige Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard Beige and Brown Mastic Only.

|                                  |           |          |    |               |    |
|----------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-76-Brown</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-76-Brown Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard Beige and Brown Mastic Only.

### MAIN BUILDING

KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN  
 VINYL SHEETING

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-38</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-38, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-46</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-46, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-39</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-39, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-40</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-40, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting Adhesive.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-41</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-41, Main Building, Multi-Purpose Room 144, Floor Under Vinyl, White Compound.

|                                     |           |          |    |               |    |
|-------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-47-Adhesive</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|-------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-47-Paper Backing, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive.

|                                  |           |          |    |               |    |
|----------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-47-Paper</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-47-Paper Backing, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive.

### MAIN BUILDING

MULTI-PURPOSE ROOM

CEILING MASTIC

|                            |           |          |   |           |    |
|----------------------------|-----------|----------|---|-----------|----|
| <b><u>17-183-3C-34</u></b> | 8/30/2017 | Positive | 5 | CHRYSTOLE | CH |
|----------------------------|-----------|----------|---|-----------|----|

Sample Collected 17-183-3C-34, Main Building, Multi-Purpose Room 144, 4'X10' Tectum Ceiling Panel, Black Mastic.

### MAIN BUILDING

MULTI-PURPOSE ROOM

CEILING PANEL

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-33</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-33, Main Building, Multi-Purpose Room 144, 4'X10' Tectum Ceiling Panel.

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

GLUED TILES

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>08-241AAA</u></b> | 10/17/2008 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

### BUILDING NAME

### LOCATION

### MATERIAL TYPE

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>08-241AAA</u></b> | 10/17/2008 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE MASTIC

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>08-241AAA</u></b> | 10/17/2008 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

### MAIN BUILDING

MULTI-PURPOSE ROOM (OLD LIBRARY)

WALL TILE MASTIC

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>08-241AAA</u></b> | 10/17/2008 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

### MAIN BUILDING

OFFICES, WORKROOM, HALLWAY

SUSPENDED CEILING TILE

|                           |          |          |    |               |    |
|---------------------------|----------|----------|----|---------------|----|
| <b><u>10-019 CW17</u></b> | 2/2/2010 | Negative | ND | NONE DETECTED | ND |
|---------------------------|----------|----------|----|---------------|----|

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>10-174AAA</u></b> | 9/1/2010 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

### MAIN BUILDING

STAFF MENS RESTROOM, 2ND FLOOR SUPPLY ROOM, NURSES OFFICE, RESTROOM, TEACHERS LOUNGE, WOMENS RESTROOM, PRINCIPALS OFFICE, AND STORAGE ROOMS

BASEBOARD MASTIC

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-21</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-21, Mezzanine, 205 Nurses Wall, 4" Baseboard Brown Mastic.

### MAIN BUILDING

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>13-038AAA</u></b> | 4/5/2013 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-08</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183 3C-08, Mezzanine, 201 Computer Area, Floor Covering, Off-White Vinyl Sheeting.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING BACKING PAPER/MASTIC

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>13-038AAA</u></b> | 4/5/2013 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183 3C-09</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-09-Paper Backing, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Backing Paper Mastic. Sample Collected 17-183-3C-09-Mastic, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Backing Paper Mastic.

### MAIN BUILDING

STORAGE ROOMS

VINYL FLOOR TILE

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-27-Floor Tile</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-27-Floor Tile, Main Building, Teacher Work Area 157, 12" Beige Vinyl Floor Tile.

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-28-Floor Tile</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-28-Floor Tile, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-29</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-29, Main Building, Teacher Work Area 157, 12" Multi-Color Vinyl Floor Tile Black Mastic.

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-30-Floor Tile</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-30-Floor Tile, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile.

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-31-Floor Tile</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-31-Floor Tile, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile.

|                                       |           |          |    |               |    |
|---------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-32-Floor Tile</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|---------------------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-32-Floor Tile, Main Building, Teacher Work Area 157, 12" Gold Vinyl Floor Tile.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-44</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-44, Main Building, Storage 147, 12" Beige Vinyl Floor Tile.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-50</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-50, Main Building, Classroom 1 (135), Beige Vinyl Floor Tile.

|                            |           |          |    |               |    |
|----------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-56</u></b> | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
|----------------------------|-----------|----------|----|---------------|----|

Sample Collected 17-183-3C-56, Main Building, Classroom 5 (130), 12" Beige Vinyl Floor Tile.

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS                                                                                                                                      | DATE      | RESULT   | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|---------------------|------------------|------------------|
| <b><u>17-183-3C-61</u></b><br>Sample Collected 17-183-3C-61, Main Building, Classroom 8 (124), 12" Beige Vinyl Floor Tile.                                  | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-66</u></b><br>Sample Collected 17-183-3C-66, Main Building, Work Room (119), 12" Beige Vinyl Floor Tile.                                    | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-73</u></b><br>Sample Collected 17-183-3C-73, Main Building, Classroom 14 (112), 12" Beige Vinyl Floor Tile.                                 | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-77-Floor Tile</u></b><br>Sample Collected 17-183-3C-77-Floor Tile, Main Building, Kindergarten 16 (102), 12" Beige Vinyl Floor Tile.        | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-78-Floor Tile</u></b><br>Sample Collected 17-183-3C-78-Floor Tile, Main Building, Kindergarten 16 (102), 12" Light Gray Vinyl Floor Tile.   | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-79-Floor Tile</u></b><br>Sample Collected 17-183-3C-79-Floor Tile, Main Building, Kindergarten 16 (102), 12" Light Green Vinyl Floor Tile.  | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-80-Floor Tile</u></b><br>Sample Collected 17-183-3C-80-Floor Tile, Main Building, Kindergarten 16 (102), 12" Peach Orange Vinyl Floor Tile. | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-83-Floor Tile</u></b><br>Sample Collected 17-183-3C-83-Floor Tile, Main Building, Kindergarten 18 (103), 12" Gold Vinyl Floor Tile.         | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |

### MAIN BUILDING

STORAGE ROOMS  
VINYL FLOOR TILE MASTIC

|                                                                                                                                                          |           |          |    |               |    |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|----|---------------|----|
| <b><u>17-183-3C-27-Mastic</u></b><br>Sample Collected 17-183-3C-27-Mastic, Main Building, Teacher Work Area 157, 12" Beige Vinyl Floor Tile Mastic.      | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| <b><u>17-183-3C-28-Mastic</u></b><br>Sample Collected 17-183-3C-28-Mastic, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile Mastic.      | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| <b><u>17-183-3C-30-Mastic</u></b><br>Sample Collected 17-183-3C-30-Mastic, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile Mastic. | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| <b><u>17-183-3C-31-Mastic</u></b><br>Sample Collected 17-183-3C-31-Mastic, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile Mastic. | 8/30/2017 | Negative | ND | NONE DETECTED | ND |
| <b><u>17-183-3C-32-Mastic</u></b><br>Sample Collected 17-183-3C-32-Mastic, Main Building, Teacher Work Area 157, 12" Gold Vinyl Floor Tile.              | 8/30/2017 | Negative | ND | NONE DETECTED | ND |

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS                                                                                                                                     | DATE      | RESULT   | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------|---------------------|------------------|------------------|
| <b><u>17-183-3C-45</u></b><br>Sample Collected 17-183-3C-45, Main Building, Storage 147, 12" Beige Vinyl Floor Tile, Black Mastic.                         | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-51</u></b><br>Sample Collected 17-183-3C-51, Main Building, Classroom 1 (135), Beige Vinyl Floor Tile, Black Mastic.                       | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-57</u></b><br>Sample Collected 17-183-3C-57, Main Building, Classroom 5 (130), 12" Beige Vinyl Floor Tile Black Mastic.                    | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-62</u></b><br>Sample Collected 17-183-3C-62, Main Building, Classroom 8 (124), 12" Beige Vinyl Floor Tile, Black Mastic.                   | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-67</u></b><br>Sample Collected 17-183-3C-67, Main Building, Work Room (124), 12" Beige Vinyl Floor Tile, Black Mastic.                     | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-74</u></b><br>Sample Collected 17-183-3C-74, Main Building, Classroom 14 (112), 12" Beige Vinyl Floor Tile, Black Mastic.                  | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-77-Mastic</u></b><br>Sample Collected 17-183-3C-77-Mastic, Main Building, Kindergarten 16 (102), 12" Beige Vinyl Floor Tile, Black Mastic. | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-78-Mastic</u></b><br>Sample Collected 17-183-3C-78-Mastic, Main Building, Kindergarten 16 (102), 12" Light Gray Vinyl Floor Tile.          | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-79-Mastic</u></b><br>Sample Collected 17-183-3C-79-Mastic Main Building, Kindergarten 16 (102), 12" Light Green Vinyl Floor Tile.          | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-80-Mastic</u></b><br>Sample Collected 17-183-3C-80-Mastic, Main Building, Kindergarten 16 (102), 12" Peach Orange Vinyl Floor Tile.        | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-81</u></b><br>Sample Collected 17-183-3C-81, Main Building, Kindergarten 16 (102), 12" Multi-Color Vinyl Floor Tile, Black Mastic.         | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |
| <b><u>17-183-3C-83-Mastic</u></b><br>Sample Collected 17-183-3C-83-Mastic, Main Building, Kindergarten 18 (103), 12" Gold Vinyl Floor Tile.                | 8/30/2017 | Negative | ND                  | NONE DETECTED    | ND               |

### MAIN BUILDING

STUDENT RESTROOMS (2) (1ST FLOOR)  
CEMENTITIOUS WALL PANEL

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>12-185AAA</u></b> | 10/12/2012 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

# SAMPLES REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

### MAIN BUILDING

STUDENT RESTROOMS (2) (1ST FLOOR)

WALL MASTIC

|                         |            |          |         |           |    |
|-------------------------|------------|----------|---------|-----------|----|
| <b><u>12-185AAA</u></b> | 10/12/2012 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|------------|----------|---------|-----------|----|

### MAIN BUILDING

STUDENT RESTROOMS (2) (ON 1ST FLOOR)

MORTAR MISCELLANEOUS

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>09-212AAA</u></b> | 9/9/2009 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

### MAIN BUILDING

STUDENT RESTROOMS (2) (ON 1ST FLOOR)

VINYL WALL COVER

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>09-212AAA</u></b> | 9/9/2009 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

### MAIN BUILDING

STUDENT RESTROOMS (2) (ON 1ST FLOOR)

VINYL WALL COVER MASTIC

|                         |          |          |         |           |    |
|-------------------------|----------|----------|---------|-----------|----|
| <b><u>09-212AAA</u></b> | 9/9/2009 | Positive | ASSUMED | NO SAMPLE | NS |
|-------------------------|----------|----------|---------|-----------|----|

**SAMPLES REPORT FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

| <b>SAMPLE NO.</b> | <b>DATE</b> | <b>RESULT</b> | <b>ASBESTOS<br/>CONTENT</b> | <b>ASBESTOS<br/>NAME</b> | <b>ASBESTOS<br/>TYPE</b> |
|-------------------|-------------|---------------|-----------------------------|--------------------------|--------------------------|
| <b>COMMENTS</b>   |             |               |                             |                          |                          |

**METAL STORAGE CONTAINER**

**METAL STORAGE CONTAINER**

METAL STORAGE CONTAINER (1 EA)

STORAGE CONTAINER

**16-074.NS**

3/17/2016

Positive

ASSUMED

NO SAMPLE

NS

Metal Storage Structure.

**SAMPLES REPORT FOR**  
**CHERRYWOOD ELEMENTARY SCHOOL**

**BUILDING NAME**  
**LOCATION**  
**MATERIAL TYPE**

| SAMPLE NO.<br>COMMENTS | DATE | RESULT | ASBESTOS<br>CONTENT | ASBESTOS<br>NAME | ASBESTOS<br>TYPE |
|------------------------|------|--------|---------------------|------------------|------------------|
|------------------------|------|--------|---------------------|------------------|------------------|

**WOOD STORAGE SHED**  
**WOOD STORAGE SHED**

WOOD STORAGE SHED  
STORAGE BUILDING

|                  |           |          |              |           |    |
|------------------|-----------|----------|--------------|-----------|----|
| <b>23-026.NS</b> | 2/14/2023 | Negative | NEW MATERIAL | NO SAMPLE | NS |
|------------------|-----------|----------|--------------|-----------|----|

|  |                                  |  |
|--|----------------------------------|--|
|  | End Of Report, Total Of 18 Pages |  |
|--|----------------------------------|--|

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

### MAIN BUILDING

#### 2ND FLOOR

CARPET MASTIC

420 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                                                                                              |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive for Gray-Black Carpet. This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                   |
| 08/23/2006 | 20,000 SF of this Material Removed from First Level in all Classrooms, Offices, Common Areas, and Hallways and Replaced with new Mastic for Charcoal Colored Carpet as of this date. Quantity changed from 22,640 SF to 2,640 SF to reflect this fact. Location changed from Entire Building to 2nd Floor. No other changes as of this date. |
| 09/01/2010 | 8 SF of Carpet Removed; exposing the Mastic/Adhesive. Friability changed from Non-Friable to Friable. Damage <5% overall. No other changes as of this date.                                                                                                                                                                                  |
| 04/05/2013 | Material Condition Re-Assessed. Damages Repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                                                                                            |
| 09/12/2016 | Damage observed. Damage: <5% Physical Damage - 2 areas near Restrooms have Carpet removed; with some Mastic/Adhesive exposed. Material Condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.                                                                        |
| 03/28/2017 | Material Re-assessed. Quantity changed from 2,640 SF to 2624 SF. Removal of Carpet Mastic by Restrooms. No other changes as fo this date.                                                                                                                                                                                                    |
| 08/28/2017 | Additional Damage Observed. Hallway on the 2nd Floor now has half of the Carpet Wrikled or Loose. No other changes as of this date.                                                                                                                                                                                                          |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/17/2022 | Material Re-assessed. Quantity changed from 2,640 SF to 420 SF, Gray Black Carpet only found on stairs and Landing. No other chagnes as of this date.                                                                                                                                                                                        |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

ALL CLASSROOMS, AND MULTI-USE ROOM

WALL MASTIC

8,900 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                             |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive for 4'X8' Glued Wall Panels. This Material is in GOOD condition as of this date.                                                                                                                                                            |
| 08/23/2006 | Offices (Administration Section) added to Location. 4,500 SF added to quantity. Material Quantity changed from 11,200 SF to 15,700 SF to reflect this fact. No other changes as of this date.                                                               |
| 11/08/2007 | Material Re-Assessed. Damage Observed. <5% Physical Damage - due to approximately 1 SF cut and removed in 2nd Floor Hallway. Friability changed from Low to Moderate. Recommendation changed to reflect this fact. No other changes as of this date.        |
| 09/09/2009 | Material remains in FAIR condition overall with several holes, cuts and gouging. This Material is unchanged as of this date.                                                                                                                                |
| 09/01/2010 | Material Re-Assessed. Location changed from ALL CLASSROOMS, AND OFFICES (ADMINISTRATION SECTION) to ALL CLASSROOMS, AND MULTI-USE ROOM. Quantity changed from 15,700 SF to 8,900 SF. Panels are on the Walls and Ceiling. No other changes as of this date. |
| 09/12/2016 | Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                         |
| 08/28/2017 | Damage Observed. <5% Physical Damage - in the form of 3 Small Holes in the Wall Panel by the Ramp in the Hallway to MPR. Material Condition changed from GOOD to FAIR. Friability changed from NON to LOW. No other changes as of this date.                |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

ALL CLASSROOMS, AND MULTI-USE ROOM

WALL PANEL

8,900 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                             |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | 4'X8' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.                                                                                                                                                                            |
| 08/23/2006 | Offices (Administration Section) added to Location. 4,500 SF added to quantity. Material Quantity changed from 11,200 SF to 15,700 SF to reflect this fact. No other changes as of this date.                                                               |
| 11/08/2007 | Material Re-Assessed. Damage: <5% Physical Damage - due to approximately 1 SF cut and removed in 2nd Floor Hallway. Recommendation changed to reflect this fact. No other changes as of this date.                                                          |
| 09/09/2009 | Material remains in FAIR condition overall with several holes, cuts and gouging. This Material is unchanged as of this date.                                                                                                                                |
| 02/02/2010 | Samples 10-019 CW-07 and CW-10 collected on this date.                                                                                                                                                                                                      |
| 09/01/2010 | Material Re-Assessed. Location changed from ALL CLASSROOMS, AND OFFICES (ADMINISTRATION SECTION) to ALL CLASSROOMS, AND MULTI-USE ROOM. Quantity changed from 15,700 SF to 8,900 SF. Panels are on the Walls and Ceiling. No other changes as of this date. |
| 09/12/2016 | Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                         |
| 08/28/2017 | Damage Observed. <5% Physical Damage - in the form of 3 Small Holes in the Wall Panel by the Ramp located in the Hallway to MPR. Material Condition changed from GOOD to FAIR. No othe changes as of this date.                                             |
| 01/31/2020 | Repairs Observed. All Damage Repaired. Material Condition changed from FAIR to GOOD. Friability updated from Friable to Non-Friable. No other changes as of this date.                                                                                      |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                 |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P):<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING MASTIC

23,350 SF

P: Less Than 5%

W: <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                       |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Mastic/Adhesive FOR 1'X1' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.                                                                                                                                                                  |
| 08/23/2006 | Administration Offices added to Location. 2,000 SF added to quantity. Quantity changed from 21,350 SF to 23,350 SF to reflect this fact. No other changes as of this date.                                                                                            |
| 10/17/2008 | Room 4 has 5 Tiles Water Stained. Friability changed from Non-Friable to Friable to reflect this fact. No other changes as of this date.                                                                                                                              |
| 05/15/2009 | Mastic/Adhesive damaged and exposed where 1 Tile is missing in the 2nd FLOOR Staff Room. Water damage is still present. This Material is in FAIR condition as of this date.                                                                                           |
| 09/09/2009 | Material remains in <5% physical damage and <10% water damage. This Material is unchanged as of this date.                                                                                                                                                            |
| 02/02/2010 | Samples 10-019 CW-09 and 10-019 CW-16 collected on this date.                                                                                                                                                                                                         |
| 09/01/2010 | This Material is on the Walls and Ceiling. Room 5 has 10 Tiles missing, exposing the Mastic and Room 16 has 1 Tile missing, exposing the Mastic. No other changes as of this date.                                                                                    |
| 12/02/2011 | Additional Damage - in the form of Classroom 9 has 4 Tiles Water stained, and Classroom 4 has 8 Tiles Water Damaged. Previously noted Room 5 Damage with 10 Tiles missing has been Repaired. Material remains in FAIR condition as of this date.                      |
| 10/12/2012 | Additional Damage - in the form of Classroom 16 has 1 Tile missing and Mastic/Adhesive is exposed. No other changes as of this date.                                                                                                                                  |
| 04/05/2013 | Material condition Re-Assessed. Damaged Tiles in Classroom 09 have been Removed and Replaced with new Tiles. Material remains in FAIR condition overall as of this date.                                                                                              |
| 08/29/2014 | Material Re-Assessed. Classroom 2 has 1 Ceiling Tile Broken. Classroom 5 has 2 Ceiling Tiles Broken. No other changes as of this date.                                                                                                                                |
| 03/16/2015 | Classroom 1 has 1 Tile missing and Brown Mastic/Adhesive is exposed. No other changes as of this date.                                                                                                                                                                |
| 09/12/2016 | Additional Damage observed. Prep Room has 2 broken Tiles. Room 13 has 3 Tiles coming loose. No other changes as of this date.                                                                                                                                         |
| 03/28/2017 | Material Re-assessed. 75% of Material has been removed from Classroom 11, currently undergoing Construction.                                                                                                                                                          |
| 08/28/2017 | Additional Damage and Repairs Observed. Classroom 4 now has 7 Tiles with Water Damage. Staff Lounge (Located in the 2nd Floor) now has 1 Tile Missing. Mastic/Adhesive is exposed. All the Tiles in Classroom 11 have been Removed. No other changes as of this date. |
| 02/13/2018 | Material Re-assessed. All Tiles in Classroom 11 have been Replaced. Other Damage still present. No other changes as of this date.                                                                                                                                     |
| 08/08/2018 | Additional Damage Observed. 8 Tiles now have Water Damage in Classroom 4. Several Tiles have Chipped Corners in Classroom 1 and in Scattered Locations. No other changes as of this date.                                                                             |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|

|            |                                                                                                                                                                                                                                                        |  |  |  |  |  |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 08/27/2020 | Damage Observed. <5% Physical Damage in the form of 6 Tiles with Holes in Girls Restroom next to Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date. |  |  |  |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |  |

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOM AREAS, AND ADMINISTRATION OFFICES

CEILING TILE

23,350 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                           |  |  |  |  |  |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| 09/07/2005 | 1'X1' Glued-On Ceiling Tile. This Material is in GOOD condition as of this date.                                                                                                                                                          |  |  |  |  |  |
| 08/23/2006 | Administration Offices added to Location. 2,000 SF added to quantity. Quantity changed from 21,350 SF to 23,350 SF to reflect this fact. No other changes as of this date.                                                                |  |  |  |  |  |
| 10/17/2008 | Room 4 has 5 Tiles Water Stained. No other changes as of this date.                                                                                                                                                                       |  |  |  |  |  |
| 05/15/2009 | 1 Tile is missing in the 2nd FLOOR Staff Room. Water Damage is still present. This Material is in FAIR condition as of this date.                                                                                                         |  |  |  |  |  |
| 09/09/2009 | Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.                                                                                                                                |  |  |  |  |  |
| 02/02/2010 | Samples 10-019 CW-08 and 10-019 CW-15 collected on this date.                                                                                                                                                                             |  |  |  |  |  |
| 09/01/2010 | This Material is on the Walls and Ceiling. Room 5 has 10 Tiles missing, exposing the Mastic/Adhesive and Room 16 has 1 Tile missing, exposing the Mastic/Adhesive. No other changes as of this date.                                      |  |  |  |  |  |
| 12/02/2011 | Additional Damage - in the form of Classroom 9 has 4 Tiles Water stained, and Classroom 4 has 8 Tiles Water Damaged. Previously noted Room 5 with 10 Tiles missing has been repaired. Material remains in FAIR condition as of this date. |  |  |  |  |  |
| 10/12/2012 | Additional Damage - in the form of Classroom 16 has 1 Tile missing and Mastic is exposed. No other changes as of this date.                                                                                                               |  |  |  |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS                                                                                                                                                                                                                                                                                | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------------------|
| 04/05/2013    |          |               |                         | Material condition Re-Assessed. Damaged Tiles in Classroom 09 have been Removed and Replaced with new Tiles. Material remains in FAIR condition overall as of this date.                                                                                                                |                      |                                           |
| 03/04/2014    |          |               |                         | 1 Tile Broken in Classroom 15 and 3 Tiles have holes in Classroom 6. Friability changed from Low to High. No other changes as of this date.                                                                                                                                             |                      |                                           |
| 08/29/2014    |          |               |                         | Material Re-Assessed. Classroom 2 has 1 Broken Ceiling Tile. Classroom 5 has 2 Ceiling Tiles Broken. No other changes as of this date.                                                                                                                                                  |                      |                                           |
| 03/16/2015    |          |               |                         | Classroom 1 has 1 Tile missing and Brown Mastic/Adhesive is exposed. No other changes as of this date.                                                                                                                                                                                  |                      |                                           |
| 09/12/2016    |          |               |                         | Additional Damage observed. Prep Room has 2 broken Tiles. Room 13 has 3 Tiles coming loose. No other changes as of this date.                                                                                                                                                           |                      |                                           |
| 08/28/2017    |          |               |                         | Additional Damage and Repairs Observed. Classroom 4 now has 7 Tiles with Water Damage. Staff Lounge (Located in the 2nd Floor) now has 1 Tile Missing. Mastic/Adhesive is exposed. All the Tiles in Classroom 11 have been Removed. No other changes as of this date.                   |                      |                                           |
| 08/30/2017    |          |               |                         | Sample Colected 17-183 3C-05, Mezzanine, 201 Computer Area, 1'X'1 Ceiling Tile. Sample Collected 17-183 3C-06, Mezzanine, 201 Computer Area, 1'X'1 Ceiling Tile, Brown Mastic. Sample Colected 17-183 3C-07, Mezzanine, 201 Computer Area, (Under 1'X'1 Ceiling Tile) Acoustic Texture. |                      |                                           |
| 02/13/2018    |          |               |                         | Additional Damage Observed. 8 Tiles now have Water Damage in Classroom 4. Several Tiles have Chipped Corners in Classroom 1 and in Scattered Locations. No other changes as of this date.                                                                                               |                      |                                           |
| 01/31/2020    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 08/27/2020    |          |               |                         | Damage Observed. <5% Physical Damage in the form of 6 Tiles with Holes in Girls Restroom next to Classroom 11. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                                  |                      |                                           |
| 02/09/2021    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 08/10/2021    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 02/17/2022    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 08/16/2022    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 02/14/2023    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 08/15/2023    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 02/13/2024    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 08/13/2024    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |
| 02/26/2025    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                             |                      |                                           |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME           |               | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|-------------------------|---------------|----------------------|-------------------------------------------|
| LOCATION                | MATERIAL TYPE |                      |                                           |
| RISK ASSESMENT CATEGORY |               |                      |                                           |
| COMMENTS                |               |                      |                                           |

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE

VINYL FLOOR TILE

4,700 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/08/2018 | 12"x12" Off White, Beige and Gray Vinyl Floor Tile, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date.                                                                                                                    |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 Tile Missing in Corner Dark Brown Mastic Exposed in Lab Room 18. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |

### MAIN BUILDING

ALL CLASSROOMS, PREP ROOMS, STAFF LOUNGE, HALLWAYS, AND NURSE'S OFFICE

VINYL FLOOR TILE MASTIC

4,700 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/08/2018 | Mastic/Adhesive for 12"x12" Off White, Beige and Gray Vinyl Floor Tile, installed in 2018 Renovation Project. This Material is in GOOD condition as of this date.                                                                                                |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |
| 02/09/2021 | Damage Observed. <5% Physical Damage - in the form of 1 Tile Missing in Corner Dark Brown Mastic Exposed in Lab Room 18. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                      |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

|            |                                             |
|------------|---------------------------------------------|
| 02/17/2022 | This Material is unchanged as of this date. |
| 08/16/2022 | This Material is unchanged as of this date. |
| 02/14/2023 | This Material is unchanged as of this date. |
| 08/15/2023 | This Material is unchanged as of this date. |
| 02/13/2024 | This Material is unchanged as of this date. |
| 08/13/2024 | This Material is unchanged as of this date. |
| 02/26/2025 | This Material is unchanged as of this date. |

### MAIN BUILDING

#### CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER

11,000 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/01/2010 | Vinyl Wall Cover. This Material is in GOOD condition as of this date.                                                                                                                                                                          |
| 03/28/2017 | Damage Observed. <5% Physical Damage - in the form of 2 LF Separation at seam outside of Classroom 15. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |
| 08/28/2017 | Additional Damage Observed. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in Vinyl. No other changes as of this date.                                                                                                         |
| 08/30/2017 | Sample Collected 17-183-3C-19, Mezzanine, 208 Reception Wall, Vinyl Wall Covered Only.                                                                                                                                                         |
| 04/19/2019 | Construction Note: Material Re-assessed. Per Information Received 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.                     |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 02/09/2021 | Additional Damage Observed. 1 SF of Torn Vinyl on Upper Wall of Classroom 18. No other changes as of this date.                                                                                                                                |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                    |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                                    |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

### BUILDING NAME

### LOCATION

### MATERIAL TYPE

### RISK ASSESSMENT CATEGORY

### COMMENTS

QTY  
(APPROXIMATE)

PHYSICAL DAMAGE (P:)  
WATER DAMAGE (W:)

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

CLASSROOMS, MULTI-USE ROOM AND WORKROOM

VINYL WALL COVER MASTIC

11,000 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/01/2010 Mastic/Adhesive for Vinyl Wall Cover. This Material is in GOOD condition as of this date.

03/28/2017 Damage Observed. <5% Physical Damage - in the form of 2 LF Separation at seam outside of Classroom 15. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.

08/28/2017 Additional Damage Observed. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in Vinyl. No other changes as of this date.

08/30/2017 Sample Collected, 17-183-3C-20, Mezzanine, 205 Nurses Wall, Vinyl Wall Covered Adhesive only.

04/19/2019 Construction Note: Material Re-assessed. Per Information Received 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 Additional Damage Observed. 1 SF of Torn Vinyl on Upper Wall of Classroom 18. No other changes as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

#### ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

67,000 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                                    |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.                                                                                                                                                                                    |
| 03/08/2007 | Material Re-Assessed. Damage Observed. <5% Physical Damage - in the form of approximately 10-15 SF of Joint/Tape seam separation in Center Work Rooms of Classrooms 7-9. Friability changed from Low to Moderate. No other changes as of this date.                                |
| 02/02/2010 | Samples 10-019 CW-03, CW-13 and CW-19 (Joint Tape), CW-03, CW-13 and CW-19 (Joint Compound), and CW-04, CW-14 and CW-20 (Drywall) collected on this date.                                                                                                                          |
| 09/01/2010 | Additional Damage observed. 10 SF Damaged at patched area in Room 5. No other changes as of this date.                                                                                                                                                                             |
| 12/02/2011 | Additional Damage - in the form of Teachers Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.                                                                                                                             |
| 10/12/2012 | Material condition Re-Assessed. Due to Water Leak, new Material installed in Hallway, Located between Boys' Restroom and ESL Room, and approximately 144 SF of Ceiling Material Removed and Replaced. No other changes as of this date.                                            |
| 08/29/2014 | Teacher's Work Room by Classroom 3-5 has <10% Water Damage - in the form of 5 SF of Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 by the Light Wall Board System is Damaged. No other changes as of this date.                                        |
| 03/16/2015 | Additional Damage observed. 2 SF hole on Ceiling of 1st Floor Storage Room by Elevator. No other changes as of this date.                                                                                                                                                          |
| 09/12/2016 | Additional Damage observed and Partial Repairs observed. Closet by Office has 2 LF of Physical Damage on the wall due to torn Skimcoat. Damages noted on 08/29/14 have been Repaired. No other changes as of this date.                                                            |
| 08/28/2017 | Additional Damage Observed. 1 SF of Physical Damage in the form of a Hole in the Hallway near the Girls Restroom. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in the Wall. No other changes as of this date.                                                    |
| 08/30/2017 | Sample Collected 17-183-3C-11, Mezzanine, 202 Conference, Wall Joint Tape and Mud (for Gypsum Wallboard). Sample Collected 17-183-3C-11, Mezzanine, 202 Conference, Wall Gypsum Board. Sample Collected 17-183-3C-36, Main Building, Multi-Purpose Room 144, Ceiling Gypsum Board. |
| 04/19/2019 | Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.                                                                             |
| 01/31/2020 | Additional Damage Observed. 2 SF of Water Damage and are Cracks in Classroom 15. No other changes as of this date.                                                                                                                                                                 |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                        |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME            |               | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|--------------------------|---------------|----------------------|-------------------------------------------|
| LOCATION                 | MATERIAL TYPE |                      |                                           |
| RISK ASSESSMENT CATEGORY |               |                      |                                           |
| COMMENTS                 |               |                      |                                           |

|            |                                                                                                                                                                                                                               |  |  |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 02/17/2022 | Additional Damage Observed. 8 SF of Water Stain in Classroom 15 Work Room. No other changes as of this date.                                                                                                                  |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                   |  |  |
| 02/14/2023 | Additional Damage Observed. 1 SF of Missing Drywall in Book Room. 1 SF of Scuffs and Missing Skim Coat with Drywall Board Exposed in Storage Closet next to LSH Room in Multi-Purpose Room. No other changes as of this date. |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                   |  |  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                   |  |  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                   |  |  |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                   |  |  |

### MAIN BUILDING

#### ENTIRE BUILDING

|                       |           |                                                 |
|-----------------------|-----------|-------------------------------------------------|
| SMOOTH WALL SURFACING | 62,760 SF | <b>P:</b> Less Than 5%<br><b>W:</b> No Evidence |
|-----------------------|-----------|-------------------------------------------------|

#### DAMAGED FRIABLE SURFACING ACM

|            |                                                                                                                                                                                                                                             |  |  |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| 08/23/2006 | Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.                                                                                                                               |  |  |
| 03/08/2007 | Material Re-Assessed. Damage: <5% Physical Damage - in the form of approximately 10-15 SF of Joint/Tape seam separation in Center Work Rooms of Classrooms 7-9. Friability changed from Low to Moderate. No other changes as of this date.  |  |  |
| 02/02/2010 | Samples 10-019 CW-12 and CW-18 collected on this date.                                                                                                                                                                                      |  |  |
| 09/01/2010 | Additional Damage observed. 10 SF Damaged at patched area in Room 5. No other changes as of this date.                                                                                                                                      |  |  |
| 12/02/2011 | Additional Damage - in the form of Teachers Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.                                                                                      |  |  |
| 10/12/2012 | Material condition Re-Assessed. Due to Water Leak, new Material installed in Hallway, Located between Boys' Restroom and ESL Room, and approximately 144 SF of Ceiling Material Removed and Replaced. No other changes as of this date.     |  |  |
| 08/29/2014 | Teacher's Work Room by Classroom 3-5 has <10% Water Damage - in the form of 5 SF of Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 by the Light Wall Board System is Damaged. No other changes as of this date. |  |  |
| 03/16/2015 | Quantity changed from 67,000 SF to 62,760 SF. No other changes as of this date.                                                                                                                                                             |  |  |
| 09/12/2016 | Additional Damage observed and Partial Repairs observed. Closet by Office has 2 LF of Physical Damage on the wall due to torn Skimcoat. Damages noted on 08/29/14 have been Repaired. No other changes as of this date.                     |  |  |
| 08/28/2017 | Additional Damage Observed. 1 SF of Physical Damage in the form of a Hole in the Hallway near the Girls Restroom. Classroom 10 has 1 SF of Physical Damage in the form of a Hole in the Wall. No other changes as of this date.             |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION                                                                                                                                                                                                                       | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
| 08/30/2017    | Sample Collected 17-183-3C-10, Mezzanine, 202 Conference, Wall Skimcoat and Paint (for Gypsum Wallboard). Sample Collected 17-183-3C-35, Main Building, Multi-Purpose Room 144, Ceiling Joint Tape and Mud (For Gypsum Board). |               |                         |          |                      |                                           |
| 04/19/2019    | Material Re-assessed. Per Information Recived 7,494 SF of Drywall has been Removed from the Mezzanine and Work Area. New Drywall has been installed at a later date. No other changes as of this date.                         |               |                         |          |                      |                                           |
| 01/31/2020    | Additional Damage Observed. 2 SF of Water Damage and are Cracks in Classroom 15. No other changes as of this date.                                                                                                             |               |                         |          |                      |                                           |
| 08/27/2020    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 02/09/2021    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 08/10/2021    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 02/17/2022    | Additional Damage Observed. 8 SF of Water Stain in Classroom 15 Work Room. No other changes as of this date.                                                                                                                   |               |                         |          |                      |                                           |
| 08/16/2022    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 02/14/2023    | Additional Damage Observed. 1 SF of Missing Drywall in Book Room. 1 SF of Scuffs and Missing Skim Coat with Drywall Board Exposed in Storage Closet next to LSH Room in Multi-Purpose Room. No other changes as of this date.  |               |                         |          |                      |                                           |
| 08/15/2023    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 02/13/2024    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 08/13/2024    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |
| 02/26/2025    | This Material is unchanged as of this date.                                                                                                                                                                                    |               |                         |          |                      |                                           |

### MAIN BUILDING

#### ENTIRE BUILDING IN DESIGNATED AREAS

|                  |          |                                              |
|------------------|----------|----------------------------------------------|
| SPRAY ON CEILING | 3,840 SF | P: Less Than 5%<br>W: <10% Stains or Flaking |
|------------------|----------|----------------------------------------------|

#### DAMAGED FRIABLE SURFACING ACM

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |  |  |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|
| 09/07/2005 | Spray-On Ceiling. This Material is in GOOD condition as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |  |  |  |  |
| 11/08/2007 | Material is Located in KITCHEN, PREP ROOMS (2), ENTRY AREAS (2), COMPUTER LAB, ENTRY COMMON AREA, ROOMS 15-16, PREP ROOMS, STAGE, LIBRARY, MPR ENTRY AREA, 2ND FLOOR ELEV. EQUIP. ROOM, CUSTODIAL ROOM, AND PRINCIPALS OFFICE. Entry Areas (2) added to Pod 07-09 and Pod 13-15. Material Quantity changed from 3,790 SF to 4,390 SF. Material Re-Assessed. Damage: <5% Physical Damage - in the form of approximately 4 SF of separation; Water Damage - 25 SF noticed in Pod 07-09. Friability changed from Low to Moderate. No other changes as of this date. |  |  |  |  |
| 05/15/2009 | Additional Damage observed. A 4" cut observed in the Storage Room next to the Elevator Equipment Room and Water Damage observed in Pod 1-5. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                    |  |  |  |  |
| 02/02/2010 | Samples 10-019 CW-01 and CW-11 collected on this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |  |  |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME           |                                                                                                                                                                                                                                                                             | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------------------|
| LOCATION                | MATERIAL TYPE                                                                                                                                                                                                                                                               |                      |                                           |
| RISK ASSESMENT CATEGORY |                                                                                                                                                                                                                                                                             |                      |                                           |
| COMMENTS                |                                                                                                                                                                                                                                                                             |                      |                                           |
| 09/01/2010              | This Material is also visible above the Ceiling Tiles in Classroom 5. This Material is unchanged as of this date.                                                                                                                                                           |                      |                                           |
| 12/02/2011              | Additional Damage - in the form of Teacher's Work Room of Classrooms 9 and 11 have approximately 10 LF of separation. No other changes as of this date.                                                                                                                     |                      |                                           |
| 10/12/2012              | Material condition Re-Assessed. Approximately 150 SF of Material has been Removed, due to Water Leak, in Hallway, located between Boys Restroom and ESL Room. New Drywall has been installed. Quantity changed from 4,390 SF to 4,240 SF. No other changes as of this date. |                      |                                           |
| 09/27/2013              | Material Re-Assessed. Material changed from GOOD to FAIR condition. No other changes as of this date.                                                                                                                                                                       |                      |                                           |
| 08/29/2014              | Teacher's Work Room by Classrooms 3-5 has Water Damage. The Multi-Purpose Area Ceiling Outside Classrooms 1, 3, 4, 5 has 2 SF of Damage. No other changes as of this date.                                                                                                  |                      |                                           |
| 03/16/2015              | Additional Damage observed. 2 SF hole on Ceiling of 1st Floor Stroage Room by Elevator. No other changes as of this date.                                                                                                                                                   |                      |                                           |
| 03/28/2017              | Material Re-assessed. Quantity changed from 4,240 SF to 3,840 SF based on Material Removed from Workroom between Classrooms 9 and 11. No other changes as fo this date                                                                                                      |                      |                                           |
| 08/28/2017              | Partial Repairs Observed. Water Damage by the Teacher's Work Room has been Repaired. Hole in the Ceiling of the Storage Room (Located in the First Floor) has been Repaired. Material remains in FAIR condition as of this date.                                            |                      |                                           |
| 08/30/2017              | Sample Collected 17-183 3C-14, Mezzanine, 203 Principal, Ceiling Acoustic Texture.                                                                                                                                                                                          |                      |                                           |
| 01/31/2020              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 08/27/2020              | Additional Damage Observed. <10% Water Damage in the form of 6 SF of Water Stains in Work Room of Classroom 17. Material remains in FAIR condition overall. No other changes as of this date.                                                                               |                      |                                           |
| 02/09/2021              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 08/10/2021              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 02/17/2022              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 08/16/2022              | Additional Damage Observed. <5% Physical Damage in the form of 2 LF Crack and Loose Ceiling Texture in Work Room of Classroom 17. Material remains in FAIR condition overall. No other changes as of this date.                                                             |                      |                                           |
| 02/14/2023              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 08/15/2023              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 02/13/2024              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 08/13/2024              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |
| 02/26/2025              | This Material is unchanged as of this date.                                                                                                                                                                                                                                 |                      |                                           |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|--------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

#### ENTIRE FIRST LEVEL

#### BASEBOARD MASTIC

3,850 LF

P: Less Than 5%

W: <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/23/2006 | Mastic/Adhesive for 4" and 6" Brown Baseboards (Apparent New Material identified by the AHERA Accredited Inspector). Mastic is Beige. This Material is in GOOD condition as of this date (Original entry updated on 05/15/09).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 05/15/2009 | Baseboards are Brown. Original entry updated. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 10/12/2012 | Damage Observed. <5% Physical Damage and <10% Water Damage - due to Water Leak on Second Floor, First Floor Damage in Hallway, located between Boys Restroom and ESL Room. Mastic/Adhesive is exposed. Material condition changed from GOOD to FAIR overall. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 09/17/2015 | Additional Damage observed and New Material installed. Classroom 1 has 3 LF of Baseboard missing. Classroom 1 has 6" Black Baseboard Installed, (Old Material may be behind New Material). No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| 03/17/2016 | Partial Repairs made and Additional Damage observed. Damage in Hallway has been Repaired. Additional Damage observed in the form of 3 LF of Baseboard missing in Cafeteria exposing Mastic/Adhesive. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 08/28/2017 | Additional Damages and Partial Repairs Observed. 3 LF of Baseboard Missing in the Cafeteria have been Repaired. Classroom 13 has 1 SF of Physical Damage in the form of Broken Baseboard. Multi-Purpose Room has 1 SF of Physical Damage in the form of Broken Baseboard. Material remains in FAIR condition as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 08/30/2017 | Sample Collected 17-183-3C-25, Main Building, Reception 154, 4" Baseboard Beige Mastic. Sample Collected 17-183-3C-37, Main Building, Multi-Purpose Room 144, 6" Baseboard Beige Mastic. Sample Collected 17-183-3C-54, Main Building, Classroom 5 (130), 6" Baseboard Beige Mastic. Sample Collected 17-183-3C-59, Main Building, Classroom 8 (124), 6" Baseboard Off-White Mastic. Sample Collected 17-183-3C-64, Main Building, Classroom 1 (117), 6" Baseboard Beige Mastic Only. Sample Collected 17-183-3C-71, Main Building, Classroom 14 (112), 6" Baseboard Beige Mastic Only. Sample Collected 17-183-3C-76-Beige Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard Beige and Brown Mastic Only. Sample Collected 17-183-3C-76-Brown Mastic, Main Building, Kindergarten 16 (102), 6" Baseboard |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

#### EXTERIOR WALLS AND OVERHANG

|            |           |                                                 |
|------------|-----------|-------------------------------------------------|
| ROUGH WALL | 15,000 SF | <b>P:</b> Less Than 5%<br><b>W:</b> No Evidence |
|------------|-----------|-------------------------------------------------|

#### DAMAGED FRIABLE SURFACING ACM

09/07/2005 Stucco Walls and Overhang. This Material is in GOOD condition as of this date.

08/13/2019 Damages Observed. <5% Physical Damage in the form of 1 SF of Holes on the Overhang by Entry to Classroom 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.

01/31/2020 This Material is unchanged as of this date.

08/27/2020 This Material is unchanged as of this date.

02/09/2021 Damage Observed. <5% Physical Damage - in the form of 1 SF of Missing Stucco and Paint on South Wall next to Girls Restroom Entry. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

08/10/2021 This Material is unchanged as of this date.

02/17/2022 This Material is unchanged as of this date.

08/16/2022 This Material is unchanged as of this date.

02/14/2023 This Material is unchanged as of this date.

08/15/2023 This Material is unchanged as of this date.

02/13/2024 This Material is unchanged as of this date.

08/13/2024 This Material is unchanged as of this date.

02/26/2025 This Material is unchanged as of this date.

### MAIN BUILDING

#### EXTERIOR WALLS AND OVERHANG

|                      |           |                                                 |
|----------------------|-----------|-------------------------------------------------|
| ROUGH WALL SURFACING | 15,000 SF | <b>P:</b> Less Than 5%<br><b>W:</b> No Evidence |
|----------------------|-----------|-------------------------------------------------|

#### DAMAGED FRIABLE SURFACING ACM

09/07/2005 Skim Coat for Stucco Walls and Overhang. This Material is in GOOD condition as of this date.

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS                                                                                                                                                                                                                                                                   | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------------------|
| 08/13/2019    |          |               |                          | Damages Observed. <5% Physical Damage in the form of 1 SF of Holes on the Overhang by Entry to Classroom 2. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.                        |                      |                                           |
| 01/31/2020    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 08/27/2020    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 02/09/2021    |          |               |                          | Damage Observed. <5% Physical Damage - in the form of 1 SF of Missing Stucco and Paint on South Wall next to Girls Restroom Entry. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |                      |                                           |
| 08/10/2021    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 02/17/2022    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 08/16/2022    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 02/14/2023    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 08/15/2023    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 02/13/2024    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 08/13/2024    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |
| 02/26/2025    |          |               |                          | This Material is unchanged as of this date.                                                                                                                                                                                                                                |                      |                                           |

### MAIN BUILDING

KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

384 SF

**P:** No Visible Damage

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                                                                                                            |  |  |  |  |  |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| 08/23/2006 | <b>Mastic/Adhesive for 12"x12" White, Grey, Blue and Begie. (2/13/2024 Updated Entry Vinyl Floor Tile Backing Paper/adhesive for Beige Vinyl Sheeting) (Apparent New Material identified by the AHERA Accredited Inspector). This Material is in GOOD condition as of this date.</b>                                                                       |  |  |  |  |  |
| 10/17/2008 | Location Description changed from KITCHEN, AND CAFETERIA to KITCHEN, CAFETERIA, AND OLD LIBRARY KITCHEN. Material Quantity changed from 1,400 SF to 1,600 SF to reflect this fact. No other changes as of this date.                                                                                                                                       |  |  |  |  |  |
| 10/12/2012 | Damage: <10% Water Damage - in the form of approximately 144 SF of Material Removed in Hallway, located between Boys' Restroom and ESL Room. Damage due to Water Leak. Quantity changed from 1,600 SF to 1,456 SF. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |  |  |  |  |  |
| 04/05/2013 | Material Condition Re-Assessed. Damages Repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                                                                                                          |  |  |  |  |  |
| 09/17/2015 | Damage observed. Cafeteria has <5% Physical Damage- in the form of 2 LF Damage. Material condition changed from GOOD to FAIR overall. Friability changed from Moderate to High. No other changes as of this date.                                                                                                                                          |  |  |  |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | MATERIAL TYPE | RISK ASSESSMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--------------------------|----------|----------------------|-------------------------------------------|
| 08/30/2017    | Sample Collected 17-183-3C-39, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting Backing Paper. Sample Collected 17-183-3C-40, Main Building, Multi-Purpose Room 144, Floor Beige Vinyl Sheeting Adhesive. Sample Collected 17-183-3C-41, Main Building, Multi-Purpose Room 144, Floor Under Vinyl, White Compound. Sample Collected 17-183-3C-47-Paper Backing, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive. Sample Collected 17-183-3C-47-Adhesive, Main Building, Lunch Serving Area 118, Floor Beige Vinyl Sheeting Paper and Adhesive. |               |                          |          |                      |                                           |
| 08/08/2018    | Material Re-assessed. Quantity changed from 1,456 SF to 384 SF of old Vinyl Floor Tiles Remaining in Kitchen. Location discription changed from KITCHEN, CAFETERIA , AND OLD LIBRARY KITCHEN to KITCHEN. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                           |               |                          |          |                      |                                           |
| 01/31/2020    | Repairs observed. Damages repaired as of this date. Material Condition changed from FAIR to GOOD. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |               |                          |          |                      |                                           |
| 08/27/2020    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 02/09/2021    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 08/10/2021    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 02/17/2022    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 08/16/2022    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 02/14/2023    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 08/15/2023    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 02/13/2024    | Material Re-assessed. Material Replaced now 12"x12" White, Grey, Blue and Begie Vinyl Floor Tile. Mastic/Adheisve may still Exist Underneath material. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                             |               |                          |          |                      |                                           |
| 08/13/2024    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |
| 02/26/2025    | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |               |                          |          |                      |                                           |

### MAIN BUILDING

STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

VINYL SHEETING

385 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                              |  |  |  |  |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|
| 04/05/2013 | Beige and White Vinyl Floor Sheeting. This Material is in GOOD condition as of this date (Original Entry updated on 03/04/14).                                                                                                               |  |  |  |  |
| 03/04/2014 | Vinyl Sheeting is Beige and White. Original entry updated. No other changes as of this date.                                                                                                                                                 |  |  |  |  |
| 03/28/2017 | Damage Observed. <10% Water Damage - in the form of 2 SF Water Stains in 2nd Floor Teacher's Lounge. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date. |  |  |  |  |
| 08/30/2017 | Sample Collected 17-183 3C-08, Mezzanine, 201 Computer Area, Floor Covering, Off-White Vinyl Sheeting.                                                                                                                                       |  |  |  |  |
| 01/31/2020 | Material Re-assessed. 215 SF of Vinyl Floor Tile has been Removed. Quantity changed from 600 SF to 385 SF. No other chagnes as of this date.                                                                                                 |  |  |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:) WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|----------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|----------------------------------------|

|            |                                                                                                                                                         |  |  |  |  |  |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                             |  |  |  |  |  |
| 02/26/2025 | Material Re-assessed. Material Only Observed in Storage Room. Material may Exist under new Floor Tile in Other Areas. No other changes as of this date. |  |  |  |  |  |

### MAIN BUILDING

#### STORAGE ROOM (HALLWAY (1ST FLOOR), TEACHERS' LOUNGE ROOM (2ND FLOOR))

|                                     |        |                                                   |
|-------------------------------------|--------|---------------------------------------------------|
| VINYL SHEETING BACKING PAPER/MASTIC | 385 SF | P: No Visible Damage<br>W: <10% Stains or Flaking |
|-------------------------------------|--------|---------------------------------------------------|

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                        |  |  |  |  |
|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|
| 04/05/2013 | Backing Paper/Adhesive for Beige and White Vinyl Floor Sheeting. This Material is in GOOD condition as of this date. (Original Entry updated on 03/04/14.)                                                                                             |  |  |  |  |
| 03/04/2014 | Vinyl Sheeting is Beige and White. Friability changed from Non-Friable to Friable. Original entry updated. No other changes as of this date.                                                                                                           |  |  |  |  |
| 03/28/2017 | Damage Observed. <10% Water Damage - in the form of 2 SF Water Stains in 2nd Floor Teacher's Lounge. Material condition changed from GOOD to FAIR overall. Friability changed from Moderate to High. No other changes as of this date.                 |  |  |  |  |
| 08/30/2017 | Sample Collected 17-183-09-Paper Backing, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Backing Paper Mastic. Sample Collected 17-183-09-Mastic, Mezzanine, 201 Computer Area, Floor Covering Off-White Vinyl Sheeting Mastic. |  |  |  |  |
| 01/31/2020 | Material Re-assessed. 215 SF of Vinyl Floor Tile has been Removed. Quantity changed from 600 SF to 385 SF. No other changes as of this date.                                                                                                           |  |  |  |  |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                                            |  |  |  |  |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

### BUILDING NAME

### LOCATION

### MATERIAL TYPE

### RISK ASSESSMENT CATEGORY

### COMMENTS

QTY  
(APPROXIMATE)

PHYSICAL DAMAGE (P:)   
WATER DAMAGE (W:)

|            |                                                                                                                                                         |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                             |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                             |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                             |
| 02/26/2025 | Material Re-assessed. Material Only Observed in Storage Room. Material may Exist under new Floor Tile in Other Areas. No other changes as of this date. |

### MAIN BUILDING

STORAGE ROOM NEXT TO RESTROOM, MULTI-PURPOSE ROOM, ELEVATOR EQUIPMENT ROOM, PRINCIPALS OFFICE, AND NURSES ROOM

FIRE DOOR CORE INSULATION

252 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                   |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| 09/07/2005 | Fire Door Core Insulation (12 EA FIRE DOORS). This Material is in GOOD condition as of this date.                                                 |
| 02/05/2019 | Material Re-assessed. 2nd Floor Elevator Mechanical Room Door Nob is Missing, White Core Insulation is Exposed. No other changes as of this date. |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                       |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                       |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                       |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                       |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                       |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                       |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                       |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                       |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                       |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                       |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                       |

### MAIN BUILDING

STORAGE ROOMS

VINYL FLOOR TILE

275 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                               |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/23/2006 | 12"X12" Multi-Colored (Beige, Peach Orange, Green and Light Gray) Vinyl Floor Tile (Apparent New Material identified by the AHERA Accredited Inspector). Mastic in Black. This Material is in good condition as of this date (Original Entry Update 8/30/17). |
|------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|---------------|----------|---------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|               |          |               | QTY<br>(APPROXIMATE)    | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| 12/02/2011    |          |               |                         | Damage Observed. <5% Physical Damage - in the form of Music Storage Room has 8 Tiles broken and Mastic is exposed. Material condition changed from GOOD to FAIR. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| 10/12/2012    |          |               |                         | Additional Damage: <10% Water Damage - in the form of Water Leak observed on 2nd Floor, and Vinyl Floor Tile removed in ESL Room. Mastic/Adhesive is exposed. Material is present under electrical switchboard. Quantity changed from 4,600 SF to 4,475 SF. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 09/27/2013    |          |               |                         | Friability changed from Moderate to Low. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 08/29/2014    |          |               |                         | Material Re-Assessed. Storage Room next to Office has 1 Vinyl Floor Tile Missing and 1 is Loose. Black Mastic/Adhesive is exposed. Classroom 13 has 2 Vinyl Floor Tile Damage. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| 08/28/2017    |          |               |                         | Additional Damage Observed. Staff Lounge now has 2 Broken Tiles. Mastic/Adhesive is Exposed. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 08/30/2017    |          |               |                         | Material Description changed from '12"X12" Cream Vinyl Floor Tile' to '12"X12" Multi-Colored (Beige, Green and Light Gray) Vinyl Floor Tile'. No other changes as of this date. Sample Collected 17-183-3C-27-Floor Tile, Main Building, Teacher Work Area 157, 12" Beige Vinyl Floor Tile. Sample Collected 17-183-3C-28-Floor Tile, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile. Sample Collected 17-183-3C-29, Main Building, Teacher Work Area 157, 12" Multi-Color Vinyl Floor Tile. Sample Collected 17-183-3C-30-Floor Tile, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile. Sample Collected 17-183-3C-31-Floor Tile, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile. Sample Collected 17-183-3C-32-Floor Tile, Main Building, Teacher Work Area 157, 12" Gold |
| 08/08/2018    |          |               |                         | Material Re-assessed. Only the Stroage Rooms now have old Multi-Colored Vinyl Floor Tiles. Every other Location has been Replaced. Quantity changed from 4,475 SF to 275 SF. Location changed from ALL CLASSROOMS, SINK AND ENTRY AREAS, STORAGE ROOMS, PREP ROOMS, HALLWAYS, AND NEW ADMINISTRATION OFFICES to STORAGE ROOMS.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 01/31/2020    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 08/27/2020    |          |               |                         | Additional Damage Observed. <10% Water Damage in the form of 3 Tiles with Water Stains in Custodian Room (Storage Room # 149). Material remains in FAIR condition overall. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 02/09/2021    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 08/10/2021    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 02/17/2022    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 08/16/2022    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 02/14/2023    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 08/15/2023    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 02/13/2024    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 08/13/2024    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 02/26/2025    |          |               |                         | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

#### STORAGE ROOMS

VINYL FLOOR TILE MASTIC

275 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 08/23/2006 | Mastic/Adhesive for 12"X12" Multi-Colored (Beige, Peach Orange, Green and Light Gray) Vinyl Floor Tile (Apparent New Material identified by the AHERA Accredited Inspector). Mastic is Black. This Material is in good condition as of this date (Original Entry Updated on 8/30/2017).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| 03/08/2007 | This Material unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 12/02/2011 | Damage: <5% Physical Damage - in the form of Music Storage Room has 8 Tiles broken and Mastic is exposed. Material condition changed from GOOD to FAIR. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 10/12/2012 | Additional Damage: <10% Water Damage - in the form of Water Leak observed on 2nd Floor, and Vinyl Floor Tile removed in ESL Room. Mastic/Adhesive is exposed. Material is present under electrical switchboard. Quantity changed from 4,600 SF to 4,475 SF. Friability changed from Low to Moderate. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| 09/27/2013 | Friability changed from Moderate to Low. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| 08/29/2014 | Material Re-Assessed. Storage Room next to Office has 1 Vinyl Floor Tile Missing and 1 is Loose. Black Mastic/Adhesive is exposed. Classroom 13 has 2 Vinyl Floor Tile Damage. No other changes as of this date..                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| 08/28/2017 | Additional Damage Observed. Staff Lounge now has 2 Broken Tiles. Mastic/Adhesive is Exposed. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 08/30/2017 | Material Description changed from 'Mastic/Adhesive for 12"X12" Cream Vinyl Floor Tile' to 'Mastic/Adhesive for 12"X12" Multi-Colored (Beige, Green and Light Gray) Vinyl Floor Tile'. Sample Collected 17-183-3C-27-Mastic, Main Building, Teacher Work Area 157, 12" Green Vinyl Floor Tile Mastic. Sample Collected 17-183-3C-30-Mastic, Main Building, Teacher Work Area 157, 12" Light Gray Vinyl Floor Tile Mastic Sample Collected 17-183-3C-31-Mastic, Main Building, Teacher Work Area 157, 12" Gray Black Vinyl Floor Tile Mastic. Sample Collected 17-183-3C-32-Mastic, Main Building, Teacher Work Area 157, 12" Gold Vinyl Floor Tile. Sample Collected 17-183-3C-45, Main Building, Storage 147, 12" Beige Vinyl Floor Tile Black Mastic. Sample Collected 17-183-3C-51 Main Building Classroom 1 (135) Beige Vinyl Floor |
| 08/08/2018 | Material Re-assessed. Only the Stroage Rooms now have old Multi-Colored Vinyl Floor Tiles. Every other Location has been Replaced. Quantity changed from 4,475 SF to 275 SF. Location changed from ALL CLASSROOMS, SINK AND ENTRY AREAS, STORAGE ROOMS, PREP ROOMS, HALLWAYS, AND NEW ADMINISTRATION OFFICES to STORAGE ROOMS.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 08/27/2020 | Additional Damage Observed. <10% Water Damage in the form of 3 Tiles with Water Stains in Custodian Room (Storage Room # 149). Material remains in FAIR condition overall. No other changes as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

**BUILDING NAME****LOCATION****MATERIAL TYPE****RISK ASSESMENT CATEGORY****COMMENTS****QTY**  
**(APPROXIMATE)****PHYSICAL DAMAGE (P:)**  
**WATER DAMAGE (W:)**

08/16/2022 This Material is unchanged as of this date.  
02/14/2023 This Material is unchanged as of this date.  
08/15/2023 This Material is unchanged as of this date.  
02/13/2024 This Material is unchanged as of this date.  
08/13/2024 This Material is unchanged as of this date.  
02/26/2025 This Material is unchanged as of this date.

**MAIN BUILDING****STUDENT RESTROOMS (2) (1ST FLOOR)**

CEMENTITIOUS WALL PANEL

1,650 SF

**P:** Less Than 5%**W:** No Evidence**DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM**

10/12/2012 Cementitious Wall Panel. Damage Observed. <5% Physical Damage - in the form of 2 panels are broken in Boys Restroom, due to Removal of Vinyl Wall Panel. Material is in FAIR condition as of this date.  
04/05/2013 Material condition Re-Assessed. Damaged section of Material may exist under 4'x8' Vinyl Wall Panel. This Material is unchanged as of this date.  
01/31/2020 This Material is unchanged as of this date.  
08/27/2020 This Material is unchanged as of this date.  
02/09/2021 This Material is unchanged as of this date.  
08/10/2021 This Material is unchanged as of this date.  
02/17/2022 This Material is unchanged as of this date.  
08/16/2022 This Material is unchanged as of this date.  
02/14/2023 This Material is unchanged as of this date.  
08/15/2023 This Material is unchanged as of this date.  
02/13/2024 This Material is unchanged as of this date.  
08/13/2024 This Material is unchanged as of this date.  
02/26/2025 This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## CHERRYWOOD ELEMENTARY SCHOOL

| BUILDING NAME | LOCATION | MATERIAL TYPE | RISK ASSESMENT CATEGORY | COMMENTS | QTY<br>(APPROXIMATE) | PHYSICAL DAMAGE (P:)<br>WATER DAMAGE (W:) |
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|
|---------------|----------|---------------|-------------------------|----------|----------------------|-------------------------------------------|

### MAIN BUILDING

#### STUDENT RESTROOMS (2) (1ST FLOOR)

WALL MASTIC

1,650 SF

**P:** Less Than 5%

**W:** No Evidence


#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

|            |                                                                                                                                                                                                                             |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 10/12/2012 | Mastic/Adhesive for Cementitious Wall Panel. Damage Observed. <5% Physical Damage - in the form of 2 panels are broken in Boys Restroom, due to Removal of Vinyl Wall Panel. Material is in FAIR condition as of this date. |
| 04/05/2013 | Material condition Re-Assessed. Damaged section of Material may exist under 4'x8' Vinyl Wall Panel. No other changes as of this date.                                                                                       |
| 01/31/2020 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 08/27/2020 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 02/09/2021 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 08/10/2021 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 02/17/2022 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 08/16/2022 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 02/14/2023 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 08/15/2023 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 02/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 08/13/2024 | This Material is unchanged as of this date.                                                                                                                                                                                 |
| 02/26/2025 | This Material is unchanged as of this date.                                                                                                                                                                                 |

**End Of Report, Total Of 23 Pages**

2/26/25


8/5/2022






CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: **2-13-24**

**Cherrywood Elementary School**  
2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
8/5/2022




CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 08-15-2023

Cherrywood Elementary School  
2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
8/5/2022



2/14/23

8/5/2022



# Cherrywood Elementary School


Black top

SJ B Daycare  
Donna Clubb  
408 259-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 08-16-2022

|                       |                                                     |                      |                                    |                                         |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishakumar<br>5 <sup>th</sup> | Rm 21<br>Ramirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|



2019-2020


Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 08-16-2022

**Cherrywood Elementary School**  
2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915



# Cherrywood Elementary School

Black top


SJ B Daycare  
Donna Clubb  
408 759-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL

INSPECTED ON: 02-17-2022

|                       |                                                     |                      |                                    |                                         |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishakumar<br>5 <sup>th</sup> | Rm 21<br>Ramirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|



2019-2020

Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian

Kindergarten Playground

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

# Cherrywood Elementary School


Black top

SJ B Daycare  
Donna Clubb  
408 759-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 12/01/8

|                       |                                                     |                      |                                    |                                         |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishakumar<br>5 <sup>th</sup> | Rm 21<br>Ramirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|



2019-2020  
Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian

Kindergarten Playground

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

# Cherrywood Elementary School

Black top

SJ B Daycare  
Donna Clubb  
408 959-9739


Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL

INSPECTED ON:

2/6/2

|                       |                                                     |                      |                                    |                                          |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|------------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishnakumar<br>5 <sup>th</sup> | Rm 21<br>Ramirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|------------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|



2019-2020  
Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

# Cherrywood Elementary School


Black top

SJ B Daycare  
Donna Clubb  
408 259-9739

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 8/27/20

Staff Parking lot  
Greengate Drive

|                       |                                                     |                      |                                    |                                         |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishakumar<br>5 <sup>th</sup> | Rm 21<br>Ranirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|



2019-2020

Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

# Cherrywood Elementary School

Black top


SJ B Daycare  
Donna Clubb  
408.259.9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
NO INSPECTION 02-02-18

|                       |                                                     |                      |                                    |                                         |                                     |                             |                                         |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|
| Rm 26<br>Waters<br>OT | Rm 25<br>Schultz-SSW<br>Lin, Psych<br>Amador, Music | Rm 24<br>Pham<br>RSP | Rm 23<br>Madsen<br>4 <sup>th</sup> | Rm 22<br>Krishakumar<br>5 <sup>th</sup> | Rm 21<br>Ramirez<br>5 <sup>th</sup> | Rm 20<br>Regalado<br>PS SDC | Rm 19<br>Shroff<br>PS SDC<br>Assessment |
|-----------------------|-----------------------------------------------------|----------------------|------------------------------------|-----------------------------------------|-------------------------------------|-----------------------------|-----------------------------------------|

CR 16  
C. R. 16  
C. R. 16  
C. R. 16



2019-2020  
Tina Tong Choy - Principal x 2310  
Debbie Logan - Secretary x2300  
Joanne Mah - Attendance Clerk x 2301  
Raymond Reyes - Day Custodian  
Jose Topete - Night Custodian


2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915

Cabrillo Drive

# Cherrywood Elementary School

2550 Greengate Drive  
 San Jose, CA 95132  
 Phone (408) 923-1915  
 Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
 INSPECTED ON: 8/13/19



Cabrillo Avenue

# Cherrywood Elementary School


2550 Greengate Drive

San Jose, CA 95132

Phone (408) 923-1915

Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 02-05-2019




# Cherrywood Elementary School

2550 Greengate Drive  
 San Jose, CA 95132  
 Phone (408) 923-1915  
 Fax (408) 258-8356

Cabrillo Avenue

Black Top


CHERRYWOOD ELEMENTARY SCHOOL  
 INSPECTED ON: 8/3/8



# Cherrywood Elementary School

2550 Greengate Drive  
 San Jose, CA 95132  
 Phone (408) 923-1915  
 Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
 INSPECTED ON: 2/13/18



Cabrillo Avenue

# Cherrywood Elementary School

2550 Greengate Drive

San Jose, CA 95132


Phone (408) 923-1915

Fax (408) 258-8356



Cabrillo Avenue


CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 8/28/17



# Cherrywood Elementary School

2550 Greengate Drive  
 San Jose, CA 95132  
 Phone (408) 923-1915  
 Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
 INSPECTED ON: 3/28/17



Cabrillo Avenue

# Cherrywood Elementary School

2550 Greengate Drive

San Jose, CA 95132

Phone (408) 923-1915

Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 9/12/16

Staff Parking Lot

Daycare  
(408) 259-9739

Rm 26  
4th  
Rm 25  
4th

Rm 24  
4th

Rm 23  
5th  
Rm 22  
5th

Rm 21  
5th  
Rm 20  
5th

Rm 19  
K

Upper  
Grade  
Playground

Rm 14  
3rd  
Rm 15  
K  
Rm 13  
3rd

Rm 17  
K  
Rm 18  
K-Lab  
Rm 16  
K/1st

Rm 12  
2nd/3rd  
Rm 11  
3rd  
Rm 10  
3rd  
Rm 9  
RSP  
Rm 8  
2nd  
Rm 7

Multipurpose Room

Speech  
Counselor  
Stage  
Library Office  
ESL/PLA  
Cafeteria

Boy's Restroom  
Kitchen  
Girl's Restroom

MAIN  
ENTRANCE

Nurse  
Office  
Principal  
Office  
Staff  
Lounge

Kindergarten Playground

New  
Library

Lower  
Grade  
Playground

Rm 6  
2nd  
Rm 4  
2nd  
Rm 5  
2nd

Rm 3  
1st  
Rm 1  
1st  
Rm 2  
1st

Black Top

Cabrillo Avenue

# Cherrywood Elementary School

2550 Greengate Drive

San Jose, CA 95132


Phone (408) 923-1915

Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL

INSPECTED ON:

3-17-16



Cabrillo Avenue

# Cherrywood Elementary School

2550 Greengate Drive

San Jose, CA 95132

Phone (408) 923-1915

Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 9/17/15

Staff Parking Lot

Rm 26

Daycare  
(408) 259-9739

Rm 25

Rm 24

Rm 23

Rm 22

Rm 21

Rm 20

Rm 19

K

Upper  
Grade  
Playground

Rm 14

3rd

Rm 15

K

Rm 13

3rd

Rm 17

K

Rm 18

K-Lab

Rm 16

K/1st

Rm 12

2nd/3rd

Rm 11

3rd

Rm 10

3rd

Rm 8

2nd

Rm 9

RSP

Rm 7

Multipurpose Room

Library  
Office

ESL/PLA

Stage

Cafeteria

Speech

Counselor

Boy's Restroom

Girl's Restroom

Kitchen

MAIN  
ENTRANCE

Nurse  
Office

Principal  
Office

Staff  
Lounge

New  
Library

Kindergarten Playground

Lower  
Grade  
Playground

Black Top

Cabrillo Avenue

# Cherrywood Elementary School


2550 Greengate Drive

San Jose, CA 95132

Phone (408) 923-1915

Fax (408) 258-8356

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 03-16-2015



Cabrillo Avenue

# Cherrywood Elementary School

Black top

Daycare  
408 259-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON 8/19/10

8/20/2010

2010-11  
Lakeisha Blackshire - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Alex Martinez - Day Custodian  
Eduardo Manuel - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356

Kindergarten Playground

Library  
Laurie Ortega

19  
Davis  
K

20

21  
Ramirez  
4th

22  
Treffkom  
4/5

23  
Cho  
5th

24


25

26  
Rubio  
5th

Upper  
Grade  
Playground

MULTIPURPOSE

Lower  
Grade  
Playground



Cabrillo Drive

# Cherrywood Elementary School

MSA's content

Black top

Daycare  
408 259-9739

Greengate Drive  
Staff Parking lot

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 3-4-14

8/20/2010

26  
Rubio  
5<sup>th</sup>

25

24

23  
Cho  
5<sup>th</sup>

22  
Treffkorn  
4/5

21  
Ramirez  
4<sup>th</sup>

20

19  
Davis  
K

Upper  
Grade  
Playground

Rm 13  
Marriott/  
Yee  
2/3<sup>rd</sup>

Rm 14  
Teehan  
4<sup>th</sup>

Rm 15  
Chan  
K/1

Rm 17  
Seeley  
K

Rm 16  
Quach  
K

18  
Asano  
SDC  
K/1

Rm 11  
Pugh  
3<sup>rd</sup>

Rm 12  
Blevins  
3<sup>rd</sup>

Rm 10  
Moriya

Rm 9  
Polyak  
RSP

Rm 8  
Lee/Yoon  
2<sup>nd</sup>

Rm 7  
Rocchi  
1<sup>st</sup>

MULTIPURPOSE

Program Reading  
Room

ESL/PLA

Stage

Cafeteria

Speech

Counselor

Boys Restroom

Kitchen

Girls Restroom

Staff  
Lounge

Nurses  
Office/  
Principal

Library  
Laurie  
Ortega

Kindergarten Playground

Boiler  
Room

2010-11  
Lakeisha Blackshire - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Alex Martinez - Day Custodian  
Eduardo Manuel - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356

Cabrillo Drive

Lower  
Grade  
Playground

Rm 3  
Shaikh

Rm 1  
Masulis  
1/2

Rm 2

Rm 6  
Murphy  
2<sup>nd</sup>

Rm 5  
Joe  
1<sup>st</sup>

Rm 4  
Lazier  
2<sup>nd</sup>

# Cherrywood Elementary School

Black top

Daycare  
408 259-9739

Greengate Drive  
Staff Parking lot


CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON 09-27-2013

8/20/2010

- 26 Rubio 5<sup>th</sup>
- 25
- 24
- 23 Cho 5<sup>th</sup>
- 22 Treffkom 4/5
- 21 Ramirez 4<sup>th</sup>
- 20
- 19 Davis K

2010-11  
Lakeisha Blackshire - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Alex Martinez - Day Custodian  
Eduardo Manuel - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356



Kindergarten Playground

Library  
Laurie Ortega

Cabrillo Drive

# Cherrywood Elementary School

Black top

Daycare  
408 259-9739

Off Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 4/65/13

8/20/2010

26  
Rubio  
5<sup>th</sup>

25

24

23  
Cho  
5<sup>th</sup>

22  
Treffkom  
4/5


21  
Ramirez  
4<sup>th</sup>

20

19  
Davis  
K

2010-11  
Lakeisha Blackshire - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Alex Martinez - Day Custodian  
Eduardo Manuel - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356



Cabrillo Drive

# Cherrywood Elementary School

Black top

Daycare  
408 259-9739

Greengate Drive  
Staff Parking lot


CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 12-12-10

8/20/2010

- 26 Rubio 5<sup>th</sup>
- 25
- 24
- 23 Cho 5<sup>th</sup>
- 22 Treffkom 4/5
- 21 Ramirez 4<sup>th</sup>
- 20
- 19 Davis K

2010-11  
Lakeisha Blackshire - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Alex Martinez - Day Custodian  
Eduardo Manuel - Night Custodian

2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356




Kindergarten Playground

Library  
Laurie Ortega

Boiler Room  
Storage  
Facilities

Cabrillo Drive

# Cherrywood Elementary School



# Cherrywood Elementary School

Black top

Daycare  
408 259-9739

metal

26  
Rubio  
5<sup>th</sup>

25

24

23  
Cho  
5<sup>th</sup>


22  
Treffkorn  
4/5

21  
Ramirez  
4<sup>th</sup>

20

19  
Davis  
K

Upper  
Grade  
Playground



2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356

2010-11  
Lakeisha Blackshire – Principal  
Debbie Logan – Secretary  
Joanne Mah – Attendance Clerk  
Alex Martinez – Day Custodian  
Eduardo Manuel – Night Custodian

Kindergarten Playground

Library  
Laurie  
Ortega

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 11-2-11

Staff Parking lot  
Greengate Drive

8/20/2010

Cabrillo Drive

# Cherrywood Elementary School


Black top

Daycare  
408 259-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 9/1/10

- 26 Ramirez 4th
- 25 Boyd 4th
- 24 Marriott 4th
- 23 Cho 5th
- 22 Treffkorn 5th
- 20 Hunter 5th
- 19 Davis K




2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356

Kindergarten Playground

2006-07  
Virginia Catbagan - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Barbara Gillette - Health Clerk  
Juan Luna - Day Custodian

Cabrillo Drive

# Cherrywood Elementary School



# Cherrywood Elementary School


Black top

|                      |                   |                       |                  |                        |                     |                  |
|----------------------|-------------------|-----------------------|------------------|------------------------|---------------------|------------------|
| 26<br>Ramirez<br>4th | 25<br>Boyd<br>4th | 24<br>Marriott<br>4th | 23<br>Cho<br>5th | 22<br>Treffkorn<br>5th | 20<br>Hunter<br>5th | 19<br>Davis<br>K |
|----------------------|-------------------|-----------------------|------------------|------------------------|---------------------|------------------|

Daycare  
408 259-9739

Staff Parking lot  
Greengate Drive

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 6/6/06




2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356


2006-07  
Virginia Catbagan - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Barbara Gillette - Health Clerk  
Juan Luna - Day Custodian

Cabrillo Drive

# Cherrywood Elementary School




# Cherrywood Elementary School



# Cherrywood Elementary School

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 4-16-08

Black top



2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356


2006-07  
Virginia Carthagen - Principal  
Debbie Logan - Secretary  
Joanne Mab - Attendance Clerk  
Barbara Gillette - Health Clerk  
Juan Luna - Day Custodian

Cabrillo Drive

# Cherrywood Elementary School

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 11-08-07

Black top



2550 Greengate Drive  
San Jose, CA 95132  
Phone (408) 923-1915  
Fax (408) 258-8356


2006-07  
Virginia Catbagan - Principal  
Debbie Logan - Secretary  
Joanne Mah - Attendance Clerk  
Barbara Gillette - Health Clerk  
Juan Luna - Day Custodian

Staff Parking lot  
Greengate Drive

Cabrillo Drive


Revised  
01/04/07

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 03/08/07




CHER-A  
MAIN FLOOR


CHER-P1



CHER-B



CHER-A  
THE LOFT



NOT TO SCALE

SCHOOL NAME: CHERRYWOOD ELEMENTARY  
ADDRESS: 2550 GREENGATE DRIVE  
SCHOOL DISTRICT: BERRYESSA UNIFIED


COUNTY: SANTA CLARA  
ACREAGE: N/A  
REV. DATE: 01/25/99

# NAMING CONVENTION SITEPLAN


BERRYESSA UNIFIED  
1376 PIEDMONT RD  
SAN JOSE, CA 95132

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 08-23-06

CHER-P1




NOT TO SCALE




CHER-A  
MAIN FLOOR

CHER-B



CHER-A  
THE LOFT




NAMING CONVENTION SITEPLAN


SCHOOL NAME: CHERRYWOOD ELEMENTARY  
ADDRESS: 2550 GREENGATE DRIVE  
COUNTY: SANTA CLARA  
ACREAGE: N/A  
REV. DATE: 01/25/99

BERRYESSA UNIFIED  
1376 PIEDMONT RD  
SAN JOSE, CA 95132

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED ON: 04/18/06




CHER-P1




NOT TO SCALE

CHER-B



CHER-A  
THE LOFT




COUNTY: SANTA CLARA  
ACREAGE: N/A  
REV. DATE: 01/25/99

SCHOOL NAME: CHERRYWOOD ELEMENTARY  
ADDRESS: 2550 GREENGATE DRIVE  
SCHOOL DISTRICT: BERRYESSA UNIFIED

# NAMING CONVENTION SITEPLAN


BERRYESSA UNIFIED  
1376 PIEDMONT RD  
SAN JOSE, CA 95132

CHERRYWOOD ELEMENTARY SCHOOL  
INSPECTED SEPTEMBER 2005





CHER-A  
MAIN FLOOR

CHER-P1



CHER-B



NOT TO SCALE

COUNTY: SANTA CLARA  
ACREAGE: N/A  
REV. DATE: 01/25/99

SCHOOL NAME: CHERRYWOOD ELEMENTARY  
ADDRESS: 2550 GREENGATE DRIVE  
SCHOOL DISTRICT: BERRYESSA UNIFIED

# NAMING CONVENTION SITEPLAN

BERRYESSA UNIFIED  
1376 PIEDMONT RD  
SAN JOSE, CA 95132