



Welding

Instructor: Mike Mullen

Email: Mullencs1@outlook.com

Required Materials:

- Leather work boots (Timberland style)
- Non-flammable clothing (natural fibers, like Carhartt's). No Polyester, Rayon, Nylon, etc.
- Safety glasses
- Welding helmet
- Welding gloves
- Either Welding Apron or Jacket