

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Cordova Gardens Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/21/2025
Number of Areas Evaluated: 13

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Cordova High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/26/2025
Number of Areas Evaluated: 32

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Cordova Meadows Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/19/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Cordova Villa Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/15/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Innovations Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/19/2025
Number of Areas Evaluated: 4

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Mills Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/27/2025
Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Natoma Station Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/20/2025
Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Navigator Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/15/2025
Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Rancho Cordova Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/14/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Theodore Judah Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/20/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: W.E. Mitchell Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/22/2025
Number of Areas Evaluated: 21

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: White Rock Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/28/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Folsom Cordova Unified School District
School Site: Williamson Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/14/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.