

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: A. M. Winn Waldorf-Inspired K-8

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/16/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Abraham Lincoln Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/3/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Albert Einstein Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/17/2025
Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Arthur A. Benjamin Health Professions High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/30/2025
Number of Areas Evaluated: 12

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Aspire Capitol Heights Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/11/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Bret Harte Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/20/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: California Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/26/2025
Number of Areas Evaluated: 21

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Capital City Independent Study

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/9/2025
Number of Areas Evaluated: 12

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Capitol Collegiate Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/17/2025
Number of Areas Evaluated: 22

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Caroline Wenzel Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/8/2025
Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Ethel Phillips Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/20/2025
Number of Areas Evaluated: 13

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Father Keith B. Kenny Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/10/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Golden Empire Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/2/2025
Number of Areas Evaluated: 20

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Growth Public

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/25/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Poor
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: H. W. Harkness Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/13/2025
Number of Areas Evaluated: 20

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Fair
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Hiram W. Johnson High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 11/3/2025
Number of Areas Evaluated: 34

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Isador Cohen Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/2/2025
Number of Areas Evaluated: 12

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: James Marshall Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/3/2025
Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: John Bidwell Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/9/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: John Cabrillo Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/10/2025
Number of Areas Evaluated: 21

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: John H. Still 7-8 Campus

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/16/2025
Number of Areas Evaluated: 22

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: John H. Still K-6 Campus

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/16/2025
Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: John Morse Therapeutic Center

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/10/2025
Number of Areas Evaluated: 13

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Leataata Floyd Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/15/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Poor
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Matsuyama Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/9/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: New Joseph Bonnheim (NJB) Community Charter

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/4/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Nicholas Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/25/2025
Number of Areas Evaluated: 23

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Pacific Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/20/2025
Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Parkway Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/25/2025
Number of Areas Evaluated: 25

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Pony Express Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/8/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Rosa Parks K-8

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/16/2025
Number of Areas Evaluated: 30

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Rosemont High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/29/2025
Number of Areas Evaluated: 30

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Sacramento Charter High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/22/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education 2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Sam Brannan Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/23/2025
Number of Areas Evaluated: 20

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Poor
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Fair: The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: School of Engineering & Sciences

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/1/2025
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Sequoia Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/10/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Sol Aureus College Preparatory

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/21/2025
Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: St. HOPE Public 7 Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/22/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: St. HOPE Public 7 Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/24/2025
Number of Areas Evaluated: 10

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Poor
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Suy:U Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/20/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: The Language Academy of Sacramento

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/1/2025
Number of Areas Evaluated: 14

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Umoja International Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/17/2025
Number of Areas Evaluated: 13

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Washington Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/15/2025
Number of Areas Evaluated: 13

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Will C. Wood Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/24/2025
Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Woodbine Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/13/2025
Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Sacramento City Unified School District
School Site: Yav Pem Suab Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/6/2025
Number of Areas Evaluated: 22

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.