

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Center Joint Unified School District
School Site: Arthur S. Dudley Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/29/2025
Number of Areas Evaluated: 20

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Center Joint Unified School District
School Site: Center High

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/18/2025
Number of Areas Evaluated: 39

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Fair
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Center Joint Unified School District
School Site: Oak Hill Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/29/2025
Number of Areas Evaluated: 21

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Poor
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.

Sacramento County Office of Education

2025-26 Williams Site Review Summary

District: Center Joint Unified School District
School Site: Wilson C. Riles Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 8/20/2025
Number of Areas Evaluated: 35

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.